



JAN 2 4 1996

Surveyor's Michigan License No.

KENT COUNTY REMONUMENTATION

Jan 2 4 1996

762	LAND CORNER R	ECORDATION CERTI	FICATE
COMMISSION	Filing Requiremen	nt of Act 74, Mich. P.	A. 1970 🕠 😙
For corners in KENT COUNTY Locat	ed In:	Corner Code #	95 n ST
(County)			REG C CENT
	7N 40W	D 40	26 27 28 28 28 28 28 28 28 28 28 28 28 28 28
1. Public Land Survey T	7N R 12W	B-10	
i T	R		PHIZ:
	R	,	FREDS RECORD
2. Property Controlling ST	R		5 5 7
	R		8863
	R		Register of Deeds Stamp & File Number
Troporty in coolers	· · · · · · · · · · · · · · · · · · ·		
4. Lot No, Recorded Plat			A B C D E F G H I J K
5. Private Claims			2 6 5 4 3 2
			3
Walle Book to 1			4-7-9-10-11
i, Kirk Breitels , in a field surve	y onNov	15 , ₁₉ 94	
do hereby certify that under requirements of P. in lines 1 and 2 above were in conformance with	A. 74, Michigan P.A. of 1	970, the corner points ment	
manual of survey instructions of the United	d State's Department o	of the Interior, Bureau of	Land 7
Management or by a decree of a Court of Law 5 above were in conformance with the rules of			·by a
Decree of a Court of Law; established, re-esta			found
as expressed below:	4		10 (30) 29 28 27 26 2
NOTE: Not more than 4 corners, all in the on this certificate.	same town and rang	e, may be recorded	12 31 32 33 34 35
	:		13
A. Description of original monument an	d accessories and/or	subsequent restoration	ı:
B-10 1837 GLO	Not	Set	
1928-72 Williams &	Works Stak	e – Iron – Monum	ent - Mon. Box
Kent Co. Wit.		Box	
Iron Fc. Pos 1972 LCRC #394	t W. 57.6′ NW Spicer 1″I	cor. hdwll. E.	56.9'
CP Pole S45°E 60.05' CP Pole S25°E 183.0' 10" Poplar S25°W 84.75'			
		. 5 020 2 100.0	10 10p141 025 # 04.75
B. Description of corner evidence found	d and/or mathod app	liad in ractoring or roact	obliching corner
B. Description of comer evidence round	and/or method appr	ned in restoring or reest	abiistiitig Corties.
B-10 Found 1/2" Rerod over	1" Iron Pipe in	side a Mon. Box t	hat fits remaining witnesses
of LCRC #394 (Kent Co. W	lit. gone). S	aid Rerod is 5.	3' W. & 2 2' N from true
intersection of 1/4 lines	and fits previo	us survey data o	t others.
The 1/2" Rerod over 1" Iro	n Pipe inside a	Mon. Box is acc	epted by me and is generally
accepted by professional su	rveyors as the	best available ev	idence of the position of the
corner.	ľ		
			990 KENT COUNTY
		PEER APP	ROVED/1/17/97
~	:	CHAIRMAN	Harry Futer
	•		
C. Description of monument for corner	and accessories esta	blished to perpetuate lo	cating the position of the corner:
B-10 Set Standard Kent Cour			n place of both Irons
Set Nail & KC Remon.			60.02'
Set Nail & KC Remon. Set Nail & KC Remon.			182.86'
SW cor. CP Tower (@ b	olt ht. of hor	iz. brace) N35°E	129.0' KIRK \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
C/L Wilson Ave. – Eas	st 2.4' <u>+</u>		BREITELS LAND
	•		SURVEYOR
	•		NO 15 10077
			30077
(/,)	40		LAND SU
Signed by Luk Br	n 2/3	Data	12/14/95
Signed by 12000 100	 	Date	DON'ED DY BICHICAN STATE DOADD OF BROKESSIANAL SHRUFYORS 14M 09 4074