## SURVEY & REMONUMENTATION

APR 2 8 1995

## KENT COUNTY REMONUMENTATION

· STATE OF MICHIGAN COUNTY OF KENT RECEIVED FOR RECORD

## COMMISSION

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

94 DEC 27 AM 9: 04

REG. OF DEEDS

For corners in KENT COUNTY

	(County)	Located in:	Comer Code -##
1.	Public Land Survey	T 7N R 12W	C-12
		T R	
		T R	
		T R	
2.	Property Controlling	S T R	
	in Section	S T R	
3.	Miscellaneous	S T R	
	Property in Sec.	S T R	

7892
Register of Deeds Stamp & File Number

Lot No. \_\_\_\_\_\_\_, Recorded Plat \_
 Private Claims

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

C-12 1837 GLO

Whitcomb Set Post

P.A. 345 1990 KENT COUNTY

PER APPROVED/12/22/9

1837 GLO Whitcomb Set Post CHAIRMAN // ta Kent Co. Wit. 1927 Tron 1981 LCRC #2035 Hackbardt Set Kent County Monument LCRC #5524 1990 Starr Kent County Monument

The position of this corner was previously approved by the Kent County Remonumentation Peer Group, monumented by Glen S. Hackbardt on 6/10/81 and was recorded per LCRC #2035.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

C-12 Found standard Kent Co. Mon. (Harrison) per witnesses from above LCRC as set by Glen S. Hackbardt in place of the 1 1/4" x 24" Iron he found. Said Iron checks with Kent Co. Wit.

LCRC #2035		LCRC #5524					
Nail & tag 30" Oak	N30°E 50.75'	Nail & tag W. side	30" Oak	N30°E 50.22'			
Nail & tag 15" Tri-	Maple \$80°E 41.80'	Nail & tag S. side	15" Tri-Maple	S80°E 41.80'			
Nail & tag 18" Maple	e S45°E 31.95'	Nail & tag N. side	18" Maple	S45°E 31.98'			
Nail & tag 16" Mapl	e S85°W 13.40'	Nail & tag S. side	16" Maple	S85°W 13.40'			

The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C-12 Standard Kent County Monument

23502

Nail & KC Remon. tag W. side 30" Oak N30°E 50.27'
Nail & KC Remon. tag S. side 15" Tri-Maple S80°E 41.81'
New Nail & KC Remon. tag N. side 18" Maple S45°E 32.05'
Set Nail & KC Remon. tag S. side Tw. 36" Maple S85°W 23.73'

@ N. edge swamp

William R.
Byl
Registered Lend
Surveyor
No.
23502

Signed by \_\_\_\_\_\_\_Surveyor's Michigan License No. \_

Date 12/07/94

RM/AFPROVED BY MIGHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983