

## SURVEY & REMONUMENTATIO



APR 2 8 1995

KENT COUNTY REMONUMENTATION

STATE OF MICHIGAN COUNTY OF KENT RECEIVED FOR RECORD

CO	RAR	MC	CI	ፖን <b>ስ</b>
	11.11	VII		L JIN

LAND CORNER RECORDATION CERTIFICATE

AND CORNER RECORDATION CERTIF

For corners in	rining Kequ	Filing Requirement of Act 74, Mich. P.A. 1970/ NOV 150 100			
KENT COUNTY (County)	Located In:	Corner Code =##	the flint		
Public Land Survey	TR T R T R T R		REG. OF DEEDS		
2. Property Controlling in Section	S T R S T R		7312	Ç	
3. Miscellaneous	S T R		Register of Deeds Stamp & File Number		
Property in Sec.	S T R		register of beeds Stamp & the Milling		
4. Lot No,	Recorded Plat		A B C D E F G H I J.K L	1.0	
5. Private Claims	·		<u> </u>		
	:		2 - 6 - 5 - 4 - 4 3 2 1		
			3		
	1	İ	4 7 8 9 10 11 11 12		
L William R. Byl	, in a field survey on	July 1 19 94	5 1 1 1 1		
		A. of 1970, the corner points mentione			
		and rules therefore as required in th	ie 10 17 17 18 19 19 19 19 19 19 19 19 19 19 19 19 19	,	
		artment of the Interior, Bureau of Lan ner points mentioned in lines 3, 4 and		_	
		d of Land Surveyors or by a Decree of	20 - 21 - 22 - 23 - 24	<b>,</b>	
		e-monumented, recovered, found a		_	
expressed below:	:		10 30 29 28 27 26 25	<b>;</b> —	
NOTE: Not more than 4 of	corners, all in the same town	and range, may be recorded	11		
on this certificate	•		12 31 32 33 34 35 36	<u>.                                    </u>	
		1	13		
A Description of original	monument and accessories a	nd/or subsequent restoration:			

E-11	1837 1940	GLO Kent Co. Wit.	Whitcomb	Set Post
	1940	Kent to. Wit.		Conc. Mon.
	1977	LCRC #1033	Merdzinski	3" Iron in Mon. Box
	1982	LCRC #3315	Tobin	Set Kent County Monument
	1990	LCRC #5540	Starr	Kent County Monument

The position of this corner was previously approved by the Kent County Remonumentation Peer Group, monumented by Douglas J. Tobin on 5/21/82 and was recorded per LCRC #3315

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

E-11 Found standard Kent Co. Mon. (Harrison) per witnesses from above LCRC as set by Douglas J. Tobin in place of the 3" Pipe he found in a Mon. Box. Said 3" Pipe checks with Kent Co. Wit. and LCRC #1033.

LCRC #3315		LCRC #5540
KC Nail & tag MBT	Pole S50°W 48.20'	Nail & KC Remon. tag MBT Pole S50°W 48.20'
KC Nail & tag MBT	Pole N50°W 56.20'	Nail & KC Remon. tag MBT Pole N50°W 56.70'
KC Nail & tag Lt.	Pole South 24.62	Nail & KC Remon. tag Lt. Pole South 24.62'
KC Nail & tag 12"	Maple N60°E 74.20'	Nail & KC Remon. tag 12" Maple N60°E 74.20'
		Nail & CK Remon. tag 12" Pine N25°E 63.19'
	·	On C/L Bit. Rd. N-E-W; On tree row S.

The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original corner.

Description of manument for corner and accessories established to perpetuate locating the position of the corner

•	Booding.com or mond				The production of the control	
	E-11 Standard	Kent County	Monument			
	Nail	& KC Remon.	tag N. side MBT	Pole S50°W	48.227	
	Nai1	& KC Remon.	tag NE side MBT	Pole N50°W	56.73'	
			tag W. side Lt.			
			tag S. side 12"			
			tag NW side 14"		53.29'	
	On C/L Bi	it. Rd. N-E-\	W; On tree row S	•	P.A. 345 1990 KENT COUNTY	
					PEER APPROVED	4
			$\sim 1/$		CHAIRMAN Journay Shaff	_
•	1	$\mathcal{L}$		<i>&gt;</i>		
	1	_ //	M		1117 62	
:	ned by	— , <sub>[C</sub> .	V y	Date	11-17-99	

Surveyor's Michigan License No.

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983