

SURVEY & REMONUMENTATION

APR 28 1995

KENT COUNTY REMONUMENTATION

COMMISSION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
KENT COUNTY

STATE OF MICHIGAN
COUNTY OF KENT
RECEIVED FOR RECORD
94 DEC -5 AM 8:52

W. J. Bond
REG. OF DEEDS

7591

Register of Deeds Stamp & File Number

	Located In:	Corner Code #
1. Public Land Survey	T <u>7N</u> R <u>12W</u>	<u>E-13</u>
	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

I, William R. Byl, in a field survey on July 7, 19 94, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

E-13 1837 GLO Brookfield Set Post
1913-55 Williams & Works Set Iron 9.08 Ch. West of NE cor.
Sec. 5, T6N, R12W
1985 LCRC #4133 Byl Computed point-corner in grav. pit lake
1990 LCRC #5542 Starr Per LCRC #4133

The position of this corner was previously approved by the Kent County Remonumentation Peer Group, documented by William R. Byl on 1/3/85 and was recorded per LCRC #4133

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

E-13 No corner found-still in gravel pit lake per above LCRC by William R. Byl. Said position was computed from data by Williams & Works survey #42084 and other information supplied by Nederveld and Associates.
LCRC #4133 & 5542

No Monument-see reverse side for detailed sketch

P.A. 345 1990 KENT COUNTY
PEER APPROVED 12/1/94
CHAIRMAN Harry Huber

The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-13 Computed Location of corner only-see reverse side for sketch



Signed by William R. Byl
Surveyor's Michigan License No. 23502

Date 11/27/94