4. Lot No. ... 5. Private Claims \_

## REMONUMENTATION

KENT COUNTY REMONUMENTATION

STATE OF MICHIGAN COUNTY OF KENT RECEIVED FOR RECORD

APR 2 8 1995

COMMISSION

\_\_ . Recorded Plat


## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

91, NOV 26 AM 11: 48

ŀο	r corners in KENT COUNTY		. 1	
	(County)	Located In:	Corner Code ##	dui falond
1.	Public Land Survey	T <u>7N</u> R <u>12W</u>	H-3	REG. OF DEEDS
		T R T R		•
		T R		
2.	Property Controlling	S T R		N 2 2 0
	in Section	S		7329
3.	Miscellaneous	S T R		Register of Deeds Stamp & File Numbe
	Property in Sec.	S T R		

William R. Byl, in a field survey on. May 27 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as

expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.



A. Description of original monument and accessories and/or subsequent restoration:

H-3	1837	GLO	Whitcomb	Set Post
	1960	Kent Co. Wit.	MDSH	3/4" Iron in mon. box
	1974	LCRC #628	South	1" Pipe in mon. box
	1974	LCRC #753	Spicer	3/4" Iron in mon. box
	1981	LCRC #1852	Tobin	Set Kent County Monument

The position of this corner was previously approved by the Kent County Remonumentation Peer Group, monumented by Douglas J. Tobin and was recorded per LCRC #1852

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

H-3 Found standard Kent Co. Mon. (Harrison) per witnesses from above LCRC as set by Douglas J. Tobin in place of the 3/4" Iron he found in a mon. box. Said 3/4" Iron in mon. box checks with Kent Co. Wit. and LCRC's #628 & #753.

LCRC #1852				P.A. 345 1990 KENT COUNTY
Nail & tag SW s	side MBT pole	S45°E	81.26	PEER APPROVED 1///7/94-
	side wood fence post	S35°W	59.27	CHAIRMAN Trangfuher
Nail & tag E. s	side 16" Poplar	N20°W	46.21'	on the state of th
Nail & tag E. s	side 26" Oak	NO5°W	66.7'	

The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

H-3 Standard Kent County Monument in gravel shoulder 835°W 59.56 Nail & KC Remon. tag SE side wood fence post N20°W New Nail & KC Remon. tag E. side 20" Poplar 46.281 New Nail & KC Remon. tag E. side 30" Oak NO5°W 66.79' 34.63' S30°W Set Nail & KC Remon. tag NW side P. Pole PK in C/L 3 Mile Rd. 17.27 NO0°E

12 My4 Registered Land Surveyor No. 23502 \*\*\* A CONTRACTOR OF THE PARTY OF TH 喜感蔑聲

Signed by Surveyor's Michigan License No. Date