

## SURVEY & REMONUMENTATION

COMMISSION





KENT COUNTY REMONUMENTATION

## STATE OF MICHIGAN COUNTY OF KEHT RECEIVED FOR RECORD

APR 2 8 1995

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 94 NOV 28 AMII: 49

For come	IT COUNTY	La calad Ta	Cause Cad		Lui	22	\	
<del></del>	(County)	Located In:	Corner Cod	ie -/-/	REG. OF	DCE00	,	
1. Public	Land Surve	y T <u>7N</u> R TR TR TR			nuc, gr	DEEDS		
2. Prope	rty Controllir				735	ŋ		
in Sec		s T R _ s T R _			100	4		
3. Misce		S T R _		—— Rec	gister of Deeds Stan	no & File N	iumbe	<del>1</del> 5
	rty in Sec.	S T R _			,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,			
4. Lot No	0	, Recorded Plat			ABCDE	F G H I	JK	L
o. Privati	e Ciainis				2 6 5 5	·——	_ 2 _	<b>├</b> - { -
		·			3		_}_	$\vdash$
					4 - 7 - 8 9	) _  	_11_	12
ı Wil	liam R. F	By] , in a field survey on	May 23	1994,	5			
do hereby o	certify that und	ler requirements of P.A. 74, Mich	igan P.A. of 1970, the corner	pointsmentioned	6 10 17 1		_14	13.
in lines 1 a	and 2 above w	vere in conformance with regula	itions and rules therefore a	as required in the	7 1 1			Ĭ
current ma	nual of survey	instructions of the United State ee of a Court of Law and/or that t	is Department of the intent he corner points mentioned	in lines 3. 4 and 5	8 10 -30 -3		22	
ahove were	in conforman	ce with the rules of the Michigar	Board of Land Surveyors	or by a Decree of a	9	1 22	-23-	1
Court of L	_aw; establish	ed, re-established, monumen	ted, re-monumented, reco	overed, found as			-	
expressed	below:	1			10 30 29 2	627	26	25- I
NOTE: N	lot more tha	n 4 corners, all in the same	town and range, may bi	e recorded	11			r—t—
o	n this certifi	cate.			12 31 32 3	33'4	35	36-
A. Descr	ription of orig	ginal monument and accesso	ries and/or subsequent	restoration:	13			<u> </u>
9ل	1837	GLO	Whitcomb E. H. Christ	Set Post Iron				
	1946	City of Grand Rapid		City Iron				
	1962	Kent Co. Wits	MDSH		ption given			

The position of this corner was previously approved by the Kent County Remonumentation Peer Group, monumented by William R. Byl on 7/27/83 and was recorded per LCRC #3511

By1

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

J-9 Found standard Kent Co. Mon. (Harrison) in mon. box (road const. after 1983) per witnesses from above LCRC as set by William R. Byl. Said location as set by William R. By1 checks with City of Grand Rapids records and "PANFILLS ASSESSOR'S PLAT NO. 20." LCRC #3511

SW cor. fdn. Hse. #1153 SE cor. fdn. Hse. #1153 C/L top of hydrant C/L 3' dia. manhole	N15°W N60°E	55.26' 51.68' 42.45' 42.48'	P.A. 345 1990 KENT COUNTY PEER APPROVED//////9 5 CHAIRMAN Day Julieue
---	----------------	--------------------------------------	---

The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

J-9 Standard Kent County Monument in	mon. box		
SW cor. fdn. Hse. #1153	N45°W	55.17'	
SE cor. fdn. Hse. #1153	N15°W	3.1.02	
C/L top of hydrant (new location)	N60°E		(T)
C/L 3' dia. manhole	SUUSW	32.58	(Typo previously?)

Set Kent County Monument

· dy.I Registered Land Survoyer No. 23502 高高製質

Surveyor's Michigan License No.

1983

LCRC #3511

APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975

CBEI "HAL BEZIVER