Surveyor's Michigan License No.

KENT COUNTY REMONUMENTATION

546

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in KENT COUNTY (County)	Located In:	Corner Code #	I .	, 95 ⊞ s
1. Public Land Survey	T 7N R 12W T R T R T R	J-11 Deg. #2	REG. OF DEEL	TATE OF MICHIC COUNTY OF KELL OF OR RELEASE FOR RELEASE OF THE COUNTY OF
Property Controlling in Section	S T R S T R		SS	
3. Miscellaneous	S T R		872	• •
Property in Section	S T R	<u></u>	Register of Deeds	Stamp & File Number
4. Lot No, Rec 5. Private Claims			A B C D	E F G H I J K
5. Frivate Oldins			2 6 5	432
Vinte Donithala	;		3 4 7 8 8	9 10 11
I, KITK Breitels I, do hereby certify that under requi	n a field survey onS	ept. 20 , ₁₉ 95	5	
in lines 1 and 2 above were in commanual of survey instructions of Management or by a decree of a 5 above were in conformance w. Decree of a Court of Law; establias expressed below: NOTE: Not more than 4 cornor on this certificate.	nformance with regulations and ru of the United States Departme Court of Law and/or that the cor ith the rules of the Michigan Boa shed, re-established, monument	ules therefore as required in the dent of the Interior, Bureau of the Interior, Bureau of the points mentioned in lines 3, and of Professional Surveyors ded, re-monumented, recovered,	current 7 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	28 27 26
			13	33 34 35
_	onument and accessories an	•		
Kent (1980 LCRC # 1982 LCRC # 1990 LCRC # 1994 LCRC # The position of thi Peer Group, monumen B. Description of corner evice	of Grand Rapids Co. Wit. #1352 Bonn #2801 Merc #5695 Mil #7353 Byl s corner was previou ted by John A. Merdzi	liron Kent County Reset Kent Isly approved by the inski on 3/24/82 and applied in restoring or rees	ounty Monument y Monument County Monument Kent County Remon was recorded per L tablishing corner:	201/3/24 Construction CRC #2801.
Co. Mon. (Harrison) in place of the Pinc	per witnesses from "2/4" per witnesses from	above LCRC as set i Iron he found and s	n 1982 by John A. Bubsequent LCRC's b	Merdzinski
and Byl. Said Iron LCRC #1352	s check with LCRC #1	1352 and Kent Co. Wi	it.	
SW cor. conc. fdn.	N05°E 50.90'	<u>LCRC #5695</u> Nail-tag P. Pole	e N10°E 46.88	<u> </u>
SE cor. conc. fdn.		Nail-tag P. po	Te S80°E 96.	.55 '
SE cor. RR cross.	r. struc. \$10°E 84.4 sign \$20°W 30.5	15' Chisel. "+" st. 0' Chisel. "+" st.	post \$20°E 33.91	' - 34.08' '' - 56.62'
SE cor. RR cross. s	sign West 59.0	8' Chisel. "+" st.	post N60°W 64.31	' - 64.31'
C/L RR track The selected locati	South 17.7 ion is accepted by	3' E. face of S. ga	ate post S70	0°W 65.28'
surveyors as the be	st available evidenc	ce of the position of	of the original co	rner.
C. Description of monument	for corner and accessories	established to perpetuate k	ocating the position of the	e comer;
J-11 Standard Kent	County Monument		_	
Chiseled "+"	in N. side 4" steel in N. side 4" steel		30°W 56.62' 30°W 64.31'	DE MICH
E. face of S.	gate post	-	'0°W 65.26'	613
SW cor. conc. SE cor. conc.			0°E 64.77'	KIRK BREITELS LAND SURVEYOR NO 30077
	_			JAND SURVEY
1/2	Bull			A N.D.
Signed by /w/l	· v - my	Date _	10/20/95	

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983