SURVEY & REMONUMENTATION

APR 2 8 1995

KENT COUNTY REMONUMENTATION

STATE OF MICHIGAN COUNTY OF KENT RECEIVED FOR RECORD

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

94 NOV 28 AM 11: 50

For	r corners in KENT C		t anata	al las	Carner Code			Sel on	l		
	(Co	ounty)	Locate	ea in:	Corner Code =	- 					
1.	Public Lar	nd Survey	Τ	/N_R12W R	K-13		REG. 0	F DEEDS	\$		
2. 3.		eous	S T S T S T	R R			73(File N	umber	
	Property is	n Sec.	s T	н							
4.	Lot No		, Recorded Plat				- ABCD	E F G	нз	J K	L
5.	Private Cla	aims				<u> </u>	- 2 5	$\Pi\Pi$		\Box	T
							3 3	+1+	- 3 <u>- 1</u> -	-?	-1-
							4 7 8				丁
	Willia	ım R. Rv	$\sqrt{1}$, in a field survey	/ OD	April 12	19 93	5		-101	ïT	
l ot	hereby certif	y that unde	r requirements of P.A. 7	4, Michigan P.A.	of 1970, the corner po	intsmentioned	6 18 17				Ţ
n li	ines 1 and 2	above we	re in conformance witl	h regulations and	d rules therefore as i	required in the	7		-13		_ 3
our: Jar	rent manual	of survey in hy a decree	nstructions of the Unite of a Court of Lawand/	ed States Depart for that the corne	ment of the interior, t rpoints mentioned in	lines 3, 4 and 5	8 10 20				Ţ
abo	ve were in c	onformance	with the rules of the N	lichigan Board o	f Land Surveyors or b	y a Decree of a	9			73-	
			d, re-established, mo	numented, re-m	onumented, recove	red, found as	10 30 20			ŢŢ	Ţ
	ressed belo						11 30 29	1-28-1-	2/	-26	-25·
40		nore than is certifica	4 corners, all in the	same town an	a range, may be re	ecoraea	12				Ţ
	on un	is cerunca	ite.	1			13		-34	73	-36
۹.	Description	n of origin	nal monument and a	ccessories and	Vor subsequent re	storation:					
	·	_					P.A. 345 1990				
	K-13	1831	GLO		•	Set Post	PEER APPRO			199	_
		1931	City of Grand			City Iron	CHAIRMAN	Lam	201	wh	~~
		4050	Kent Co. Wit.	1			corner, wit et Iron abov		grve	11	
		1953 1972	Williams & Wor Williams & Wor				n-1953 Irons		anna		
		1972	LCRC #4049	·	tadt	"T" Iron	L 1900 TIOUZ	מייים מייים	june		
		1984	LCRC #4129				unty Monumen	t.			
	The no		of this corner						tatio	n	
	Peer G	roup. m	nonumented by W	/illiam R.	Bvl on 11/28/	84 and was i	recorded per	LCRC #	4129		
3.	Descriptio	n of corne	er evidence found ar	nd/or method a	pplied in restoring	or reestablishin	g corner:				
			tandard Kent Co								
			/1 in place of					with Ci	ity o	f	
		• •	Kent Co. Wit.	., Williams	& Works, and	LCRC #4049.	•				
		#4129				0					
			er of brick blo	ig.		N15°V			•		
			of East rail	- - 1 1		N90°W					
			oolt of RR sign			N80°E					
			oolt of RR sigr	iai pase		\$60°W \$35°E					
			steel shed Monument (K-1	I Tan Dia	w)	: N90°E					
	۲	went to.	monument (K-)	i, ioii, K12	n j	. 1820 6	. 11.41				
										_	

The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: S. Alton

K-13 Standard Kent County Monument N15°W SE corner of brick bldg. 39.09 S35°E NW cor. steel shed 51.14' S80°W 40.94 C/L Manhole S60°W 59.631 Set Nail & KC Remon. tag E. side P. Pole N75°E 86.653 Face of fire hydrant @ grade N90°E Kent Co. Monument (K-1, T6n, R12W) 71.27

Signed by Surveyor's Michigan License No.

waten A

5ys

Registated Land

Sur royer

No. 分落在白鹭