SUHVEY & REMONUMENTATION

MAY 0 9 1996

KENT COUNTY REMONUMENTATION

STATE OF MICHIGAN COUNTY OF KENT RECEIVED FOR RECORD

COMMISSION

LAND CORNER RECORDATION CERTIFICATED DEC -5 AM 8: 52

			ruing i	nequirement or	ACL 74, WICH.	F.M. 1970					
For	corners in KENT COUNTY		h	0	Corner Code =##			08	Į		
	(County)	Located In:	Corne	er Code <i>-##</i>			Plano	^		
1.	Public Land S	urvey	T 7N R T 6N R	11W A-1 11W A-13 12W M-1			REG. O	F DEEDS			
			T 7N R	\	3)		\				
2.	Property Controlling S T R					7594					
			S T R			Rea		eeds Stam	n & Filal	Numba	
U.	Property in Se		S T R			neg		ecus Stain		Tunibe	
			Recorded Plat				A B	CDEF	G H	JK	L
ე.	Private Ciamis	·				······	2 - 6-	54-	- l - 3		-!
							3	 			\dashv
					_	. .	4	 	10		12
۱, _	William I	R. Byl	, in a field survey on	March 3	19	94	5	 			-
dot in li	nereby certify that nes 1 and 2 abo	atunderre ove were i	quirements of P.A. 74, Mich in conformance with regula	igan P.A. of 1970, the ations and rules the	comer points me refore as require	ntionea d in the	6 -18-	 1/7 - 1/6	15	14	13
curr	ent manual of si	urvey insti	ructions of the United State	es Department of the	Interior, Bureau	of Land	7	╂╌╂╌╂╌╋		- - 	-
Mar	agement or by a	decree of	a Court of Law and/or that t ith the rules of the Michigar	he corner points me	ntioned in lines 3,	4 and 5	8 - 19-	20 -21	-22-	23	2 ¹ 4
abo Cou	ve were in como irt_of_Law:_esta	rmance w ablished.	re-established, monument	ted, re-monumente	d, recovered, fo	und as	9	╄┼┼┼			-+
exp	ressed below:			•			1030	2928	27-	26	25
NO.			corners, all in the same	town and range, r	may be recorde	ed	11	 			
	on this c	ertificate	•				12 -31-	32 - 33	34-	3'5	36
Α.	Description of	f original	monument and accesso	ries and/or subse	quent restoration	on:	13	 		<u> </u>	L4
•							01E 40	100 L/ENE			
	A-1 18		LO	Lyon		Post P.A					
			ity of Grand Rapid illiams & Works	as		Iron PEE					_
	198		CRC #2933	Bonnema	PK N	Iron _{CH/}	AIRMAN	Var	JM	up	el
	198		CRC #4042	By1		eel Bar	& "KEN"	r co. RÆI	MON."	cap	
			this corner was								
	Peer Gro	up, mo	numented by Willi	am R. Byl on	11/30/84 a	nd was r	ecorded	per LCR	RC #404	2.	
						•					
3.	Description of	f corner of	evidence found and/or m	nethod applied in	restoring or ree	stablishing	corner:				
	A-1 Fou	nd Ste	el Bar (1/2" x 6") with "KENT	CO. REMON	." cap pe	er witn	esses fi	om abo	ove	
	LCRC as	set by	William R. Byl i	in place of t	he PK Nail						
	remaining	g witne	esses and survey	data by other	rs.						
	LCRC #40	40									
			. side traffic si	anal nole	S45°E	56.86'					
			. side traffic si		N45°W	51.91'					
			k veneer of build		N55°E	75.45'					
			dation of building		S15°E	118.15					
	NE cor	. found	dation of building	9	\$45°₩	44.79'					
			ocation is accep ne best available							nal	
Э.	Description of	monum	ent for corner and acces	sories established	d to perpetuate	locating the	position	of the corn	er:		
•	A-1 Stee	l Bar a	and "KENT CO. REM	ON." cap							
			g E. side traffic		\$45°I	E 56.7	6'	, <u></u>	No. of Lot		

Nail & tag N. side traffic signal pole SW cor. brick veneer of building NW cor. foundation of building

NE cor. foundation of building

ale 112794

51.98'

75.40'

44.86

119.17

N45°W

N55°E

S15°E

S45°W

William R.
Byl
Registered Land
Surveyor
No.
23502

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975