MAR 0 3 1998



SECTION

LAND CORNER RECORDATION CERTIFICATE

For co	orners in		r		Ment of Act 74, Wich. P.A JNTY REMONUMENTATIO				W.		TOR		71	
Kent (County)			Located	in: Grattan Township	Corner Code #		PEEDS AM 9: 00							
1. F	ublic Lan	d Šurvey	Т	R_ <u>9W</u> R R	A-10					S		,		
2. F	Property C	Controlling s	T T	_ R _ R		}								
ii	Section		3 T				1	030	4.					
3. Miscellaneous			STR			Rec	Register of Deeds Stamp & File Number							
F	roperty in	n Sec.	3T	_ я	£	110								
		, Rec				· · · · · · · · · · · · · · · · · · ·								
5, 1	TIVALE CI	aii 115					A B	C D	E I	: G	B ∣	J	K	
						Section 1	26				- g —	 	+	-
1.	Bandy Ko	niehouse	in a field surve	von Jul	v 1 19	97	3				\Box		_	
I, Randy Kolehouse , in a field survey on July 1 19 97 , 4 7 8 9 10 11 19 19 19 19 19 19 19 19 19 19 19 19											1			
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the														
current manual of survey instructions of the United States Department of the interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5											-	—1		
					r points mentioned in lines 3, 4 Land Surveyors or by a Deci		7	-			+-		十	_
	of Law;				monumented, recovered, for		8	20) 2	1	-22	23		—2
expre	ssed belov	v:					9				-}}	┝─┤	-	
NOTE		more than 4 corn ils certificate.	ers, all in the same town and range, may be recorded				10 3	23	2	\	-27-	26	; 	2
A.	Descrip	tion of original m	onument and	accessories a	nd/or subsequent restorati	ion;	12 3	32	:	-	-94 	d	; -	
A-10	1831	G.L.O. Notes	Mu	ullett	Set Post									
	1939	Witness Map		C. Surveyor	1" iron (M-10, T81	N, R10W)								
	1980	L.C.R.C. #14		lliams & Works										
	1982	L.C.R.C. #31		illiams & Works										
•	1989	L.C.R.C. #52	95 J.	Bueche	K.C. Monument	P.A. 345	14830v	RENT	ÇOL	NTY				
	Note: This corner is common with M-10, T8N, R10W.							FO E	428, ~_f)	19 <i>1</i> 7	S	 <u>U</u>	r	,
•		ner was originally d was recorded p			/ Remonumentation Peer G	aroup and	monum	ented l	o y Wil	liams	& W	ork	s	
B.	Descrip	tion of corner ev	idence found a	and/or method	applied in restoring or ree	establishin	ng corn	er:						
A-10					nue (gravel) running North a .'s #1403, #3112, #5295 an						ining			
•		L.C.R.C. #1	403		L.C.R	R.C. #5295								

The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original corner.

Nail & Remon. tag in W side P & T pole S 15° E 45.20'

Nail & Remon. tag in N side corner fence post W 34.36' Nail & Remon. tag in SE side 18" Oak S 45° W 94.44' Nail & Remon. tag in S side 10" Birch S 80° E 59.90'

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

∆_1ი	Decet a	Standard K	ant County	Manumant
			#111 CAGILICIEV	IVICITII II TIPETI

PK nail in face cor fence post West 33.49'

C/L steel fence post S. 25° W. 75.43'

Nail & K.C. remon. tag on W side P. & T. pole S 15° E 45.20' Nail & K.C. remon. tag on N side cor. fence post West 34.36'

Nail & K.C. remon. tag on SE side 18" Oak S 45° W 94.44'

Nail & K.C. remon. tag on S side 10" Birch S 80° E 59.90'

RANDY J KOLEHOUSE LAND

Signed by

EARTH TECH 25854 Surveyor s Michigan License No.