

For	corners in	SECTION	Filing Require	RECORDATION CERTIF ment of Act 74, Mich. P.A JNTY REMONUMENTATIO	. 1970		REG		B DEC	ECEIVE MOOR	SIA SIA
	Kent		Located in: Grattan	Corner Code #	I		위 스	۶. ۱		(C)	40%
		unty)	Township	Joiner Jode "			F R			SS-	}- <u>,-</u> -
1.	Public Land	d Survey	T R	L-9				\$2) 	4 8: <b>0</b> 0		
	Property Coin Section	s	T R			1:	100	3			
	Miscellaned Property in		TR		Regist	er of I	Deeds	Stamp	& File	Numi	ber
I, do it ment in the Land 4 an Decr	Randy Kol hereby certif tioned in line e current ma I Manageme d 5 above w ee of a Co d as express	ehouse , in a by that under requirer by 1 and 2 above were anual of survey instruct ont or by a decree of a were in conformance w urt of Law; establish and below:	nents of P.A. 74 Michigan in conformance with regular ions of the United States D Court of Law and/or that the ith the rules of the Michiga ed, re-established, monum	n P.A. of 1970, the corner ions and rules therefore as repartment of the interior, But a corner points mentioned in Board of Land Surveyors rented, re-monumented, recorner, may be recorded	points equired reau of lines 3, or by a	7-18-	8	9	G H	22	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
		is certificate.		range, may be recorded	11						
A.	Descripti	ion of original monur	nent and accessories an	d/or subsequent restoratio	n: 13		32	33	34-		3
L-9	1837 1983 1986 1991	G.L.O. Notes L.C.R.C. #3649 L.C.R.C. #4432 L.C.R.C. #5901	Cathcart John Bueche R. Kolehouse William Byl	Set Post Set K.C. Monumer Set River Over K.C K.C. Monument	C. Monument	CH.	ER AI AIRM	1990 PROJ	JED _	9]! 4]	24 f
	This com	ier was originally app	roved by the Kent County	Remonumentation Peer G	aroup and mo	onume	ented h	v John	Buet	he o	n

₿. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found a Standard Kent County Monument (broken) on the C/L of 6 Mile Road (bit.) running East and West per L.C.R.C.'s #3649, #4432 and #5901 as set by John Bueche 1/2 way and on line between the Southwest and Southeast corners of Section 24. Reset broken monument.

L.C.R.C. #3649

11/21/83 and was recorded per L.C.R.C. #3649.

K.C. Remon. tag & nail in W. side 6" Oak S 0° W 23.20'

K.C. Remon. tag & nail in S.W. side 12" Poplar S 55° E 48.76'

K.C. Remon. tag & nail in S.W. side 14" Poplar S 70° E 82.65'

PK nail in S. side Power pole N 80° E 122.31'

C/L 18" Poplar n 60° W 95.4'

L.C.R.C. #5901

Nail & KC Remon. tag W. side 6" Oak S00°W 23.18' (m. 23.07') Nail & KC Remon. tag SW side 14" Poplar S55°E 48.72' (m. 48.63') Nail & KC Remon. tag SW side 16" Poplar S70°E 82.62' (m. 82.52') PK Nail & KC Remon. tag S. side P. Pole N80°E 122.31' (m. 122.52') Nail & KC Remon. tag S. side 24" Poplar N60°W 95.21' (m. 95.24') Cut "X" top W. end 12" conc. culv. N50°E 33.81' (m. 33.72')

The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original corner.

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

L-9 Reset a Standard Kent County Monument

Nail & K.C. remon. tag on W side 6" Oak S 00° W 23.07'

Nail & K.C. remon. tag on SW side 14" Poplar S 55° E 48.63'

Nail & K.C. remon. tag on SW side 16" Poplar S 70°E 82.52'

Nail & K.C. remon. tag on S side P. pole N 80° E 122.52'

Nail & K.C. remon. tag on S side 24" Poplar N 60° W 95.24'

"X" cut top W end 12" conc. culv. N 50° E 33.72'

On C/L of bit, road running E-W

KOLEHOUSE ENSCO LAND

Surveyor's Michigan License No.

25854