Mar o 8 199<mark>9</mark>

SECTION

## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in		KENT COUNTY REMONUN	
	Kent	Located in: Grattan Corner Code :	
	(County)	Township	
1.	Public Land Survey	T8NR_9W	- 8. CO. 3. CO.
2.	Property Controlling in Section	STR STR	11005
3.	Miscellaneous Property in Sec.	S T R S T R	Register of Deeds Stamp & File Number
		D. a. of Apple	

, in a field survey on 19 January 28 98 Randy Kolehouse do hereby certify that under requirements of P.A. 74 Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE-Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:

G.L.O. Notes 1979 L.C.R.C. #1281

**Private Claims** 

N. Brookfield J. Fletcher

Set 1/2" Iron Rod (M-13, T9N, R9W)

1981 L.C.R.C. #1677

Williams & Works

Fnd. 1/2" Iron Rod / Set K.C. Monument (M-13, T9N, R9W)

1994 L.C.R.C. #7266 Glaza & Associates

K.C. Monument (M-13, T9N, R9W) P.A. 345 1990 KENT COUNTY

10

Note: This corner is common with M-13, T9N, R9W; A-13, T9N, R8W; A-1,T8N, R8W

PEER APPROVED Z

This corner was originally approved by the Kent County Remonumentation Peer Group and monumented by Williams & Works on 2/26/81 and was recorded per L.C.R.C. #1677.

R Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found a Standard Kent County Monument at the C/L intersection of Montcalm Avenue (gravel) running South, 10 Mile Road (gravel) running West, and Bricker Road (bit.) running East per L.C.R.C.'s #1677 and #7266 as set by Williams & Works in place of a 1/2" iron rod they found which checked L.C.R.C. #1281.

L.C.R.C. #1677

L.C.R.C. #7266

Nail & K.C. Remon. Tag in S'ly Side 22" Oak N 75°W 90.28'

Nail & K.C. Remon. Tag in NE Side 24" Hickory N 25°W 61.40'

Nail & K.C. Remon. Tag in W Side 10" Twin Oak N 12°E 38.90"

Nail & K.C. Remoon. Tag in N Side 8" Apple S 58°E 92.61'

Nail & K.C. remon tag in S'ly side 24" Oak N75°W 90.23'

Nail & K.C. remon tag in NE side 24" Hickory N25°W 61.42' (m. 61.44')

Nail & K.C. remon tag in W side 18" Twin Oak N12°E 38.79' (m. 38.81')

Nail & K.C. remon tag in N side 8" Apple S58°E 92.61' (m. 92.65')

The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original corner.

Description of monument for corner and accessories established to perpetuate locating the position of the corner: C.

M-1 Standard Kent County Monument

Nail & K.C. remon. tag on S'ly side 24" Oak N 75° W 90.23'

Nail & K.C. remon. tag on NE side 24" Oak N 25° W 61.44'

Nail & K.C. remon. tag on W side 18" twin Oak N 12° E 38.81'

Nail & K.C. remon. tag on N side 8" Apple S 58° E 92.65'

On C/L of gravel road running S

On C/L of gravel road running W

On C/L of bit, road running E

URVEYOR ENSED LAND

Signed by

Surveyor's Michigan License No

25854

REVISED JAN., 1983