## SURVEY & REMONUMENTATION

MAR 0 3 1998

## SECTION

		QEOTION	LAND CORNER REC		· · · · —		
Ford	orners in			of Act 74, Mich. P.A. 1 REMONUMENTATION	970	<b>9</b>	
1 01 0						吕 随复数	
	Kent (Coun	ty)	Located in: Cannon Cori Township	ner Code #	RED. CH.	<b>一</b>	
1,	Public Land S	Survey	TR TR	G-5	F DEEDS	AN RECOR	
0 :	Duan anti o Oan	atuallia a	T R		1014m	5 8	
	Property Cor in Section		TR		10117		
	Miscellaneou		TR				
	Property in S		T R		Register of Deeds Stamp	0 & File Number	
4.	Lot No	, Record	ed Plat				
5.	Private Claim	ns			A B C D E F	G H I J K L	
do he in lin curre Mana above Court	ereby certify the same of and 2 and 2 and 2 and 2 and manual of agement or by a were in continuous to the same of	nat under requirements  above were in conformations  a decree of a Court  formance with the ru	a field survey on	O, the corner points mentice therefore as required in f the interior, Bureau of Le mentioned in lines 3, 4 as Surveyors or by a Decree	oned 5	15 14 13	
NOT		re than 4 corners certificate.	, all in the same town and range	, may be recorded	10 30 29 29	272525	
Α.			ument and accessories and/or s	who avent restaration	12 31 32 32	34 35 36	
				·	13		
G-5	1831 1940-54	G.L.O. Notes Notes	Mullett Williams & Works	Set Post Iron	P.A. 345 1990 KENT (		
	1963	Witness Map	K.C. Surveyor	Iron	PEER APPROVED 6 CHAIRMAN Fu	126/9/	
	1963	Notes	MDOT	N/A	CHAIRMAN / For	w/Kuber	
	1979	L.C.R.C. #1268	Exxel Engineering	2" Pipe			
	1984 1991	L.C.R.C. #3873 L.C.R.C. #6311	M. Rosema Chris Marschall	Fnd. Iron / Set K.C K.C. Monument	C. Monument	•	
		er was originally ap	oproved by the Kent County Remer L.C.R.C. #3873.		oup and monumented by M	1. Rosema on	
В.	Descriptio	n of corner evide	nce found and/or method applie	ed in restoring or reesta	ablishing corner:		
G-5							
		L.C.R.C. #38	73	L	C.R.C. #6311		
					sd. 20" Poplar N 17 E 46.15'		
	SE corner brick chimney - S70°W 5.41' SW comer of siding on cottage (0.8' above ground) S41°E 42.17' Nail and remon. tag in W side 24" Poplar - N17°E 46.15' SE corner concrete block fndn to cottage - S19°W 20.02' S edge of water - N 55'			NE corner (Hse. #7 SE comer brick chi SE corner conc. blo	NE corner (Hse. #7197) conc. block Fndn to cottage N 35 W 13.45' SE corner brick chimney S 79 W 5.41' SE corner conc. block Fndn. to cottage S 19 W 20.01' S. edge of water N 55.00'		
	The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original corner.					e evidence	
C.	Description	on of monument fo	or corner and accessories estab	lished to perpetuate lo	ocating the position of the c	corner:	
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.  G-5 Standard Kent County Monument						of Min	
	NE o SE o	or. (hse. #7197) c or. brick chimney t	on W side 20" Poplar N 17° E 46, onc. block fndn. to cottage N 35° to hse. #7197 S 79° W 5.41' In. to hse. #7197 S 19° W 20.01' ake North 55' ±			RANDY J. KOLEHOUSE LAND SURVEYOR No. 25854	
Sign	ed by	way !	DTU TECH	Date	110/9/	CAND SURVE	
Surv	eyor's Michie	gan License No	RTH TECH 25854		M APPROVED BY MICHIGAN STATE BOARD O	FLAND SHRYEVORS IAM 28 (2)	
				FUR	The tag of microtaday STATE BUAKU U		