SURVEY & REMONUMENTATION

MAR 0 3 1998

1. F	orners in SECTIO Kent (County) Public Land Survey	N Located T 8N T 1	iling Requireme KENT COUN in: Cannon Township R 10W R R R	ent of A ITY REM Corner		. 1970	10		REG. OF DEEDS C	Lwid Sond	97 OCT 15 AM 8: 48	RECEIVED FOR RECUMB	STATE OF PROBLEM	
it	Property Controlling n Section Miscellaneous	s T	R R				10		56					
	Property in Sec.	R	Register of Deeds Stamp & File Number											
		, Recorded Plat												
l, do he in line currer Mana above Court	Randy Kolehouse reby certify that under es 1 and 2 above wer nt manual of survey in gement or by a decree were in conformance of Law; establishe	, in a field surver requirements of P.A. 7 re in conformance with structions of the Uniter of a Court of Law and/of with the rules of the Mi ed, re-established, mi	y onJuly 1 4 Michigan P.A. of n regulations and d States Departme or that the corner p ichigan Board of La	1 1970, the rules the ent of the points me and Surv	e corner points me erefore as required e interior, Bureau o ntioned in lines 3, eyors or by a Decr	97 , ntioned I in the of Land 4 and 5 ree of a	2 9 4 5 6 7 8	7		5 - 4 - 4 - 5 - 4 - 5 - 5 - 6 - 6 - 6 - 6 - 6 - 6 - 6 - 6	G H		11 -14	-13 -13 -24
expre NOTE	ssed below: E: Not more than 4	l corners, all in the s	ame town and ra	ange, ma	y be recorded		10	30		92	827		26	—25 —25
	on this certifica			• ,			11						25	-
Α.	• -	inal monument and			•	on:	13						35	
L-13	1969 Notes 1981 L.C.R.0 1985 L.C.R.0 1989 L.C.R.0 Note: This corner i	Wi C. #3308 GI C. #4055 Ex	ne Kent County R) F P	Set Post N/A RR Spike Fnd. RR Spike / S K.C. Monument nentation Peer Gi					by Exx	el Engi	neeri	ng	
В.		•		n beilaa	n restoring or ree	stablish	nina c	orne	er:					
L-13	Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found a Standard Kent County Monument 10' East and 2' South of the C/L intersection of Mc Cabe Avenue (bit.) running North and South and 4 Mile Road (gravel) running East and West per L.C.R.C.'s #4055 and #5286 as set by Exxel Engineering in place of a RR spike they found which checked L.C.R.C. #3308 and the K.C. Surveyor's records.													
	L.C		L.C.R.C. #5286											
	Nail & remon tag in Nail & remon tag in Nail & remon tag in	,	Nail & remon. tag in N side 14" Hickory S 75° W 71.04' Nail & remon. tag in E side 12" Walnut S 04° E 78.43' Nail & remon. tag in N side 10" Hickory S 74° E 75.75' SE cor. house fndn. N 38° E 148.44' PK in remon. tag in N side t. pole N 53° W 73.01' "T" iron East 12.58' K.C. Mon. (L-1, 7-10) West 64.23'											
	The selected locati	on is accepted by me ne original corner.	and is generally	accepte	d by professional	surveyo	ors as	the	best	availab	le evide	∍nce		
C.	•	nument for corner a	nd accessories e	establish	ned to perpetuate	o locatin	ig the	pos	sition	of the	obliger.	MIC	10000	۵.
L-13		•	4" Lliakanı C 7E9	10/71 0/	47					in the	RANE	Y J.	Ç.	2"
	Nail & K.C. re Nail & K.C. re SE cor. hse. t	emon. tag on N side 1 emon. tag on E side 1 emon. tag on N side 1 fnd. N 38° E 148.44' -1, T7N, R10W, West	2" Walnut S 04° i 0" Hickory S 74°	E 78.43'			رھ	100	, <u>/</u>	* CN	KOLEH SURV N 258	ND EYO R	•	A. A.
Sign	ed by $\int Cdd$	FARTH TECH	reple	ege	Date		91	12	/7	/ /"	*******	mini.	*193.	

P.A. 345 1990 KENT COUNTY

PEER APPROVED 7/24/97/
CHAIRMAN TEMPORAL PROVED PROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1671
REVISED MAY 14, 1875
REVISED JAN., 1883

25854

Surveyor's Michigan License No. _