SURVEY & REMONUMENTATION

APR 2 8 1995

KENT COUNTY REMONUMENTATION

STATE OF MICHIGAN COUNTY OF KENT RECEIVED FOR RECORD

COMMISSION

Property in Sec.

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

94 DEC 27 AM 9: 05

REG. OF DEEDS

Register of Deeds Stamp & File Number

P.A. 345 1990 KENT COUNTY

For corners in KENT COUNTY	•	
(County)	Located In:	Corner Code =##
Public Land Survey	T 8N R 12W	M-11
	T R also	(A-11)
:	TR	
2. Property Controlling	S T R	
in Section	S T R	
3. Miscellaneous	S T R	

7911

_ , Recorded Plat 5. Private Claims

William R. Byl Aug. , in a field survey on do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:

PEER APPROVED 12/22/9 1837 Set Post GLO Brookfield Iron at fence postAIRMAN Kent Co. Wit. 1 1/4" Iron 1977 LCRC #1057 LCRC #2135 Set Kent County Monument 1981 Starr 1990 LCRC #5433 Kent County Monument

The position of this corner was previously approved by the Kent County Remonumentation Peer Group, monumented by Robert J. Jonker on 8/24/81 and was recorded per LCRC #2135

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

M-11 Found standard Kent Co. Mon. (Harrison) per witnesses from above LCRC as set by Robert J. Jonker in place of the 1 1/4" x 36" Iron Pipe he found. Said Iron Pipe checks with Kent Co. Wit. and LCRC #1057.

LCRC #2135

LCRC #5433

same witnesses as LCRC #2135

Iron N. 12.04'

Remon. tag 20" Beech Remon. tag 30" Tw. Oa NO1°W 29.17'

S89°E 47.95 Tw. Oak

Remon. tag 30" Oak S35°E 37.72

Remon. tag 20" W. Cherry N25°W

On N-S fence

The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M-11 Standard Kent County Monument

N00°E 12.04' Tron New Nail & KC Remon. tag W. side 24" Beech NO1°W 29.18 New Nail & KC Remon. tag N. side 36" Tw. Oak S89°E 47.89' New Nail & KC Remon. tag SW side 36" Oak S35°E Nail & KC Remon. tag SW side 24" W. Cherry N25°W 37.78' 12.97

On N-S fence

01 B1707 William R. BVI Registered Lan Surveyor No. 23502

23502 Surveyor's Michigan License No.

REVISED JAN., 1983