

FEB 14 1997

KENT COUNTY REMONUMENTATION

COMMISSION LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in KENT COUNTY (County)


Table with columns: Located In, Corner Code #. Rows for Public Land Survey, Property Controlling in Section, Miscellaneous Property in Section.

STATE OF MICHIGAN COUNTY OF KENT RECEIVED FOR RECORD 96 MAR 20 AM 8:58 REG. OF DEEDS

9093

Register of Deeds Stamp & File Number

- 4. Lot No. Recorded Plat
5. Private Claims



I, Kirk Breitels, in a field survey on Jan. 15, 1996, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Table with columns: I-11, 1831, GLO, Mullet, Set Post, 1930, Kent Co. Wit., Iron & Stone, 1973, LCRC #506, Spicer, Iron in Mon. Box, 1981, LCRC #2385, Bueche, Set Kent County Monument in Mon. Box, 1988, LCRC #4858, Bueche, Kent County Monument in Mon. Box, 1993, LCRC #6742, Roon, Set Kent County Monument after const.

P.A. 345 1990 KENT COUNTY PEER APPROVED 3/7/96 CHAIRMAN

The position of this corner was previously approved by the Kent County Remonumentation Peer Group, monumented by John C. Bueche on 11/16/81 and was recorded per LCRC #2385.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I-11 Found standard Kent Co. Mon. (Harrison) per witnesses from above LCRC as set by Russel L. Roon at the same location as set by John C. Bueche in place of the 3/4" x 18" Iron he found inside a Mon. Box. Said Iron in Mon. Box checks with Kent Co. Wit. and LCRC #506.

Table with columns: LCRC #2385 & #4858, SW corner frame house #3187, SE corner frame garage #3187, "X" cut in conc. curb, Nail/tag T & P Pole, Nail/tag T & P Pole, Face of curb; LCRC #6742, Nail/tag 8" Oak, Nail/tag P.P., Top C/L Hydr., SE cor. porch.

The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Table with columns: I-11 Standard Kent County Monument, SW corner frame house #3187, SE corner frame garage #3187, Top C/L Hydr., SE cor. porch, Nail & MDSH tag NW side 10" Oak, Nail & MDSH tag NW side P. Pole, NW face of steel walk signal post.



Signed by [Signature] 30077

Date 2/6/96

Surveyor's Michigan License No. 30077