

SEP 18 1995
COMMISSION

KENT COUNTY REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN
COUNTY OF KENT
RECEIVED FOR RECORD
95 JUN 29 AM 11:51
REG. OF DEEDS
David Spauld

For corners in
KENT COUNTY

	Located In:	Corner Code #
1. Public Land Survey	T <u>8N</u> R <u>12W</u>	<u>A-7</u>
	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

8422

Register of Deeds Stamp & File Number

I, Kirk Breitels, in a field survey on April 3, 1995, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	16	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

A-7 1837 GLO Brookfield Set Post
Ottawa Co. Wit. Sleigh shoe
1986 LCRC #4407 Bueche Set Kent County Monument

The position of this corner was previously approved by the Kent County Remonumentation Peer Group, monumented by John c. Bueche on 3/11/85 and was recorded per LCRC #4407.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A-7 Found standard Kent Co. Mon. (Harrison) per witnesses from above LCRC as set by John C. Bueche in place of the Rerod he found. Said Rerod checks with previous survey data by others and testimony of property owner as to the location of corner.

LCRC #4407

PK Nail in top of fence post S20°E 4.19'
Nail E. side 12" Box Elder S20°E 29.10'
Nail E. side 10" Box Elder S40°E 56.58'
Nail S. side 8" Maple S80°E 42.18'

P.A. 345 1990 KENT COUNTY
PEER APPROVED 6/22/95
CHAIRMAN Harry Hubert

The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-7 Standard Kent County Monument

PK Nail in top of fence post S20°E 4.60' (leaning S'ly)
Set Nail & KC Remon. tag E. side 16" Box Elder S20°E 29.01'
Set Nail & KC Remon. tag E. side 14" Box Elder S40°E 56.64'
Set Nail & KC Remon. tag S. side 12" Box Elder S80°E 42.06'
C/L ditch to NW & E is N 6' m/l



Signed by Kirk Breitels
Surveyor's Michigan License No. 30077

Date 6/22/95