## SURVEY & REMONUMENTATION





STATE OF HIGHIGA COUNTY OF HEAT RECEIVED FOR LEDAS

APR 28 1995

## KENT COUNTY REMONUMENTATION

## COMMISSION

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

		LD ;	unt,	2 C(	16
94	DEC	27	AM	S:	04

REG. OF DEEDS

7909

Register of Deeds Stamp & File Number

For corners in KENT COUNTY						
		Located In:	Corner Code ≠#			
1.	Public Land Survey	T 8N R 12W	L-11			
		T R T R				
		T R				
2.	, ,	S T R				
	in Section	S T R				
3	Miccellaneous	STR				

\_\_ T \_\_\_\_ R \_\_

4. Lot No. \_\_\_\_\_\_, Recorded Plat \_

Private Claims \_\_\_

Property in Sec.

I, William R. Byl., in a field survey on Aug. 1, 19, 94, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:

P.A. 345 1990 KENT COUNT

L-11	1838	GLO	Whitcomb	Set Post PEER APPROVED 12/22/3 "X" in pavement CHAIRMAN 3/4" Iron in mon. box
	1960	Kent Co. Wit.		"X" in pavement CHAIRMAN
	1977	LCRC #1057	Bonnema	3/4" Iron in mon. box
	1981	LCRC #2614	Nederveld	Set Kent County Monument
	1990	LCRC #5422	Starr	Kent County Monument

The position of this corner was previously approved by the Kent County Remonumentation Peer Group, monumented by Gordon D. Nederveld on 9/15/81 and was recorded per LCRC #2614

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

L-11 Found standard Kent Co. Mon. (Harrison) per witnesses from above LCRC as set by Gordon D. Nederveld in place of the 3/4" Iron he found inside a mon. box. Said Iron in mon. box checks with Kent Co. Wit. and LCRC #1057.

LCRC #2614			LCRC #5422			
Nail & tag P. Pole	S00°W	29.65	Nail & KC tag W. side P. Pole	W <sup>o</sup> 002	29.65'	
Nail & tag Tw. Maple	NO0°E	35.80'	NE cor. porch foundation	S21°W	88.80'	
NE cor. porch fnd.	S21°W	88.80'	NW cor. hse. foundation	S39°E	124.50'	
NW cor. hse. fnd.	S39°E	124.50'	Plat Mon.	NO0°E	50.01'	
Plat Mon.	NOO <sup>o</sup> E	50.01	Nail & KC tag W. side 12" Maple	N30°W	50.35	
			Nail & KC tag SE side 10" Tree	N60°E	87.58.	
			On C/L E-W bit. rd.; On fence line N.			

The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the position of monument for corner and accessories established to perpetuate locating the position of the corner.

On tree row N-S

L-11 Standard Kent County Monument Nail & KC Remon. tag W. side P. Pole SOOPW 29.65' NE cor. porch foundation NW cor. hse. foundation S21°W 88.85' S39°E 124.53 NOO°E 50.01' Plat Monument New Nail & KC Remon. tag W. side 12" Maple New Nail & KC Remon. tag SE side 10" Tree N30°W 50.37' N60°E 87.62' On C/L E-W bit. rd.; On fence line N.

23502

On tree row N-S

Date 12 07 94

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971

REVISED MAY 14, 1975 REVISED JAN., 1983

William R.

Dyl

Registered Land

Surveyor

No. 23502

【大照》

Surveyor's Michigan License No.

\_\_\_\_\_ Dat