



For corners in

MAR 08 1999

## LAND CORNER RECORDATION CERTIFICATE

on the same of the same	Filin	Filing Requirement of Act 74, Mich. P.A. 1970			
BECTION	<b>V</b>	KENT COUNTY REMONUMENTATION			
	Located in:	Oakfield	Corner Code #	1	

	(County)		eakfield Corner Code # wnship
1.	Public Land Survey	T <u>9N</u> R_9	9WH-13
		<b>T</b> R_	
		T R_	
		T R_	
2.	Property Controlling	SR_	
	in Section	SR_	
3.	Miscellaneous	S T R_	
	Proporty in Soc	C T D	

STATE OF MICHIGAN COUNTY OF KENT RECEIVED FOR RECORD

38 DEC 14 AM 8: 00

REG. OF DEEDS

10957

Register of Deeds Stamp & File Number

4.	Lot No, Re	orded Plat	<del> </del>
5.	Private Claims		

I, Randy Kolehouse, in a field survey on January 30 19 98, do hereby certify that under requirements of P.A. 74 Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

H-13	1837	G.L.O. Notes
	1965-77	Notes
	1980	L.C.R.C. #3329
	1985	L.C.R.C. #4118

1994

N. Brookfield Williams & Works Glaza & Associates

Glaza & Associates

William Byl

Set Post "T" Iron "T" Iron P.A. 345 1990 KENT COUNTY
PEER APPROYED 9/24/99

Fnd. "T" Iron / Set K.C. Monument K.C. Monument

Note: This corner is not common with H-1, T8N, R9W.

L.C.R.C. #7213

This corner was originally approved by the Kent County Remonumentation Peer Group and monumented by William Byl on 11/5/84 and was recorded per L.C.R.C. #4118.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

H-13 Found a Standard Kent County Monument 4' North of a fence line running East and 170' ± East of the C/L of McArthur Avenue (gravel) running North and South per L.C.R.C.'s #4118 and #7213 as set by William Byl in place of a "T" iron he found which checked L.C.R.C. #3329 and the 1965-77 notes of Williams & Works.

L.C.R.C. #4418

Nail & tag, W sd. Trip. 18" Hickory S 45 E 75.37'
Nail & tag, S sd. 12" Hickory N 80 E 31.80'
Nail & tag, E sd. 8" Oak N 30 W 44.13'
East-West fence S 00 E 4.4'

L.C.R.C. #7213

Nail & K.C. remon tag in W side 18" Triple Hickory S45°E 75.37'
Nail & K.C. remon tag in S side 14" Hickory N80°E 31.85'
Nail & K.C. remon tag in E side 12" Oak N30°W 44.15'

East-West fence S00°E 4.40'

Kent Co. Mon (N 1/4 cor, Sec 3, T8N, R9W) N90°W 170.68' (m. 170.69')

The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original corner.

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

H-13 Standard Kent County Monument

Nail & K.C. remon. tag on W side 18" triple Hickory S 45° E 75.37'

Nail & K.C. remon. tag on S side 14" Hickory N 80° E 31.85'

Nail & K.C. remon. tag on E side 12" Oak N 30° W 44.15'

Nail & K.C. remon. tag on N side 12" Cherry N 90° W 31.98"

Fence line running E, South 4'

C/L of gravel road running N-S, West 170' ± K.C. Mon., H-1, T8N, R9W, N 90° W 170.69'

d by Pany & Kale hom

Date 11/18/98

RANDY J.
KOLEHOUSE
LAND
SURVEYOR
No
25854
1 AND SURVEYOR
1 AND SURVEYOR

Signed by\_

C.

Surveyor's Michigan License No.

25854