\$7.00 \$7.00 MAR 08 1999

KENT COUNTY REMONUMENTATION

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in	\ 8 a v	
KENT COUNTY Located In: Corner Code #	REG. C AR CHARA	
(County)	- 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
1. Public Land Survey T 9N R 11W	OF MOUNGAN OF OR LECON OF DEEDS	
2. Property Controlling S TR	\ \tag{8}	
B. Miscellaneous S T R	10579	
Property in Sec. S TR	Register of Deeds Stamp & File Number	
	. 1	
4. Lot No, Recorded Plat	ABCDEFGHIJKLM	1
5. Private Claims	1 2 5 5 4 3 2 1	
	3	1
, Kirk Breitels , in a field survey on Jan. 23 , 19 98 do hereby state t	hat under 4 7 8 9 10 11 12	
equirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above conformance with regulations and rules therefore as required in the current manual of survey instructions.	re were in _	
United States Department of the Interior, Bureau of Land Management or by a decree of a Court of La that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the	aw and /or 6 18 17 16 15 14 13	$\frac{1}{1}$
Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, mon		
recovered, found as expressed below:	8 19 20 21 22 23 24 24	
NOTE: Not more than 2 comers, all in the same town and range, may be recorded	9	
on this certificate.	10 30 29 28 27 26 25	•
	11 31 35 36	
	13	ا
A. Description of original monument and accessories and/or subsequent restoration:		
M-4 1837 GLO Brookfield Set Post	P.A. 345 1990 KENT COUNTY	
1964 Kent Co. Wits PK Spike	PEER APPROVED 2/19/18/ CHAIRMAN Hamy Huber	
1974 LCRC #729 Nederveld PK Nail 1982 LCRC #3121 Merdzinski Set Kent County Monument	CHAIRMAN Jamy Juker	
1994 LCRC #7061 Byl Kent County Monument		
The position of this corner was previously approved by the Kent County Re	monumentation Page Group, monumented	
by John A. Merdzinski on 10-27-82 and was recorded per LCRC #3121.	monumentation recreation, monumented	
B. Description of corner evidence found and/or method applied in restoring or reestable	ishing corner.	
M-4 Found Kent County Monument (Harrison) per witnesses from above LCRC	-	
PK Nail he found. Said PK Nail checks with Kent Co. Wits. and LCRC #72 LCRC #3121 LCRC #7061	29.	
Nail & Remon. tag P. Pole N45°E 152.55' Nail & Remon. tag P. Nail & Remon. tag L. Nail & Remon. tag L. Nail & Remon. tag L.		
SW corner house S35°E 160.02' Cut "X" top of curb	N75°W 59.03'	
S'ly corner MBT Box S75°W 71.15' Cut "X" top of curb	N15°W 56.16'	
C/L Northland Dr. (Asph.) is East 6' On C/L Russell St. E-W S'ly corner MBT Box	andation S35°E 159.93' x S75°W 71.15'	
The selected location is accepted by me and is generally accepted by profess	sional surveyors as the best available	
evidence of the position of the original corner. C. Description of monument for corner and accessories established to perpetuate locat	ing the position of the corner:	
M-4 Standard Kent County Monument	OF MICH	
Nail & KC Remon. tag SE side Power Pole N45°E 152.55'	Ta Marie Carlo	
Nail & KC Remon. tag E. side Light Pole S20°W 148.63' Cut "X" on top of conc. curb (6' E. of W. end) N75°W 59.03'	BREITELS BREITELS	
Cut "X" on top of conc. curb (6' S. of N. end) N15°W 56.16'	LAND	
SW corner of house foundation S35°E 159.93'	SURVEYOR NO	
S'ly corner to Tele. Box S75°W 71.15' C/L Northland Dr. (Asph. pavement) is East 6'	30077	
On C/L Russell St, E-W	OLAND SOME	
1/1 2 1/2	The state of the s	
	KIRK BREITELS LAND SURVEYOR NO 30077	-
Surveyor's Michigan License No. 30077		