MAR 0 8 1999

KENT COUNTY REMONUMENTATION

For consens in SCOTONY Located in: Control Code # KENT COUNTY Located in: Consens 1. Public Land Survey TON R 10W A-10			SECTION			RECORDATION			æ \	38 O	REC	→
Compared Code # Compared Code # Compared Code #			ues r				1		5 5			- - - :
1. Public Land Survey TON R 10W A-10 TON R 10W A-1	KI	ENT COUN	. <u></u> l	_ocated In:	Corne	r Code #		9				· }
1. Public Land Survey TNR 10W A-10 TNR 10W TNR 1		(Coun	ity)				,	ſ	11 10V0 -	∞ رز	웃유종	•
in Section S T R Property in Sec. S T R Property in Sec. S T R R Recorded Plat S. Private Claims Kirk Breitels	1. P	ublic Land	Survey		<u>W</u>			i C	Fig. 2	H 10: 15		
Property in Sec. S T R Register of Deeds Stamp & File Number 4. Lot No. 5. Private Claims Kirk Breitels Kirk B			ntrolling S	S TR S T R					460	m o		
A. Lot No				S TR			;		106	76		
4. Lot No, Recorded Plat	P	roperty in S	Sec. S	S TR]	Regist	er of Deed	ls Stam	p & File t	Number
S. Private Claims in a field survey on Scpt. 9 19 98 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore are required in the current ramual of survey instructions of the furnish 3 alales Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for half the corner points mentioned in lines 3, 4 and 5 above were in conformance with the current ramual of survey instructions or the furnish of Land Surveyors or by a Decree of a Court of Law, established, monumented, recent of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, monumented, recent law and for the three covered, count as expressed below. NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. P.A. 345 1990 KENT COUNTY PEER APPROVED 97.00 April 1990 KENT COUNTY PEER APPROVED 97				•					· ··· ··		·	
Kirk Breitels In a field survey on Sept. 9 19 98 do hereby slate that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the corner points mentioned in lines 3, 4 and 5 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the band of that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Band of Land Surveyors or by a Deciee of a Court of Law, established, menumented, recovered, found as expressed below: NOTIE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. M-10 1837 GLO Brookfield Set Post Post Nent Co. Wits PK in pavement PSE K in pavement	4. L	ot No	, Recorded	Plat			1	АВ	CDE	F G	нтл	к т. м
Kirk Breitels in a field survey on Sept. 9 19 8 do hereby state that under requirements of P.A. 74. Michigen P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior. Bursun of Land Management of by a decree of a Court of Law and for that the corner points mentioned in lines 3.4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Bectree of a Court of Law, established, re-established, monumented, recovered, found as expressed below. NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: M-10 1837 GLO Brookfield Set Post Rent Co. Wits PK in pavement PFER APPBOYED ALLERS For Set Kent County Monument in Mon. Box The position of this corner was previously approved by the Kent County Remonumentation Peer Group, monumented by Robert J. Jonker on 8-26-81 and was recorded per LCRC #1986. Description of corner evidence found and/or method applied in restoring or reestablishing corner: M-10 Found PK Nail at same location as Kent Co. Mon. per witnesses from above LCRC as set by Robert J. Jonker in place of the ½" Copper Conduit the found inside a Mon. Box. Said Copper Conduit checks LCRC's #928 & 1986. LCRC #1986 Nail & Remon. tag 14" Maple S88"E 69.16' Nail & Remon. tag 18" Maple S88"E 69.16' Nail & Remon. tag 9" Locust N75" W 40.9' Nail & Remon. tag 18" Maple S88"E 69.16' Nail & Remon. tag 6" Oak N43" W 41.05' Nail & Remon. tag 10" Oak N43" W 41.20' C/L traveled way, Easterly 6' ± The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:	J. F	nvate Ciain	ns					1		ÌΪ	ΪΪĬ	ΪΪ
I, Kitk Breitels , in a field survey on Scpt. 9 19 8 do hereby state that under requirements of PA. 74, Michigan PA. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management of to 9 a decree of a Court of Law and for that the corner points mentioned in lines 3,4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented recovered, frout as supressed below: NOTIE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: M-10 1837 GLO Brookfield Set Post Pk in pavement 1976 LCRC #1986 Jonker Set Kcnt County Monument in Mon. Box Kent Co. Wits Pk in pavement 1981 LCRC #1986 Jonker Set Kcnt County Monument in Mon. Box The position of this corner was previously approved by the Kent County Remonumentation Peer Group, monumented by Robert J. Jonker on 8-26-81 and was recorded per LCRC #1986. Description of corner evidence found and/or method applied in restoring or reestablishing corner: M-10 Found PK Nail at same location as Kent Co. Mon. per witnesses from above LCRC as set by Robert J. Jonker in place of the ½" Copper Conduit he found inside a Mon. Box. Said Copper Conduit checks LCRC's #928 & 1986. LCRC #1986 Nail & Remon. tag 14" Maple S88°E 69.16' Nail & Remon. tag 18" Maple S88°E 69.16' Nail & R		•						-1 i	5-	1	3- 2-	1
requirements of P.A. 74, McNigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management of by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, monumented, recovered, found as expressed below. NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: M-10 1837 GLO Brookfield Set Post PK in pavement 1976 LCRC #1986 Jonker Set Kent County Monument in Mon. Box Kent Co. Wits PK in pavement 1981 LCRC #1986 Jonker Set Kent County Monument in Mon. Box The position of this corner was previously approved by the Kent County Remonumentation Peer Group, monumented by Robert J. Jonker on 8-26-81 and was recorded per LCRC #1986. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: M-10 Found PK Nail at same location as Kent Co. Mon. per witnesses from above LCRC as set by Robert J. Jonker in place of the ½" Copper Conduit he found inside a Mon. Box. Said Copper Conduit checks LCRC's #928 & 1986. LCRC #1986 Nail & Remon. tag 14" Maple S88°E 69.16' Nail & Remon. tag 18" Maple S88°E 69.16' Nail & Remon. tag 9" Locust N75°W 40.9' Nail & Remon. tag 18" Maple S88°E 69.16' Nail & Remon. tag 19" Locust N75°W 40.9' Nail & Remon. tag 10" Oak N43°W 41.20' CL traveled way, Easterly 6' ± The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:	,]	Kirk Breitels	S in	a field survey on	Sept. 9	19 98 de bezelou	elete that under	1				
United States Department of the Interior, Bureau of Land Management of by a decree of a Count of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, re-establish	requi	rements of P.	.A. 74, Michigan P.,	A. of 1970, the corner	points ment	ioned in lines 1 and	2 above were in					12-1
that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below: NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: M-10 1837 GLO Brookfield Set Post PK in pavement PK in pavement PK in pavement PEER APPROVED #721 #85 CHAIRMAN	confe Unite	rmance with r d States Depa	egulations and rule: artment of the Interi	s therefore as required i or . Bureau of ! and Mar	in the current pagement or	nt manual of survey in thy a decree of a Cou	structions of the					
P.A. 345 1990 KENT COUNTY Motificate. A. Description of original monument and accessories and/or subsequent restoration: M-10 1837 GLO Kent Co. Wits PK in pavement 1976 LCRC #928 McCloskey Monument 1981 LCRC #1986 Jonker Set Kent County Monument in Mon. Box The position of this corner was previously approved by the Kent County Remonumentation Peer Group, monumented by Robert J. Jonker on 8-26-81 and was recorded per LCRC #1986. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: M-10 Found PK Nail at same location as Kent Co. Mon. per witnesses from above LCRC as set by Robert J. Jonker in place of the ½" Copper Conduit the found inside a Mon. Box. Same Copper Conduit checks LCRC's #928 & 1986. LCRC #1986 Nail & Remon. tag 26" Box Elder S38°E 120.5' Nail & Remon. tag 14" Maple Nail & Remon. tag 9" Locust N75°W 40.9' Nail & Remon. tag 9" Locust N75°W 40.9' Nail & Remon. tag 10" Oak N43°W 41.05' Nail & Remon. tag 10" Oak N43°W 41.20' C/L traveled way, Easterly 6' ± The selected location of the original corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:	that I	the corner pol	ints mentioned in fir	nes 3, 4 and 5 above we	ere in confor	mance with the rules	of the Michigan	1 1			15 14	13-
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: M-10 1837 GLO Brookfield Set Post PK in pavement 1976 LCRC #928 McCloskey Monument 1981 LCRC #1986 Jonker Set Kent County Monument in Mon. Box 1994 LCRC #7067 Byl Kent County Monument in Mon. Box The position of this corner was previously approved by the Kent County Remonumentation Peer Group, monumented by Robert J. Jonker on 8-26-81 and was recorded per LCRC #1986. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: M-10 Found PK Nail at same location as Kent Co. Mon. per witnesses from above LCRC as set by Robert J. Jonker in place of the ½" Copper Conduit the found inside a Mon. Box. Said Copper Conduit checks LCRC's #928 & 1986. LCRC #1986 LCRC #7067 Nail & Remon. tag 26" Box Elder S38°E 120.5' Nail & Remon. tag 14" Maple S88°E 69.16' Nail & Remon. tag 9" Locust N75°W 40.9' Nail & Remon. tag 18" Maple S88°E 69.16' Nail & Remon. tag 6" Oak N43°W 41.05' C/L traveled way, Easterly 6' ± The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.	recov	u of Land Su rered, found as	irveyors or by a L sexpressed below:	ecree of a Court of I	Law; establ	ished, re-established	i, monumented,	1	20	21	22 23	24
A. Description of original monument and accessories and/or subsequent restoration: M-10 1837 GLO Brookfield Sct Post PK in pavement PEER APPROVED 9 24 8 McCloskey Monument 1981 LCRC #1986 Jonker Set Kent County Monument in Mon. Box The position of this corner was previously approved by the Kent County Remonumentation Peer Group, monumented by Robert J. Jonker on 8-26-81 and was recorded per LCRC #1986. E. Description of corner evidence found and/or method applied in restoring or reestablishing corner: M-10 Found PK Nail at same location as Kent Co. Mon. per witnesses from above LCRC as set by Robert J. Jonker in place of the ½" Copper Conduit the found inside a Mon. Box. Said Copper Conduit checks LCRC's #928 & 1986. LCRC #1986 Nail & Remon. tag 26" Box Elder S38°E 120.5' Nail & Remon. tag 14" Maple S88°E 69.16' Nail & Remon. tag 9" Locust N75°W 40.9' Nail & Remon. tag 18" Maple S88°E 69.16' Nail & Remon. tag 9" Locust N75°W 40.9' Nail & Remon. tag 12" Locust N75°W 40.91' Nail & Remon. tag 6" Oak N43°W 41.05' Nail & Remon. tag 10" Oak N43°W 41.20' C/L traveled way, Easterly 6' ± The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.	NOT	T: Notmo	rothan 2 cornorn	all in the same tour				1 1				
A. Description of original monument and accessories and/or subsequent restoration: M-10 1837 GLO Brookfield Set Post Kent Co. Wits PK in pavement 1976 LCRC #928 McCloskey Monument 1981 LCRC #1986 Jonker Set Kent County Monument in Mon. Box 1994 LCRC #7067 Byl Kent County Monument in Mon. Box The position of this corner was previously approved by the Kent County Remonumentation Peer Group, monumented by Robert J. Jonker on 8-26-81 and was recorded per LCRC #1986. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: M-10 Found PK Nail at same location as Kent Co. Mon. per witnesses from above LCRC as set by Robert J. Jonker in place of the ½" Copper Conduit he found inside a Mon. Box. Said Copper Conduit checks LCRC's #928 & 1986. LCRC #1986 Nail & Remon. tag 26" Box Elder S38°E 120.5' Nail & Remon. tag 33" Box Elder S38°E 120.40' Nail & Remon. tag 9" Locust N75°W 40.9' Nail & Remon. tag 18" Maple S88°E 69.16' Nail & Remon. tag 9" Locust N75°W 40.9' Nail & Remon. tag 12" Locust N75°W 40.91' Nail & Remon. tag 6" Oak N43°W 41.05' Nail & Remon. tag 10" Oak N43°W 41.20' C/L traveled way, Easterly 6' ± The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.	NO			and the same town :	anu range,	may be recorded]	29	28	27 26	25
A. Description of original monument and accessories and/or subsequent restoration: M-10 1837 GLO Brookfield Set Post Kent Co. Wits PK in pavement 1976 LCRC #928 McCloskey Monument 1981 LCRC #1986 Jonker Set Kent County Monument in Mon. Box 1994 LCRC #7067 Byl Kent County Monument in Mon. Box The position of this corner was previously approved by the Kent County Remonumentation Peer Group, monumented by Robert J. Jonker on 8-26-81 and was recorded per LCRC #1986. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: M-10 Found PK Nail at same location as Kent Co. Mon. per witnesses from above LCRC as set by Robert J. Jonker in place of the ½" Copper Conduit he found inside a Mon. Box. Said Copper Conduit checks LCRC's #928 & 1986. LCRC #1986 Nail & Remon. tag 26" Box Elder S38°E 120.5' Nail & Remon. tag 33" Box Elder S38°E 120.40' Nail & Remon. tag 9" Locust N75°W 40.9' Nail & Remon. tag 18" Maple S88°E 69.16' Nail & Remon. tag 9" Locust N75°W 40.9' Nail & Remon. tag 12" Locust N75°W 40.91' Nail & Remon. tag 6" Oak N43°W 41.05' Nail & Remon. tag 10" Oak N43°W 41.20' C/L traveled way, Easterly 6' ± The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.								11				
M-10 1837 GLO Brookfield Set Post Kent Co. Wits PK in pavement 1976 LCRC #928 McCloskey Monument 1981 LCRC #1986 Jonker Set Kent County Monument in Mon. Box 1994 LCRC #7067 Byl Kent County Monument in Mon. Box The position of this corner was previously approved by the Kent County Remonumentation Peer Group, monumented by Robert J. Jonker on 8-26-81 and was recorded per LCRC #1986. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: M-10 Found PK Nail at same location as Kent Co. Mon. per witnesses from above LCRC as set by Robert J. Jonker in place of the ½" Copper Conduit he found inside a Mon. Box. Said Copper Conduit checks LCRC's #928 & 1986. LCRC #1986 LCRC #1067 Nail & Remon. tag 26" Box Elder S38°E 120.5' Nail & Remon. tag 33" Box Elder S38°E 120.40' Nail & Remon. tag 14" Maple S88°E 69.16' Nail & Remon. tag 18" Maple S88°E 69.16' Nail & Remon. tag 9" Locust N75°W 40.9' Nail & Remon. tag 12" Locust N75°W 40.91' Nail & Remon. tag 6" Oak N43°W 41.05' Nail & Remon. tag 12" Locust N75°W 40.91' Nail & Remon. tag 6" Oak N43°W 41.05' Nail & Remon. tag 10" Oak N43°W 41.20' C/L traveled way, Easterly 6' ± The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:									32	33	 3435.	36
M-10 1837 GLO Brookfield Set Post Kent Co. Wits PK in pavement 1976 LCRC #928 McCloskey Monument 1981 LCRC #1986 Jonker Set Kent County Monument in Mon. Box 1994 LCRC #7067 Byl Kent County Monument in Mon. Box The position of this corner was previously approved by the Kent County Remonumentation Peer Group, monumented by Robert J. Jonker on 8-26-81 and was recorded per LCRC #1986. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: M-10 Found PK Nail at same location as Kent Co. Mon. per witnesses from above LCRC as set by Robert J. Jonker in place of the ½" Copper Conduit he found inside a Mon. Box. Said Copper Conduit checks LCRC's #928 & 1986. LCRC #1986 LCRC #1067 Nail & Remon. tag 26" Box Elder S38°E 120.5' Nail & Remon. tag 33" Box Elder S38°E 120.40' Nail & Remon. tag 14" Maple S88°E 69.16' Nail & Remon. tag 18" Maple S88°E 69.16' Nail & Remon. tag 9" Locust N75°W 40.9' Nail & Remon. tag 12" Locust N75°W 40.91' Nail & Remon. tag 6" Oak N43°W 41.05' Nail & Remon. tag 12" Locust N75°W 40.91' Nail & Remon. tag 6" Oak N43°W 41.05' Nail & Remon. tag 10" Oak N43°W 41.20' C/L traveled way, Easterly 6' ± The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:								13		<u> </u>		
Rent Co. Wits PK in pavement PEER APPROVED \$\frac{124.08}{0.0000} \] 1976 LCRC #928 McCloskey Monument GHAIRMAN GHAIRMAN Monument 1981 LCRC #1986 Jonker Set Kent County Monument in Mon. Box 1994 LCRC #7067 Byl Kent County Monument in Mon. Box The position of this corner was previously approved by the Kent County Remonumentation Peer Group, monumented by Robert J. Jonker on 8-26-81 and was recorded per LCRC #1986. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: M-10 Found PK Nail at same location as Kent Co. Mon. per witnesses from above LCRC as set by Robert J. Jonker in place of the ½" Copper Conduit he found inside a Mon. Box. Said Copper Conduit checks LCRC's #928 & 1986. LCRC #1986 LCRC #1086	A . [Description o	of original monum	ent and accessories	and/or su	bsequent restorati	on:	D. 4	45 4000	177417	COUNT	rs.r
1976 LCRC #928 McCloskey Monument 1981 LCRC #1986 Jonker Set Kent County Monument in Mon. Box 1994 LCRC #7067 Byl Kent County Monument in Mon. Box The position of this corner was previously approved by the Kent County Remonumentation Peer Group, monumented by Robert J. Jonker on 8-26-81 and was recorded per LCRC #1986. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: M-10 Found PK Nail at same location as Kent Co. Mon. per witnesses from above LCRC as set by Robert J. Jonker in place of the ½" Copper Conduit he found inside a Mon. Box. Said Copper Conduit checks LCRC's #928 & 1986. LCRC #1986 Nail & Remon. tag 26" Box Elder S38°E 120.5' Nail & Remon. tag 33" Box Elder S38°E 120.40' Nail & Remon. tag 14" Maple S88°E 69.16' Nail & Remon. tag 14" Maple S88°E 69.16' Nail & Remon. tag 9" Locust N75°W 40.9' Nail & Remon. tag 12" Locust N75°W 40.91' Nail & Remon. tag 6" Oak N43°W 41.05' Nail & Remon. tag 10" Oak N43°W 41.20' C/L traveled way, Easterly 6' ± The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:	l	M-10 1837								•	, ,	08
1981 LCRC #1986 Jonker Set Kent County Monument in Mon. Box 1994 LCRC #7067 Byl Kent County Monument in Mon. Box The position of this corner was previously approved by the Kent County Remonumentation Peer Group, monumented by Robert J. Jonker on 8-26-81 and was recorded per LCRC #1986. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: M-10 Found PK Nail at same location as Kent Co. Mon. per witnesses from above LCRC as set by Robert J. Jonker in place of the ½" Copper Conduit he found inside a Mon. Box. Said Copper Conduit checks LCRC's #928 & 1986. LCRC #1986 LCRC #7067 Nail & Remon. tag 26" Box Elder S38°E 120.5' Nail & Remon. tag 33" Box Elder S38°E 120.40' Nail & Remon. tag 14" Maple S88°E 69.16' Nail & Remon. tag 18" Maple S88°E 69.16' Nail & Remon. tag 9" Locust N75°W 40.9' Nail & Remon. tag 12" Locust N75°W 40.91' Nail & Remon. tag 6" Oak N43°W 41.05' Nail & Remon. tag 10" Oak N43°W 41.20' C/L traveled way, Easterly 6' ± The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:		1076									124/	1.46
The position of this corner was previously approved by the Kent County Remonumentation Peer Group, monumented by Robert J. Jonker on 8-26-81 and was recorded per LCRC #1986. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: M-10 Found PK Nail at same location as Kent Co. Mon. per witnesses from above LCRC as set by Robert J. Jonker in place of the ½" Copper Conduit he found inside a Mon. Box. Said Copper Conduit checks LCRC's #928 & 1986. LCRC #1986 LCRC #1986 LCRC #7067 Nail & Remon. tag 26" Box Elder S38°E 120.5' Nail & Remon. tag 33" Box Elder S38°E 120.40' Nail & Remon. tag 14" Maple S88°E 69.16' Nail & Remon. tag 18" Maple S88°E 69.16' Nail & Remon. tag 9" Locust N75°W 40.9' Nail & Remon. tag 12" Locust N75°W 40.91' Nail & Remon. tag 6" Oak N43°W 41.05' Nail & Remon. tag 10" Oak N43°W 41.20' C/L traveled way, Easterly 6' ± The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:				•			ent in Mon. Roy	CHAIF	MANY #	Tur.	44	wee
The position of this corner was previously approved by the Kent County Remonumentation Peer Group, monumented by Robert J. Jonker on 8-26-81 and was recorded per LCRC #1986. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: M-10 Found PK Nail at same location as Kent Co. Mon. per witnesses from above LCRC as set by Robert J. Jonker in place of the ½" Copper Conduit he found inside a Mon. Box. Said Copper Conduit checks LCRC's #928 & 1986. LCRC #1986 LCRC #1986 LCRC #7067 Nail & Remon. tag 26" Box Elder S38°E 120.5' Nail & Remon. tag 33" Box Elder S38°E 120.40' Nail & Remon. tag 14" Maple S88°E 69.16' Nail & Remon. tag 18" Maple S88°E 69.16' Nail & Remon. tag 9" Locust N75°W 40.9' Nail & Remon. tag 12" Locust N75°W 40.91' Nail & Remon. tag 6" Oak N43°W 41.05' Nail & Remon. tag 10" Oak N43°W 41.20' C/L traveled way, Easterly 6' ± The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:											,	
M-10 Found PK Nail at same location as Kent Co. Mon. per witnesses from above LCRC as set by Robert J. Jonker in place of the ½" Copper Conduit he found inside a Mon. Box. Said Copper Conduit checks LCRC's #928 & 1986. LCRC #1986 LCRC #7067 Nail & Remon. tag 26" Box Elder S38°E 120.5' Nail & Remon. tag 33" Box Elder S38°E 120.40' Nail & Remon. tag 14" Maple S88°E 69.16' Nail & Remon. tag 18" Maple S88°E 69.16' Nail & Remon. tag 9" Locust N75°W 40.9' Nail & Remon. tag 12" Locust N75°W 40.91' Nail & Remon. tag 6" Oak N43°W 41.05' Nail & Remon. tag 10" Oak N43°W 41.20' C/L traveled way, Easterly 6' ± The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:		The pos by Rob	sition of this cor ert J. Jonker on	ner was previously 8-26-81 and was re	approved	by the Kent Cour		ation Peer	Group, me	onumer	nted	
Nail & Remon. tag 14" Maple S88°E 69.16' Nail & Remon. tag 18" Maple S88°E 69.16' Nail & Remon. tag 9" Locust N75°W 40.9' Nail & Remon. tag 12" Locust N75°W 40.91' Nail & Remon. tag 6" Oak N43°W 41.05' Nail & Remon. tag 10" Oak N43°W 41.20' C/L traveled way, Easterly 6' ± The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:		M-10 Found place LCR0	d PK Nail at sam of the ½" Coppe C#1986	e location as Kent (er Conduit he found	Co. Mon. j l inside a l	per witnesses from Mon. Box. Said (LCRC #7067	n above LCRC a Copper Conduit o	s set by R checks LC	RC's #928	nker ir 3 & 198	1 86.	
Nail & Remon. tag 9" Locust N75°W 40.9' Nail & Remon. tag 12" Locust N75°W 40.91' Nail & Remon. tag 6" Oak N43°W 41.05' Nail & Remon. tag 10" Oak N43°W 41.20' C/L traveled way, Easterly 6' ± The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:												
C/L traveled way, Easterly 6' ± The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.		Nail	& Remon. tag 9	" Locust N75°	W 40.9'	Nail & Remon	. tag 12" Locust	N75°	W 40.91'			
evidence of the position of the original corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:					W 41.05'	Nail & Remon	. tag 10" Oak	N43°	'W 41.20'			
M-10 Standard Kent County Monument Nail & KC Remon. tag W. side P. Pole Nail & KC Remon. tag S. side P. Pole Nail & KC Remon. tag S. side B. Pole Nail & KC Remon. tag S. side B. Solow Nail & KC Remon. tag S. side B. Solow Nail & KC Remon. tag S. side B. Stump Nail & KC Remon. tag S. side B. Solow Nail & KC Remon. tag S. side B. Solow Nail & KC Remon. tag S. side B. Solow N25°W 134.71' Concrete Monument - West 60.00' Signal A. N.D. A. N.D.		evidenc	ce of the position	of the original com	ier.					ilable		
Nail & KC Remon. tag W. side P. Pole Nail & KC Remon. tag S. side P. Pole Nail & KC Remon. tag SW side 33" stump Nail & KC Remon. tag S. side 18" stump Nail & KC Remon. tag E. side P. Pole Nail & KC Remon. tag E. side P. Pole Nail & KC Remon. tag E. side P. Pole Noil & KC Remon. tag E. side P. Pole Noorete Monument - West 60.00' Surveyor 30077					es estadiis	med to perpetuate	locating the positi	ion of the	corner:		F MI	100 mg
Nail & KC Remon. tag S. side P. Pole Nail & KC Remon. tag SW side 33" stump Nail & KC Remon. tag S. side 18" stump Nail & KC Remon. tag S. side 18" stump Nail & KC Remon. tag E. side P. Pole Concrete Monument - West 60.00' KIRK BREITELS LAND SURVEYOR NO 30077	ſ				S20°W	150.96'			3	A E	A STATE OF THE PARTY OF THE PAR	'On the
Nail & KC Remon. tag SW side 33" stump Nail & KC Remon. tag S. side 18" stump Nail & KC Remon. tag E. side P. Pole Nail & KC Remon. tag E. side P. Pole N25°W 134.71' Concrete Monument - West 60.00' Size of the stump of the s		Nail &	KC Remon. tag	S. side P. Pole	S90°W				18		KIRK	Mary State of the
Nail & KC Remon. tag S. side 18" stump Nail & KC Remon. tag E. side P. Pole N25°W 134.71' Concrete Monument - West 60.00' Surveyor AND SURVEYOR NO 30077									新女	g Bi	REITELS	复金袋
Concrete Monument - West 60.00' NO 30077									新 本	SU	RVEYOR	¥ 28
With Bul 2/20/08					1945°W	134./1			るこ	870	NO	15%
lik Bul									A.	A CONTRACT	30077 عبر	A LITTER
With Bu & 9/20/08			, ,	0					The state of the s	AST OF	ANDS	4 . Fr.
	Cia	ad by	Kish	Bul			Date 9	/20/	, 98	A. A. A. A. A.	enerating of	S.

Date

30077

Surveyor's Michigan License No.