FRANKS &

JAN 2 4 1996

KENT COUNTY REMONUMENTATION

•	\$ 7	.(Ū	<u>0</u>	
	\$ 2		Û	0	Ì

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corpers in KENT COUNTY	Located In:	Corner Code #	\ G ??
(County) 1. Public Land Survey	T	H-12	STATE OF MICHIC COUNTY OF KEN RECOVED FOR RECOVED FOR RECOVED FOR RECOVED SON REGION OF DEEDS
	ST R ST R		8761 & COMPAN
3. Miscellaneous	S T R		· - · · ·
Property in Section	S R		Register of Deeds Stamp & File Number
4. Lot No, Reco			A B C D E F G H I J K L
5. Private Claims		d and de the transfer	2 6 - 5 - 4 - 3 - 2 1
Kirk Breitels	Oct	. 31 95	4 7 9 0 10 11 11 11 12
I, Indo hereby certify that under require in lines 1 and 2 above were in conformanual of survey instructions of Management or by a decree of a Co 5 above were in conformance with Decree of a Court of Law; establish as expressed below: NOTE: Not more than 4 corner on this certificate.	ormance with regulations and rules f the United State's Department Court of Law and/or that the corner in the rules of the Michigan Board thed, re-established, monumented,	therefore as required in the cu of the Interior, Bureau of points mentioned in lines 3, 4 of Professional Surveyors or re-monumented, recovered, f	urrent Land 7 4 and 8 19 20 21 22 23 24 by a
A. Description of original mo	nument and accessories and/o	or subsequent restoration	
1939 Kent Co. 10" Oak 1949 "Vinkmuld 1984 Survey A	e-Ne-Be" point of beg Wit. 1/2" Iron bar NE 18.85' 8" Oak NE der Plat" point of beg All Points 4" Conc. A N50°W 46.22' 14" Pir	13.65' 10" Pine s ginning Concrete Non.	
B. Description of corner evid	ence found and/or method ap	plied in restoring or reesta	ablishing corner:
Co. witnesses that lines and fits measu	remain. Said Concret	e Monument is 5.7 in surveys by All	Points survey and 1939 Kent '' S. & 13.4' E. of "X" 1/4 Points, Roosien, and Donker
	nt is accepted by me st available evidence		y accepted by professional f the corner.
H-12 Set Standard K Set Nail & KC Set Nail & KC Set Nail & KC Iron Pipe NE corner hou	for corner and accessories estained for County Monument if Remon. tag NE side 18 Remon. tag SE side 18 Remon. tag SW side 20 Ise foundation	n place of the Cor 5" Pine S40°E 1 2" Oak N60°E 4 4" Oak N40°W 4 S90°W 7	cating the position of the corner: ncrete Monument 11.96' 42.04' 45.96' BREITELS 10.25' LAND 30077
Signed by white	mit!	Date	12/4/95
Surveyor's Michigan License N	30077		PROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971