For corners in

MAR 0 3 1998

J	 •	-	

SECT	LION
~	( ) Y

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

KENT COUNTY REMONUMENTATION

Located in: Courtland Corner Code # Kent Township (County) **Public Land Survey** 9N R 10W Property Controlling R in Section Miscellaneous Property in Sec.

10328

Register of Deeds Stamp & File Number

	, N . 1	·
4.	Lot No	Recorded Plat
,	Private Claims	
v.	THEORE ORDING	

Randy Kolehouse in a field survey on July 14 do hereby certify that under requirements of P.A. 74 Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law: established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:

K-13 1831 G.L.O. Notes 1959 Witness Map 1972 L.C.R.C. #204 1981 L.C.R.C. #1721 1991 L.C.R.C. #6227

Mullett K.C. Surveyor **Exxel Engineering** 

Williams & Works

Chris Marschall

Monument Box 3/4" Iron in Mon. Box

Fnd. 3/4" Iron in Mon. Box / Set K.C. Monument P.A. 345 1990 KENT ÇOUNT K.C. Monument in Mon. Box

Note: This corner is not common with K-1, T8N, R10W.

PEER APPROVED 7/24/9

CHAIRMAN This corner was originally approved by the Kent County Remonumentation Peer Group and monumented by on 1/13/81 and was recorded per L.C.R.C. #1721.

В. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

K-13 Found a Standard Kent County Monument on the C/L of 10 Mile Road (bit.) running East and West per L.C.R.C.'s #1721 and #6227 as set by Williams & Works in place of a 3/4" iron they found in a monument box which checked L.C.R.C. #204 and the K.C. Surveyor's records.

L.C.R.C. #1721

LCRC.#6227

K.C. Remon. Tag & Nail in NE Side 18" Walnut N 60°W 71.26'

K.C. Remon, Tag & Nail in N Side MBT Service Pole N 75°E 157.43'

K.C. Remon. Tag & Nail in NE Side 28" Oak S 50°E 114.53'

K.C. Remon, Tag & Nail in N Side P. Pole S 70°W 101.62'

NW Cor. Hse. Fnd. S 20°W 117,99'

NE Cor. Hse, Fnd, S 10°E 117.16'

Nail & Tag N sd. 18" Walnut N 72 W 71.19' Nail & Tag NW sd. U.P. S 65 W 101.61'

Mon. K-1 T8N 10W N 90 E 92.28' NW cor. Hse, fnd. S 10 W 117.91

Date

SW cor. of 1.5' x 22' stone wall S 35 E top 122.70' Nail & Tag NE sd. 30" Oak S 55 E 116.34'

The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original corner.

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K-13 Standard Kent County Monument

Surveyor's Michigan License No.

SW cor. of 1.5' x 22' stone wall S 35° E top 122.70' Nail & K.C. remon. tag on N side 18" Walnut N 72° W 71.19' NW cor. hse. #8800 fndn, S 10° E 117.91' NE cor. hse. #8800 fndn. S 20° W 117.99'

Nail & K.C. remon. tag on NW side Util. pole S 65° W 101.61'

25854

K.C. Mon., K-1, T8N, R10W, East 92.28'

TH TECH

RANDY J. KOLEHOUSE LAND No. 25854

CASCO LAND SUR