LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For a	arna	ro	in

SECTION

	•	1959 007		i i
꼰	\		F CENTED	n F
평. 유.		បា	FOR RE	き
FDEEDS			RE	這
os		6; 0	ECORD	7
		õ		

Fo	r corners in	KENI COUNTY	REMONUMENTATION	이 이 이유를	
	Kent (County)	Located in: Courtland Co Township	rner Code #	RECEIPED AND STREET	
1.	Public Land Survey	T <u>9N</u> R <u>10W</u> T R T R R	M-5	08	
2.	Property Controlling in Section	S T R S T R	1	11382 Register of Deeds Stamp & File Number	
3.	Miscellaneous Property in Sec.	S T R S T R	Register of Deeds		
4. 5.		, Recorded Plat	A B C D	E F G H I J K L	

in a field survey on February 1 do hereby certify that under requirements of P.A. 74 Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:

Cathcart Set Post M-5 1837 G.L.O. Notes MSHD Monument Box 1963 Notes Fnd. Iron in Mon. Box / Set K.C. Mon. in Mon. Box 1985 L.C.R.C. #4306 R. Kolehouse K.C. Monument in Mon. Box 1991 L.C.R.C. #6218 C. Marschall

Note: This corner is common with A-5, T9N, R9W.

This corner was originally approved by the Kent County Remonumentation Peer Group and monumented by Randy Kolehouse on 8/19/85 and was recorded per L.C.R.C. #4306.

Description of corner evidence found and/or method applied in restoring or reestablishing corner: B.

Found a Standard Kent County Monument in a monument box at the C/L intersection of 14 Mile Road (bit.) running East and West and Ramsdell Drive (bit.) running South and (gravel) running North per L.C.R.C.'s #4306 and #6218 as set by Randy Kolehouse in place of an iron he found in a monument box which checked the 1963 MSHD records.

L.C.R.C. #4306

L.C.R,C. #6218

P.K. Nail in curb joint N 45° W 41.71' P.K. Nail in curb joint S 45° W 44.12'

P.K. Nail in curb joint S 40° E 43.60'

PK Nail in curb joint S 33 W 43.70' (m. 43.64') Nail & Tag W sd. 18" Oak S 9 E 255.43'

NW Corner Bldg. (Proper) Brick 2' above grd. S 59 E 173.20' (m. 173.23')

The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original corner.

Description of monument for corner and accessories established to perpetuate locating the position of the corner: C.

M-5 Standard Kent County Monument in a Monument Box

> Naîl & K.C. remon, tag on W side P. pole N 14° W 120.89' P.K. nail in curb joint N 45° W 41.67'

P.K. nail in curb joint S 45° E 44.13'

Nail & K.C. remon. tag on W side 22" Oak S 09° E 255.43'

NW cor. bldg. (proper) brick 2' abv. Gnd. S 59° E 173.23'

Fence cor./angle iron N 74° E 218.55'

Fence cor./angle iron N 10° E 180.21'

Signed by

On C/L of bit, road running E-W

On C/L of bit, road running S and gravel road running N

P.A. 345 1990 KENT COUNT

CHAIRMAN

PEER APPROV

RANDY J. KOLEHOUSE LAND

<u> 25854</u> Surveyor's Michigan License No.