_	in.
(N)	ور ا
1	3
	J

KENT COUNTY

MAR 0 8 1999

IMMERIATION

## KENT COUNTY REMONUMENTATION

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Corner Code #

or corners in	SECTION
or corners in	

 $\mathbb{N}\mathbb{C}$ Located in:

(County) 1. Public Land Survey common with A-3


2. Property Controlling in Section 3. Miscellaneous Property in Sec.

10497 Register of Deeds Stamp & File Number

\_, Recorded Plat 5. Private Claims

Kirk Breitels Jan. 5 in a field survey on do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.



P.A. 345 1990 KENT COUNT

KIRK

BREITELS

LAND

SURVEYOR

NO

3007

4AND

.

PEER APPROJUED 2/19

A. Description of original monument and accessories and/or subsequent restoration:

M-3 1837 GLO. Brookfield Set Post 1934 Kent Co. Wits I" Iron 1" Round Iron 1979 LCRC #1313 Nederveld

1983 LCRC #3385 Stadt Set Kent County Monument 1995 LCRC #8330 **Breitels** Kent County Monument

The position of this corner was previously approved by the Kent County Remonumentation Peer Group, monumented by Russell E. Stadt on 5-5-83 and was recorded per LCRC#3385.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

M-3 Found Kent County Monument (Harrison) per witnesses from above LCRC as set by Russell E. Stadt in place of a 1" Iron over a 1" Iron he found over a Stone. Both Irons and Stone check with Kent Co. Wits. and LCRC #1313.

LCRC #3385 LCRC #8330 Nail & Remon. tag 12" Oak S25°E 73.78 Nail & Remon. tag Tri. 6"-15" Oak S25°E Nail & Remon. tag 12" Oak S40°E 41.68 Nail & Remon. tag Tri. 24" Oak S25°W 126.32' Nail & Remon. tag 16" Tw. Oak S25°W 126.43' NE corner house foundation (#10) S45°W 82.83 NE corner house foundation S45°W 82.83' S. edge 4" steel fence post N00°E 32.24 S. edge 4" steel fence post 33.20 North Nail & Remon, tag 10" Oak S70°E

C/L road W. is 3' N. and C/L road S. is 8' W.

The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M-3 Standard Kent County Monument

Nail & KC Remon. tag W. side Tri. 6"-15" Oak S25°E 73.75 Nail & KC Remon, tag E. side Tri. 24" Oak S25°W 126.37 NE corner house foundation (#10) S45°W 82.83 S. edge 4" dia. steel fence post (2nd post N.) N00°E 48.06 Nail & KC Remon, tag N, side 12" Oak S70°E 24.27 C/L blktp. road (ext.) West is 3' North C/L blktp. road (ext.) South is 8' West

On fence line North

Signed by Surveyor's Michigan License No.

30077

4