

MAR 0 8 1999

KENT COUNTY REMONUMENTATION

Con.	1-	CI	"10	``}	V

LAND CORNER RECORDATION CERTIFICATE

SECTION	LAND CORNER RECORDATION	CERTIFICATE SO TO SO
For corners in	Filing Requirement of Act 74, Mi	(ii. F.A. 1970 \ ○○
KENT COUNTY		ATE COUNT ON I
(County)	ed In: Corner Code #	OF OF STATE
1. Public Land Survey	T <u>9N</u> R <u>11W</u> B-2 T R T R T R	DEEDS WE COND
2. Property Controlling S in Section S 3. Miscellaneous S	TR	
Property in Sec. S	TR	10008 Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat		_
5. Private Claims		A B C D E F G H I J K
Widen to 1		
I, Kirk Breitels, in a fiek	d survey on $\frac{\text{Sept. }30}{\text{970}}$, 19 $\frac{98}{\text{98}}$ do hereby states of the corner points mentioned in lines 1 and 2 all	te that under 4 7 8 9 10 11 1
conformance with regulations and rules theref	fore as required in the current manual of current instru	pove were in
undume corner points mentioned in lines 3, 4	eau of Land Management or by a decree of a Court of and 5 above were in conformance with the rules of t	the attention
recovered, found as expressed below:	of a Court of Law; established, re-established, m	nonumented, 7 8 19 20 21 22 23 2
NOTE: Not more than 2 corners, all in the	he same town and range, may be recorded	9
on this certificate.	and tange, may be recolded	10 30 29 28 27 26 2
		11
		12 31 32 33 34 35 3
A. Description of original monument an	nd accessories and/or subsequent restoration:	13
B-2 1837 GLO	Not Set	
1949 Williams & Works	Stone	
Steel Post SW 35.7 Kent Co. Wits	-5 00 W 15 1.0 I.1 Old E.3.	E 128.5' NE cor. school SW 145.2'
1953-72 Williams & Works	Stone Iron	
1972 LCRC #357 Spi	cer 1" Iron	
CP Pole S27°W 66.3 1980 LCRC #1398 Cha	3' 14" Oak \$70°E 87.8' 12" Oak N40°E sambers 1 ½" Iron Pine	86.57'
P. Pole \$20°W 66 30	ambers 1 ½" Iron Pipe 0' 8" Pine S30°E 44.08' 12" Oak S75°E 8' id and/or method applied in restoring or reesta	7.43' 14" Oak N65°E 86.23'
B-2 Found 1 ½" Iron Pipe per the fo	ollowing remaining witnesses: V 66.30' C/L 14" Pine S30°E 44'+	Middling Corner.
C/L 16" Oak S75°E 8	7.5'± Nail in 20" Oak N65°E 86.10'	
Said 1 ½" Iron Pipe is 16.0' N. Works, Bueche, Byl, Roosien a	and 59.3' E. from Intersection of 1/4 lines a and Ochs.	and has been used in surveys by Williams &
The 1 ½" Iron Pipe is accepted of the position of the corner.	by me and is generally accepted by professi	ional surveyors as the best available evidence
C. Description of monument for corner a	and accessories established to perpetuate loca	ating the position of the corner
B-2 Set Standard Kent County Mont	ument in place of the 1 ½" Iron Pipe.	
Nail & KC Remon. tag SW si Nail & KC Remon. tag W. sid	dc P. Pole N40°W 29,60'	
Nail & KC Remon. tag SW si-	de 14" Pine S30°E 44 02'	AP TO RIDE TO . TO
Nail & KC Remon. tag S. side	e 16" Oak S75°E 87.47'	LAND *
Nail & KC Remon. tag S. side C/L E-W pavement is South 3	20" Oak N65°E_86.10' '± P.A. 345 1990 KEN'	BREITELS LAND SURVEYOR NO 30077
	PEER APPROVED	10/27/98
./ , 0	CHAIRMAN	
Signed by Luk Pu	1	AND SOME
2	20077	Date
Surveyor's Michigan License No3	30077	