	_li	£
	UU	
Z 1	<u>.UU</u>	
	000	
~ ()	Π	1
~ 7		,

KENT COUNTY

10AR 0 8 1999

KENT COUNTY REMONUMENTATION

٦.	
	SECTION
For corners in	

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Corner Code #

REG. OF	98 MAY 21	STATE OF I
See		983 865
509	လ	The second of
سن	ယ	

1. Public Land Survey

2. Property Controlling in Section

3. Miscellaneous Property in Sec.

10606


Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat 5. Private Claims

Located In:

Kirk Breitels Feb. 26, 19 98 do hereby state that under in a field survey on requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 comers, all in the same town and range, may be recorded on this certificate.



A. Description of original monument and accessories and/or subsequent restoration:

E-6 1837 GLO 1984

Whitcomb

Set Post

LCRC #3802 Bueche

1990: LCRC #5646

Marschall

Set Kent County Monument Kent County Monument

P.A. 345 1990 KENT COUNTY PEER APPROYED 4/30/9 CHAIRMAN / family 9

OF MICHIO

KIRK

BREITELS

LAND SURVEYOR

30077

The position of this corner was previously approved by the Kent County Remonumentation Peer Group, monumented by John C. Bucche on 4-21-84 and was recorded per LCRC #3802.

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

South

E-6 Found Kent County Monument (Harrison) per witnesses from above LCRC as set by John C. Bueche. 0.40'

LCRC #3802 Face of 12" dia. fence post LCRC #5646

Nail & Remon. tag 24" Oak N90°E 11.13'

Nail & Remon. tag 24" Oak N90°E 11.15' Nail & Remon. tag 14" Beech N50°E 32.11'

Nail & Remon. tag 14" Beech N50°E 32.12'

Nail & Remon. tag 10" Maple N30°W 25.74'

Nail & Remon. tag 10" Maple N30°W 25.71' Nail & Remon. tag 24" Oak N70°W 32.10'

Nail & Remon. tag 24" Oak N70°W 32.14'

Nail & Remon. tag 28" Oak S15°E 28.68' Nail & Remon. tag28" Oak S15°E 28.61'

The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-6 Standard Kent County Monument

Near A-frame "cottage"

Surveyor's Michigan License No.

N90°E 11.16' N50°E 32.11' Nail & KC Remon. tag N. side 24" Oak stump Nail & KC Remon. tag SE side 18" Beech Nail & KC Remon. tag SW side 14" Maple N30°W 25.74' Nail & KC Remon. tag S. side 26" Oak N70°W 32.10' Nail & KC Remon. tag E. side 30" Oak S15°E 28.61' Face of 12" dia. fence post is South 0.4"

Date 4/30/98

Signed by 30077