SURVEY & REMONUMENTATION



MAR 08 1999

KENT COUNTY REMONUMENTATION

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Common C	For comers in	ON Filing i	Requirement of Act 74, Micf	1. P.A. 1970 	۱ ۵	3 20 00
1. Public Land Survey T. R. T	KENT COUNTY	Located In:	Corner Code #		•	
2. Property Controlling S T R S S T R S S T R S S S S	-				, , , , , , , , , , , , , , , , , , ,	
3. Miscellaneous S T R 10916 Register of Deeds Stamp & File Number 15. Private Claims Kirk Breitels In a field survey on Sept. 8 19 98 do hereby state that under requirements of PA. 74, Michigan PA. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with residence on a requirement of the Interior. Bureau of Land Management of by a decree of a Court of Law, established, or established, inconserted, found as expressed below. NOTE: Not more than 2 comman, all in the same town and range, may be recorded on this certificate. P-4 1837 GLO Not Set Old stake in conter of fences - 2634 W. of E 1/4 corn. Not Set Old stake in conter of fences - 2634 W. of E 1/4 corn. P-4 1837 GLO Not Set Old stake in conter of fences - 2634 W. of E 1/4 corn. P-4 1837 GLO Not Set Old stake in conter of fences - 2634 W. of E 1/4 corn. P-4 1837 GLO Not Set Old stake in conter of fences - 2634 W. of E 1/4 corn. P-4 1837 GLO Not Set Old stake in conter of fences - 2634 W. of E 1/4 corn. P-4 1837 GLO Not Set Old stake in conter of fences - 2634 W. of E 1/4 corn. P-4 1837 GLO Not Set Old stake in conter of fences - 2634 W. of E 1/4 corn. P-4 1838 Williams & Works Not Information B. Description of comer evidence found and/or method applied in restoring or reestablishing comer. P-4 Established Intersection of 1/4 lines and found nothing at corner. Location is on fence line to North ± and fence to West is 8" North ±. Measured 2633.13" W. of E 1/4 corner (2633" Williams & Works 1895). Location agrees with measurements of Hackbardt, Gluza, Roesien and Fricke. The Intersection of 1/4 lines is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the corner. C. Description of monument for corner and accessories established to perpetuate localing the position of the corner. P-4 Sat Standard Kent County Monument at the Intersection of 1/4 lines. Noil & KC Remon. lag S. side 71.3" Oak Nat'N 29.7 P-4 A 345 1890 KENT COUNTY P-4 A 345 189	1. Public Land Survey	TR TR	<i>W</i> F-4		H W	CONTRACT CONTRACT
3. Miscollaneous Property in Sec. S T R 10916 Register of Deads Stamp & File Number 4. Lot No. Recorded Plat 5. Private Claims Kirk Breizlas in a field survey on Sept. 8 1998 do hereby state that under requirements of PA. 74. Michigan PA. of 1970, the corner points meritioned in lines 1 and 2 above were in conformance with regulations and nate before as required in the current menal of any plasticular of the world for the world for the world of the corner points meritioned in lines 3. 4 and 5 above were in conformance with equilations and nate before as required in the current menal of a large plasticular of the world for th	2. Property Controlling	S TR	*****		ي ک	3 8 7
## Register of Deeds Stamp & File Number ## A. Lot No					1091	ß
Kirk Brotitels In a field survey on Sept. 8 19 98 de hereby state that under requirements of PA. 74 Michigan PA. of 1970, the corner points meetined in his and a state was in the signal to the distribution of the field of the	Property in Sec.	S TR		Regi		_
Kirk Brotitels In a field survey on Sept. 8 19 98 de hereby state that under requirements of PA. 74 Michigan PA. of 1970, the corner points meetined in his and a state was in the signal to the distribution of the field of the	4 Lot No Pacor	rded Dist				
Kirk Breitels , in a field survey on Scpt. 8 19 98 do hereby state that under requisements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in the United States Departed one and full the three corner points mentioned in lines 3.4 and 5 above were in the Corner points mentioned in lines 3.4 and 5 above were in the corner points mentioned in lines 3.4 and 5 above were in confirmation of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, received, fund as expressed better. NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. A Description of original monument and accessories and/or subsequent restoration: F-4 1837 GLO Not Set Old stake in center of fences - 2654 W. of E 1/4 cor. Not Information Not Set Old stake in center of fences - 2654 W. of E 1/4 cor. No Information B. Description of comer evidence found and/or method applied in restoring or reestablishing corner: F-4 Established Intersection of 1/4 lines and found nothing at corner. Location is on fence line to North ± and fence to West is 8' North ± Measured 2653.13' W. of E 1/4 corner (2653' Williams & Works 1895). Location agrees with measurements of Hackbardt, Glaza, Roosien and Fricke. The Intersection of 1/4 lines is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: F-4 Set Standard Kent County Mönument at the Intersection of 1/4 lines. Nail & KC Remon. ug SE side 20' Oak SSSW 7.59' Nail & KC Remon. ug SE side 20' Oak SSSW 7.59' Nail & KC Remon. ug S. side 17i. 3'' Oak Nail & KC Remon. ug S. side 17i. 3'' Oak P-A 3.45 1990 KENT COLNIY P-EER APPROYED 9 1/1/12/198 Signed by Market Standard Market Standard Standa	5. Private Claims	ded i iat		A B	C D E F G	HIJKL
Likis Bretiels in a field survey on Sopi. 8 19/8 do hereby state that under requirements of PA. 74 Michigan PA. of 1970, the corresponds mentioned in the same and survey was above were to conformance with regulations and rules therefore as required in the current manual of survey and survey was above to the fulled States Department of the interfor. Bursau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented on this cartification. NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this cartification. NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this cartification. F-4 (837) GLO Not Set Old stake in center of fences - 2654' W. of E I/4 cor. F-4 (837) GLO Not Set Old stake in center of fences - 2654' W. of E I/4 cor. No information B. Description of comer evidence found and/or method applied in restoring or reestablishing corner: F-4 (838) Williams & Works Kent Co. Wils Not 194 (194) W. of E I/4 corner (2653' Williams & Works 1895). Location agrees with measurements of Hackbardt, Glaza, Roosien and Pricke. The Intersection of I/4 lines is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the corner: F-4 Set Standard Kent County Mönument at the Intersection of I/4 lines. Nail & KC Remon. tag St side 20° Cak S559W 7,59° Nail & KC Remon. tag St side 20° Cak S559W 7,59° Nail & KC Remon. tag St side 20° Cak S559W 7,59° Nail & KC Remon. tag S. side Tri. 3" Oak Nail & KC Remon. tag S. side Tri. 3" Oak Nail & KC Remon. tag S. side Tri. 3" Oak Nail & KC Remon. tag S. side Tri. 3" Oak CHAIRMAN Management of the torrer. Date of the position of the corner. PAS A Standard Rem County Monument at the Intersection of I/4 lines. Signed by Management A Standa				1 1	5 4	$-\frac{1}{3}$ $-\frac{1}{2}$ $-\frac{1}{1}$
Requirements of PA. 74, Michigan PA. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rise threfore are required in the current manual of survey instructions of the function process of the function of the function process of the function of the funct	Kirk Breitels	. in a field survey on S	ept. 8 19 98 do hereby state			10 11 12
United States Department of the Interior, Burrau of Land Management or by a occree of a Court of Law and for the Interior of I	requirements of P.A. 74, Michiga	IN P.A. of 1970, the corner b	points mentioned in lines 1 and 2 abo	ve were in !!		
Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed between. NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. A Description of original monument and accessories and/or subsequent restoration: F-4 1837 GLO Not Set 1895 Williams & Works Old stake in center of fences - 2654' W. of E 1/4 cor. No Information B. Description of comer evidence found and/or method applied in restoring or reestablishing corner: F-4 Established Intersection of 1/4 lines and found nothing at corner. Location is on fence line to North ± and fence to West is 8' North ±. Measured 2653.13' W. of E 1/4 corner (2653' Williams & Works 1895). Location agrees with measurements of Hackbardt, Glaza, Roosien and Fricke. The Intersection of 1/4 lines is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner. F-4 Set Standard Kent County Mônument at the Intersection of 1/4 lines. Nail & KC Remon. tag St side 20' Cola S\$55'W 7.59' Nail & KC Remon. tag St side 20' Colar S\$69'E 50.51' N45'W 29.27' P-A. 345 1890 KENT COLNIY PEER APPROVED 9 1/24 198. CHAIRMAN PEER APPROVED 9 1/24 198.	United States Department of the I	Interior, Bureau of Land Mana	agement or by a decree of a Court of L	aw and /or $\epsilon = 10$	17 16	
NOTE: Not more than 2 comers, all in the same town and range, may be recorded on this certificate. A Description of original monument and accessories and/or subsequent restoration: F-4 1837 GLO Not Set 1895 Williams & Works Old stake in center of fences - 2654' W. of E 1/4 cor. No Information B. Description of comer evidence found and/or method applied in restoring or reestablishing corner: F-4 Established Intersection of 1/4 lines and found nothing at corner. Location is on fence line to North ± and fence to West is 8' North ±. Measured 2653.13' W. of E 1/4 corner (2653' Williams & Works 1895). Location agrees with measurements of Hackbardt, Glaza, Roosien and Fricke. The Intersection of 1/4 lines is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the corner. C. Description of monument of the corner and accessories established to perpetuate locating the position of the corner. F-4 Set Standard Kent County Monument at the Intersection of 1/4 lines. Nail & KC Remon. tag W. side 30' Basswood Noo'e 8.82' Nail & KC Remon. tag W. side 30' Basswood S80'E 50.51' Nail & KC Remon. tag S. side 8" Basswood S80'E 50.51' Nail & KC Remon. tag S. side 8" Basswood S80'E 50.51' NAS'W 29.27' P-A. 345 1990 KENT COUNTY PEER APPROVED/9/124/196. CHAIRMAN PARAMANA AND PARAMANANA AND PARAMANANANANANANANANANANANANANANANANANAN	Board of Land Surveyors or by	a Decree of a Court of La	aw; established, re-established, mo	numented,		
A Description of original monument and accessories and/or subsequent restoration: F-4 1837 GLO 1895 Williams & Works Old stake in center of fences - 2654' W. of E 1/4 cor. No Information B. Description of comer evidence found and/or method applied in restoring or reestablishing corner: F-4 Established Intersection of 1/4 lines and found nothing at corner. Location is on fence line to North ± and fence to West is 8' North ± Measured 2653.13' W. of E 1/4 corner (2653' Williams & Works 1895). Location agrees with measurements of Hackbardt, Glaza, Roosien and Fricke. The Intersection of 1/4 lines is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: F-4 Set Standard Kent County Mönument at the Intersection of 1/4 lines. Nail & KC Remon. tag SE side 20' Oak S55°W 7.59' Nail & KC Remon. tag Ws side 10' Cherry N60°E 41.33' Nail & KC Remon. tag S. side 8" Basswood S80°E 50.51' Nail & KC Remon. tag S. side 7' Basswood S80°E 50.51' Nail & KC Remon. tag S. side 7' Basswood S80°E 50.51' NA5°W 29.27' PA. 345 1990 KENT COUNTY PEER APPROVED/ 9 124 196, CHAIRMAN PARSON Date 11/12/198 Signed by MILLER AND SALE A					20 21	23 24-
A Description of original monument and accessories and/or subsequent restoration: F-4 1837 GLO Not Set 1895 Williams & Works Old stake in center of fences - 2654' W. of E 1/4 cor. No Information B. Description of comer evidence found and/or method applied in restoring or reestablishing corner: F-4 Established Intersection of 1/4 lines and found nothing at corner. Location is on fence line to North ± and fence to West is 8' North ±. Measured 2653.13' W. of E 1/4 corner (2653' Williams & Works 1895). Location agrees with measurements of Hackbardt, Glaza, Roosien and Fricke. The Intersection of 1/4 lines is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner. F-4 Set Standard Kent County Mönument at the Intersection of 1/4 lines. Nail & KC Remon. tag W. side 30' Basswood Nail & KC Remon. tag W. side 30' Basswood Nail & KC Remon. tag S. side 8' Basswood Nail & KC Remon. tag S. side 8' Basswood Nay Sey 25.05.1' Nail & KC Remon. tag S. side 8' Basswood Nay Sey 25.7 P-A. 345 1990 KENT COUNTY PEER APPROVED 9 1/24 1 95 CHAIRMAN CHAIRMAN Date Miliams & More Sey 1/4 cor. Not Sey 25.7 PA. 345 1990 KENT COUNTY PEER APPROVED 9 1/24 1 95 CHAIRMAN CHAIRMAN Date Miliams & More Sey 1/4 cor. Not The County More Sey 1/4 cor. Not Sey 25.7 PA. 345 1990 KENT COUNTY PEER APPROVED 9 1/24 1 95 CHAIRMAN Date Miliams & More Sey 1/4 cor. Not Sey 1/4 cor.		ners, all in the same town ai	nd range, may be recorded		29 28	-272625-
A Description of original monument and accessories and/or subsequent restoration: F-4 1837 GLO 1895 Williams & Works Old stake in center of fences - 2654' W. of E 1/4 cor. No Information B. Description of comer evidence found and/or method applied in restoring or reestablishing corner: F-4 Established Intersection of 1/4 lines and found nothing at corner. Location is on fence line to North ± and fence to West is 8' North ±. Measured 2653.13' W. of E 1/4 corner (2653' Williams & Works 1895). Location agrees with measurements of Hackbardt, Glaza, Roosien and Fricke. The Intersection of 1/4 lines is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: F-4 Set Standard Kent County Mönument at the Intersection of 1/4 lines. Nail & KC Remon. tag W. side 30' Basswood N00°E 8.82' Nail & KC Remon. tag W. side 30' Basswood N00°E 41.33' Nail & KC Remon. tag W. side 30' Basswood N00°E 41.33' Nail & KC Remon. tag S. side 8' Basswood S00°E 50.51' Nail & KC Remon. tag S. side 8' Basswood S00°E 50.51' Nail & KC Remon. tag S. side 8' Basswood S00°E 50.51' P-A. 345 1990 KENT COUNTY PEER APPROVED 9 124 199 CHAIRMAN PEER APPROVED 9 124 199 CHAIRMAN PEER APPROVED 9 124 199 CHAIRMAN PEER APPROVED 9 11/12/98				11		
A Description of original monument and accessories and/or subsequent restoration: F-4 1837 GLO Not Set Old stake in center of fences - 2654' W. of E 1/4 cor. No Information B. Description of comer evidence found and/or method applied in restoring or reestablishing corner: F-4 Established Intersection of 1/4 lines and found nothing at corner. Location is on fence line to North ± and fence to West is 8' North ±. Measured 2653.13' W. of E 1/4 corner (2653' Williams & Works 1895). Location agrees with measurements of Hackbardt, Glaza, Roosien and Fricke. The Intersection of 1/4 lines is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: F-4 Set Standard Kent County Monument at the Intersection of 1/4 lines. Nail & KC Remon. tag SE side 20' Oak S55°W 7.59' Nail & KC Remon. tag W. side 30' Basswood N00°E 8.82' Nail & KC Remon. tag S. side 8' Basswood N00°E 41.33' Nail & KC Remon. tag S. side 8' Basswood N00°E 41.33' Nail & KC Remon. tag S. side 8' Basswood N00°E 41.33' Nail & KC Remon. tag S. side 8' Basswood N00°E 41.33' PEER APPROVED 9 1/4 1/8. CHAIRMAN PEER APPROVED 9 1/4 1/8.				12-31-	32-33	34-35-36
B. Description of comer evidence found and/or method applied in restoring or reestablishing corner: F-4 Established Intersection of 1/4 lines and found nothing at corner. Location is on fence line to North ± and fence to West is 8' North ±. Measured 2653.13' W. of E 1/4 corner (2653' Williams & Works 1895). Location agrees with measurements of Hackbardt, Glaza, Roosien and Fricke. The Intersection of 1/4 lines is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: F-4 Set Standard Kent County Monument at the Intersection of 1/4 lines. Nail & KC Remon. tag St side 20' Oak St55' 7.59' Nail & KC Remon. tag St side 20' Oak St55' 7.59' Nail & KC Remon. tag St side 20' Oak St55' 7.59' Nail & KC Remon. tag St side 8' Basswood N00'E 8.82' Nail & KC Remon. tag St side 8' Basswood S80'E 50.51' Nail & KC Remon. tag St side 8' Basswood S80'E 50.51' Nail & KC Remon. tag St side 8' Basswood S80'E 50.51' Nail & KC Remon. tag St side 8' Basswood S80'E 50.51' Nail & KC Remon. tag St side 8' Basswood S80'E 50.51' Nail & KC Remon. tag St side 8' Basswood S80'E 50.51' Nail & KC Remon. tag St side 7' Salvandur Surveyors Surveyor	A. Description of original mo	nument and accessories:	and/or subsequent restoration:	131		
Established Intersection of 1/4 lines and found nothing at corner. Location is on fence line to North ± and fence to West is 8' North ±. Measured 2653.13' W. of E 1/4 corner (2653' Williams & Works 1895). Location agrees with measurements of Hackbardt, Glaza, Roosien and Fricke. The Intersection of 1/4 lines is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: F-4 Set Standard Kent County Mönument at the Intersection of 1/4 lines. Nail & KC Remon. tag SE side 20" Oak S55°W 7.59' Nail & KC Remon. tag W. side 30" Basswood N00°E 8.82' Nail & KC Remon. tag N. side 8" Basswood N00°E 41.33' Nail & KC Remon. tag S. side 8" Basswood S80°E 50.51' Nail & KC Remon. tag S. side 8" Basswood S80°E 50.51' P.A. 345 1990 KENT COLNIY PEER APPROVED/9/124/96 CHAIRMAN Date 1//12/98 Signed by Date 1//12/98	1895 Williams &	Works	Old stake in center of fences -	2654' W. of E 1/4 c	or.	
Measured 2653.13' W. of E 1/4 corner (2653' Williams & Works 1895). Location agrees with measurements of Hackbardt, Glaza, Roosien and Fricke. The Intersection of 1/4 lines is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: F-4 Set Standard Kent County Mönument at the Intersection of 1/4 lines. Nail & KC Remon. tag SE side 20" Oak S55°W 7.59' Nail & KC Remon. tag W. side 30" Basswood N00°E 8.82' Nail & KC Remon. tag W. side 30" Basswood N00°E 41.33' Nail & KC Remon. tag S. side 8" Basswood S80°E 50.51' Nail & KC Remon. tag S. side Tri. 3" Oak N45°W 29.27' P.A. 345 1990 KENT COUNTY PEER APPROVED 9 124 196 CHAIRMAN PEER APPROVED 9 124 196 CHAI	B. Description of corner evid	dence found and/or metho	od applied in restoring or reestab	lishing corner:		
Location agrees with measurements of Hackbardt, Glaza, Roosien and Fricke. The Intersection of 1/4 lines is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: F-4 Set Standard Kent County Mönument at the Intersection of 1/4 lines. Nail & KC Remon. tag SE side 20" Oak S55°W 7.59' Nail & KC Remon. tag W. side 30" Basswood N00°E 8.82' Nail & KC Remon. tag W. side 30" Basswood N00°E 41.33' Nail & KC Remon. tag S. side 8" Basswood S80°E 50.51' Nail & KC Remon. tag S. side 8" Basswood S80°E 50.51' Nail & KC Remon. tag S. side Tri. 3" Oak N45°W 29.27' P-A. 345 1990 KENT COUNTY PEER APPROVED 9 124 196 CHAIRMAN Date 11/12/98 Signed by Date 11/12/98	west is a north ±.			is on fence line to N	forth ± and fence	to
The Intersection of 1/4 lines is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: F-4 Set Standard Kent County Monument at the Intersection of 1/4 lines. Nail & KC Remon. tag SE side 20" Oak S55°W 7.59' Nail & KC Remon. tag W. side 30" Basswood N00°E 8.82' Nail & KC Remon. tag NW side 10" Cherry N60°E 41.33' Nail & KC Remon. tag S. side 8" Basswood S80°E 50.51' Nail & KC Remon. tag S. side Tri. 3" Oak N45°W 29.27' P.A. 345 1990 KENT COUNTY PEER APPROVED 9 124 196 CHAIRMAN PARAMAN SURVEYOR NO 30077 PEER APPROVED 9 124 196 CHAIRMAN PARAMAN SURVEYOR NO 30077 Date 1/1/2/98						
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: F-4 Set Standard Kent County Monument at the Intersection of 1/4 lines. Nail & KC Remon. tag SE side 20" Oak S55°W 7.59' Nail & KC Remon. tag W. side 30" Basswood N00°E 8.82' Nail & KC Remon. tag NW side 10" Cherry N60°E 41.33' Nail & KC Remon. tag S. side 8" Basswood S80°E 50.51' Nail & KC Remon. tag S. side 8" Basswood S80°E 50.51' Nail & KC Remon. tag S. side Tri. 3" Oak N45°W 29.27' P.A. 345 1990 KENT COUNTY PEER APPROVED 9 124 198 CHAIRMAN PARAMAN AND SURVEYOR NO 30077 Date 1//12/98	Location agrees with	n measurements of Hackl	oardt, Glaza, Roosien and Frick	e. No.		
F-4 Set Standard Kent County Monument at the Intersection of 1/4 lines. Nail & KC Remon. tag SE side 20" Oak S55°W 7.59' Nail & KC Remon. tag W. side 30" Basswood N00°E 8.82' Nail & KC Remon. tag NW side 10" Cherry N60°E 41.33' Nail & KC Remon. tag S. side 8" Basswood S80°E 50.51' Nail & KC Remon. tag S. side Tri. 3" Oak N45°W 29.27' P.A. 345 1990 KENT COUNTY PEER APPROVED 9 124 98 CHAIRMAN PEER APPROVED 14 12/98 CHAIRMAN PEER APPROVED 14 12/98 Signed by Date 1//12/98	The Intersection of 1 evidence of the posit	/4 lines is accepted by material times is accepted by material times.	ne and is generally accepted by	professional survey	ors as the best ava	iilable
Signed by Date 11/12/98	F-4 Set Standard Kent Co Nail & KC Remon. Nail & KC Remon. Nail & KC Remon. Nail & KC Remon.	unty Monument at the Intag SE side 20" Oak tag W. side 30" Basswotag NW side 10" Cherry tag S. side 8" Basswood	S55°W 7.59° Odd N00°E 8.82° N60°E 41.33° 4 S80°E 50.51°	ing the position of th	OF	ITELS & *
Signed by Date 11/12/98	,			OLNIY		10 /5
Signed by Date 11/12/98			O(1)	124/98,	30	OII
20072		B. ()	CHAIRMAN / Jan	y Hube	U TOU	ND SU
20072	Signed by Luth	/ Man	n: •	ete ///2/	98	Adding
	- /	20077			***************************************	· · · · · · · · · · · · · · · · · · ·