	7		
F #17.7	1 mm 1 mm	. Th	MOTENTION

MAR 0 8 1999

## KENT COUNTY REMONUMENTATION

( ) E ( )	TION
Section 1	TON

 LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

1	ద్ద	m w
y\ 2	SHAR SE	STATE OF STATE
5 5	70	in Zir
	ည်	
7 1 7/		
5 VV		71.5 m
	Ç)	ON REPORT
y)	••	
	(4)	ę~;


For comers in

KENT COUNT	Located in:	Corner Code #
(County)		
1. Public Land Survey	T <u>9N_R</u>	11W I-10
	TR	
2. Property Controlling	S T R	
in Section	S T R	<del></del>
3. Miscellaneous	S TR	
Proporty in Coo	C T D	

10552
Register of Deeds Stamp & File Number

I, <u>Kirk Breitels</u>, in a field survey on <u>Jan. 9</u>, 19 <u>98</u> do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.



A. Description of original monument and accessories and/or subsequent restoration:

				•	
I-10	1837	GLO	Whitcomb	Set Post	P.A. 345 1990 KENT COUNTY
	1964	Kent Co. Wits		Mon Box	PEER APPROVED Z/19/95
	1975	LCRC #897	Bonnema	1/4" Iron in Mon. Box	Ollar Branch
	1975	LCRC #899	Spicer	3/8" Iron in Mon. Box	CHAIRSMAN / aug / fu
	1982	LCRC #2521	Starr	Set Kent County Monument in Mon. Box	
	1994	LCRC #7031	Byl	Kent County Monumentin Mon. Box	

The position of this corner was previously approved by the Kent County Remonumentation Peer Group, monumented by Thomas C. Starr on 1-5-82 and was recorded per LCRC #2521.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I-10 Found Kent County Monument (Harrison) per witnesses from above LCRC as set by Thomas C. Starr in place of the 3/8" Solid Iron he found inside a Mon. Box. Said Iron checks with Kent Co. Wits. and LCRC's #897 & #889. LCRC #2521

LCRC #7031

Ì	LCRC #2521		LCRC #7031		
	Nail & Remon. tag 8" Pine	N20°W 47.64'	Nail & Remon. tag 6" Maple	N05°W	90.38
	Nail & Remon. tag 2" Maple	N05°W 90.27'	Nail & Remon. tag 10" Oak	S70°W	45.45'
	Nail & Remon. tag 6" Oak	S70°W 45.60'	"+" mark of sta. 904+00 SB lane	N45°E	44.67'
ì,	Nail & Remon. tag top guard po	ost West 51.90'	W. edge of conc. SB lane (at rt. an	g.) East	27.45'
ż	West edge conc. SB lane	East 27.45'	-	- /	

The selected location is accepted by me and is generally accepted by professional surveyors as the best available

evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I-10	Standard	Kent	County	Monument	in Mon	Box
2 10	O WILLIAM G	170110	COULTRY	INVOIDULITORIC	MI INVII	· DUA

Nail & KC Remon. tag SE side 12" Oak S70°W 45.42'
"+" mark of sta. 904+00 S. Bd. Lane US-131 N45°E 44.67'
West edge conc. S. bd. Lane US-131 (at rt. angle) Easterly 27.45'
East edge conc. parking lot (at rt. angle) Westerly 53.07'



Signed by Luck Bru Surveyor's Michigan License No. 30077

Date 2/19/98