1√√ MAR 0 8 1999

KENT COUNTY REMONUMENTATION

SECTION	LAND CORNER Filing Requireme	RECORDATION CERTIFICATION OF Act 74, Mich. P.A. 19	STATE OF A RECEIVED FO REG. OF
For corners in			
KENT COUNTY Loc	ated in: Corner C	Code#	
(County)			REEDS AND COMMENTS
	T9N R11W	L-8	GV9 ⊙ ⊙⊴₹₹
1. Public Land Survey	TR		S 5 15
2. Property Controlling S_	_ TR		
in Section S_	<u>TR</u>		40000
3. Miscellaneous S_	<u>-</u>		Register of Deeds Stamp & File Number
Property in Sec. S_	'\ ~		Register of Boods Status
4. Lot No, Recorded P 5. Private Claims			7 B C D E F G H I J K L M 2 6 5 4 3 2 1 1 3 3 2 1 3 3 3 3 3 3 3 3 3 3 3 3
I, Kirk Breitels requirements of P.A. 74, Michigan P.A. conformance with regulations and rules tunited States Department of the Interior that the corner points mentioned in line Board of Land Surveyors or by a Derecovered, found as expressed below:	Bureau of Land Management or	by a decree of a Court of Law and /o	6 -18 -17 -13 -13 -13 -13 -13 -13 -13 -13 -13 -13
NOTE: Not more than 2 corners, a	I in the same fown and range.	may be recorded	9
NOTE: Not more than 2 contents, a on this certificate.	in the same our and tanger	•	10 30 29 28 27 26 29
Off this octained.			11 32 34 35 36
			12 31 32 33
			13
A. Description of original monum	ent and accessories and/or su	ubsequent restoration:	P.A. 345 1990 KENT COUNTY
L-8 1837 GLO	Not Set	ŧ	PERD ADDROVED #120/98
Williams & Wo		ormation	PEER APPROYED 8/20/98 CHAIRMAN Hamy Huther
1072 I CRC #598	Bonnema 3/4" Iro		CHAIRMAN / Farry / France
- cn C (11000	rth 19.76' 28" Oak ENE 7 Hackbardt 3/4" Iro 0°W 19.48' 28" Oak N45°		.60'
L-8 Found 3/4" Iron Pipe pe Nail in 12" Ch	r the following remaining warry N00°W 19.51' Nail in	150 Out 1170 25 7 200 1	
Byl, and Roosien.			sed in surveys by Hackbardt, Exxel,
The 3/4" Iron Pipe is a of the position of the c	ccepted by me and is genera orner.	Ily accepted by professional s	urveyors as the best available evidence
Nail & KC Remon. t Nail & KC Remon. t	nty Monument in place of the ag E. side 12" Cherry ag S. side 30" Oak ag W. side 10" Poplar	blished to perpetuate locating the 3/4" Iron Pipe N00°W 19.51' N70°E 71.30' S10°E 15.17' S70°W 24.67'	KIRK BREITELS LAND SURVEYOR NO 30077
Vale	Bul. 30077	Date	9/25/88
Signed bySurveyor's Michigan License N	30077		