SUTVEY & REVIOUS WENT ATTON OF



KENT COUNTY REMONUMENTATION

		CORNER RECOR			√ 公 两 ∽
For corners in	, FINIT	g Requirement of <i>I</i>	Act 74, Mich. P.A.	1970	
} :	•			껆	
KENT COUNTY	Located In:	Corner Code #		REG	
(County)				90	See in the second
4 Dublic Land Survey	Tou D	1377	-	R (元 三 三 三
1. Public Land Survey	T <u>9N_R</u>			rin Y	光 三
·	I R_	Common	with	5 V	~
	T <u>9N_R</u> T R	0WA-12			가 B 점 ~
2. Property Controlling	S T R				<u></u>
in Section	S TR				
3. Miscellaneous	S R_			1	0585
Property in Sec.	S TR				
			L	Register of Dee	ds Stamp & File Number
4 1 -441 - 5					. 1
4. Lot No, Record	ed Plat	****		ABCDE	FGHTJKIM
5. Private Claims				1 1 1 1 1	
				z - 6 - 5 -	-411
				3	
, Kirk Breitels	in a field survey on	Jan. 14 , 19 <u>98</u> c	do hereby state that und	er 4 - 7 - 8	-9-10-11-12-
requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in					
United States Department of the Interior Disease of the Interior Disease of Control of the Interior Disease of the Interior Di					
that the corner points mentioned in	i lines 3, 4 and 5 above	were in conformance with	the rules of the Michia	an ÎÎII	19 14 13 1
Board of Land Surveyors or by a recovered, found as expressed belo	a Decree of a Court o	f Law; established, re-e	stablished, monumente	a,	
roovered, round do expressed belo	****			8 19 20	-21 -22 -23 -24
NOTE: Not more than 2 comers, all in the same town and range, may be recorded				9	
on this certificate.				10 30 29	-28 -27 -26 -25 -
				11	
es.				12 31 32	33 34 35 36
N. Carlotte					
A. Description of original mon	ument and accessori	es and/or subsequent	restoration:	13	
			rostoratori.		
M-12 1837 GLO	Brookfield	Set Post		P.A. 345 1990 k	
Kent Co. Wi		Stone - Mon. Box		PEER APPROVE	D/2/19/98
1973 LCRC #480,		1/2" Iron in Mon. Bo		CHAIRMAN 2	famply her
1981 LCRC #1983		Set Kent County Mo		х	777
1994 LCRC #7069	9 Byl	Kent County Monun	nent in Mon. Box		•
The position of this c	orner was previousl	y annroyed by the Ke	nt County Damonus	mantation Base Crown w	o a manage to d
The position of this corner was previously approved by the Kent County Remonumentation Peer Group, monumented by Robert J. Jonker on 8-26-81 and was recorded per LCRC #1988.					
•		•			
B. Description of corner evide	ence found and/or me	ethod applied in restori	ng or reestablishing	corner:	
M-12 Found Kent County	Monument (Harriso	n) per witnesses from	n above LCRC as se	t by Robert J. Jonker in	place of the
				. and LCRC's #480 & #	
LCRC #1988		LCRC #70	069		
	g P. Pole N47°E		Remon, tag P. Pole		
	urch step N45°W		oottom church step		
C/L steel fence po			I fence post	N89°W 44.12'	
Face of North gate	ck bldg. N77°E e post S36°W		bldg. (siding)	N77°E 73.73'	
race of North gate	post 550 w	59.00 Face 01	North gate post	S36°W 89.58'	
The selected location	is accepted by me a	nd is generally accen	ted by professional	surveyors as the best av	ailahl <i>a</i>
evidence of the positi	ion of the original co	orner.	ted by protessionar.	saiveyors as are best av	anaose
evidence of the position. Description of monument for	or corner and access	ories established to pe	rpetuate locating the	position of the corner:	
M-12 Standard Kent Coun	ity Monument in Mo	on. Box			OF MICHIGA
Nail & KC Remon, ta	ag NW side P. Pole	N47°E 34.73'			1
SE corner bottom ste	p of bldg.	N45°W 76.10'		# 31	KIRK
C/L steel fence post		N89°W 44.07'			BREITELS
SW corner bldg. (sid		N77°E 73.65'		\$ * !	SURVEYOR 2
Face of North gate po	ost	S36°W 89.58'		\$ - \$	NO E
A.				# EV	30077
,	•			7,	RV
1/1	0 1/	7		***************************************	TAND SUP
1/.76	Bruth				THE PARTY OF THE P
Signed by	1 - 000		Date	2/19/98	
Surveyor's Michigan License N	30077	· · · · · · · · · · · · · · · · · · ·			