| \$7.00 | |
|--------|--|
| \$2.00 | |

Signed by

Surveyor's Michigan License No.

30077

KENT COUNTY REMONIMENTATION

| 2/.// | IEEE COOM I | LIVIONOIVILNIAIIO | | ، ن سی |
|--|---------------------------------|---------------------------------|--|--|
| \$2.00 | | RNER RECORDATION | | 32 86 |
| Car assument in | Filing Re | equirement of Act 74, M | | 台 注意 |
| For corners in | | | | \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ |
| KENT COUNTY | Located In: | Corner Code # | | SE D Res |
| (County) | , | Sparta Twp. | <u> </u> | |
| 1. Public Land Survey | T R | opana i wp. | 新 | |
| | TR | | ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,, | *#12 B |
| | TR | | othe | r-11/0 - |
| 2. Property Controlling | s_5 T_9NR_12V | | pec S | eg, 2 |
| in Section | STR | N-S 1/4 line | , | . * |
| 3. Miscellaneous | S TR | | | 11675 |
| Property in Sec. | S TR | | • | Deeds Stamp & File Number |
| | | | | |
| 4. Lot No, Recor | ded Plat | | a c c | |
| 5. Private Claims | | | | |
| · | | | 2 6 5- | |
| ET L D V L | , | 10 00 | 3 | |
| Kirk Breitels | , in a field survey on | c. 13 , 19 do hereby sta | ate that under 4 - 7 - 8- | 9-10-11-12- |
| requirements of P.A. 74, Michiga | in P.A. of 1970, the comer poin | ts mentioned in lines 1 and 2 a | bove were in | |
| conformance with regulations and | | | | |
| United States Department of the li that the corner points mentioned | | | | 16 15 14 13 |
| Board of Land Surveyors or by | | | | |
| recovered, found as expressed be | | , | 8 19 20 | 21 22 23 24 |
| NOTE: Not many than 2 com | | | 9 | |
| NOTE: Not more than 2 com on this certificate. | ers, all in the same town and | range, may be recorded | 10 30 29 | 28 27 26 25 |
| on the certificate. | | | 10 30 - 29 | |
| | | | 11 | |
| | | | 12 31 32 | 33 34 35 36 3 |
| A Description of adminstrate | | d/ar aukaa auant raataratian | 13 <u> </u> | |
| A. Description of original mor | | • | • | |
| • | Monument, LCRC #1070 | | | |
| SW corner of steel | _ | S80°E 73.87' | D 4 045 1055 | |
| | e block farm building | N55°E 98.04' | | KENT COUNTY |
| NW corner barn for | | N40°E 160.00' | PEER APPROV | ED/9/24/98 |
| | tag W. side P. Pole | N25°E 65.96' | CHAIRMAN 🕰 | |
| • | eche) - 0.07' West of line | North 88.77' N60°W 97.83' | | |
| SE corner house sid | . tag W. side P. Pole | N60°W 97.83' S15°E 161.38' | | |
| In C/L N-S asphalt | • | 313 101.36 | | 1 |
| • | lence found and/or method | applied in restoring or reest | ablishing corner: | \.\.\.\.\.\.\.\.\.\.\.\.\.\.\.\.\.\.\. |
| Found Kent County Wit | | | | |
| All witnesses above | • OV | | | PARTICION . |
| An witnesses above | 3 OK | | The state of the s | |
| | | | | |
| | | | ₽UA (| 22 2000 |
| | | | , (Co.) (Proc.) | No. Aug. |
| | | | . 52(| TION |
| | | | | |
| C Description of manument f | for corner and accessories | setablished to perpetuate for | cating the position of the corner | er vijetil 2000 til 100 til 10 |
| | County Witness Monumen | | and position or the conflet | OF WICH |
| SW corner of steel | | S80°E 73.87' | | KIRX BREITELS LAND |
| | block farm building | N55°E 98.04' | | XIRX X |
| NW corner barn for | | N40°E 160.00' | ; | BREITELS |
| | tag W. side P. Pole | N25°E 65.96' | Ÿ | LAND & |
| | eche) - 0.07' West of line | North 88.77' | | 🔠 🕻 SURVEYOR 🥻 🦥 |
| SE corner house sid | | N60°W 97.83' | | NO NO NO |
| Nail & KC Remon. | | S15°E 161.38' | | 30077 |
| In C/L N-S asphalt | | | | The second second |
| , [] | $\rho(I)$ | | _ | The state of the s |

12/28/99