

MAR 08 1999

KENT COUNTY REMONUMENTATION

SECTION LAND CORNER RECORDATION CERTIFIC Filing Requirement of Act 74, Mich. P.A. 19	970 \ 🙅 📆
KENT COLINTY	AR-5
County) Located in: Corner Code #	
1. Public Land Survey T 9N R 12W A-2 T R T R T R	M 8: 28
2. Property Controlling S T R S S T R S S T R	18422
Property in Sec. STR	Register of Deeds Stamp & File Nymber
A Lat N	. 1
4. Lot No, Recorded Plat 5. Private Claims	A B C D E F G H I J K L I
	2 - 6 - 5 - 4 - 3 - 2 - 1 -
I, Kirk Breitels , in a field survey on Jan. 20 , 19 98 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the	3 4 7 8 9 10 11 12
United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan	6 18 17 16 15 14 13
Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below:	7 8 19 20 21 22 23 24
NOTE: Not more than 2 corners, all in the same town and range, may be recorded	9
on this certificate.	10 30 29 25 27 26 25
The state of the s	11 12 -31 -32 -33 -34 -35 -36 -
A. Description of original monument and accessories and/or subsequent restoration:	
1943 Kent Co. Wits Iron & Stones 1984 LCRC #3806 Chettleburgh Set Kent County Monument	P.A. 345 1990 KENT COUNTY PEER APPROVED 2/19/98/ CHAIRMAN Day Johnson
The position of this corner was previously approved by the Kent County Remonume by Thomas M. Chettleburgh on 4-30-84 and was recorded per LCRC #3806.	ntation Peer Group, monumented
B. Description of corner evidence found and/or method applied in restoring or reestablishing cor	ner.
A-2 Found Kent County Monument (Harrison) per witnesses from above LCRC as set by of the Iron Pipe (36" deep) he found. Said Iron Pipe checks with Williams & Works LCRC #3806 Nail & Remon. tag 27" Willow N38°E 71.46' Nail & Remon. tag 30" Willow	Thomas M. Chettleburgh over top information. Kent Co. Wits. gone. N38°E 71.34'
Nail & Remon. tag 32" Willow N67°E 68.40' Nail & Remon. tag 36" Willow Nail & Remon. tag 13" Elm S70°E 55.01' Nail & Remon. tag 13" Elm Nail & Remon. tag 7" Elm S90°W 80.48' Nail & Remon. tag 16" Pine Nail & Remon. tag 8" Elm S90°W 83.83' Iron Pipe in Mon. Box	7 N67°E 68.70° S70°E 55.01° S30°E 147.16° S14°W 2.22°
Iron pipe in Mon. Box S14°W 2.22' Steel bar & cap (All-Points) The selected location is accepted by me and is generally accepted by professional sure evidence of the position of the original corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the original corner.	S45°E 46.61'
A-2 Standard Kent County Monument A-2 Standard Kent County Monument	
Nail & KC Remon, tag W. side 40" Willow N38°E 71.26' Nail & KC Remon, tag SE side 42" Willow N67°E 68.42' Nail & KC Remon, tag W. side 18" Pine S30°E 147.12' Nail & KC Remon, tag N. side P. Pole S90°W 54.06' Steel bar & cap (All-Points) S45°E 46.61' Iron pipe in Mon, Box S14°W 2.22'	KIRK BREITELS LAND SURVEYOR NO 30077
Signed by Kink Bun Ho	TAND SUR
Date	/19 /98
Surveyor's Michigan License No. 30077	