MAR 08 1999

KENT COUNTY REMONUMENTATION

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

REG. OF	98 MAR -5	STATE OF I
DEEDS	AM 8: 29	ANONIO MICHIGAN

For corners in

MENT COLDITY

KENT COONTT	Located In:	Corner Code #
(County)		
1. Public Land Survey	T <u>9N</u> R <u>1</u> T R_ T R_	12W E-5
2. Property Controlling in Section	S TR_ S T R	
3. Miscellaneous Property in Sec.	S T R_ S T R	


10449

Register of Deeds Stamp & File Number

4. Lot No. _, Recorded Plat 5. Private Claims

Kirk Breitels Jan. 22 , 19 $\frac{98}{}$ do hereby state that under in a field survey on requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.



A. Description of original monument and accessories and/or subsequent restoration:

1837 E-5 GLO Whitcomb Set Post 1935 Kent Co. Wits 3/4" Iron

1983 LCRC #3622 Chettleburgh Set Kent County Monument in Mon. Box

LCRC #6154 Byl

Kent County Monument in Mon. Box

P.A. 345 1990 KENT COUNTY PEER APPROVED 2/19/90

The position of this corner was previously approved by the Kent County Remonumentation Peer Group, monumented by Thomas M. Chettleburgh on 11-25-83 and was recorded per LCRC #3622.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

E-5 Found Kent County Monument (Harrison) per witnesses from above LCRC as set by Thomas M. Chettleburgh in place of the 1/2" Iron Pipe inside a 3/4" Iron Pipe he found inside a Mon. Box. Both Iron Pipeschecks with Kent Co. Wits. LCRC #3622 LCRC #6154

Nail & Remon. tag 10" Spruce NE 53.26' Nail & Remon. tag 12" Spruce N40°E 53.26' Nail & Remon. tag P. Pole SE 74.12' Nail & Remon. tag P. Pole S40°E 74.17' Nail & Remon. tag 25" Maple SSW 73.53' Nail & Remon. tag 28" Maple S45°W 55.46' Nail & Remon. tag 28" Maple SW 56.01' SW corner house foundation N50°W 98.07' SW corner House NW 98.00' SE corner brick porch pillar N30°W 67.65'

SE corner porch pillar NNW 67.60'

The selected location is accepted by me and is generally accepted by professional surveyors as the best available

c. Description of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

E-5 Standard Kent County Monument in Mon. Box

Nail & KC Remon. tag NW side 12" Spruce N40°E 53.26' Nail & KC Remon. tag NE side P. Pole S40°E 74.17' Nail & KC Remon, tag NW side 30" Maple S45°W 55.46' SW corner house foundation N50°W 98.07' SE corner brick porch pillar N30°W 67.65'

OF MICHIO KIRK **BREITELS** LAND SURVEYOR NO 30077 FOLAND

Signed by Surveyor's Michigan License No. 30077

2/19/98