

MAR 08 1999

KENT COUNTY REMONUMENTATION

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

REG. OF	98 MAY 21	STATE OF I
Selled	MH 8: 32	9977 182040 182040

For corners in

KENT COUNTY	Located In:	Corner Code #
(County)		
1. Public Land Survey	T <u>9N</u> R <u>1</u> T R_ T R_	2W E-8
Property Controlling in Section Miscellaneous	S TR_ S TR_ S TR_	
Property in Sec.	S TR_	


10619

Register of Deeds Stamp & File Number

4. Lot No	, Recorded Plat		
5. Private Claims		 	

I, Kirk Breitels , in a field survey on April 7, 19 $\frac{98}{}$ do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.



A. Description of original monument and accessories and/or subsequent restoration:

E-8	1837	GLO	Whitcomb	Set Post
	1935	Kent Co. Wits	•	Concrete Monument
	1979	LCRC #1253	Merdzinski	Iron
	1982	LCRC #2941	Merdzinski	Set Kent County Monument
	1991	LCRC #6157	Byi	Kent County Monument

P.A. 345 1990 KENT COUNTY
PEER APPROYED 4/30/98
CHAIRMAN Town Thukes

OF MICHIG

KIRK

BREITELS

LAND

SURVEYOR

NO

30077

The position of this corner was previously approved by the Kent County Remonumentation Peer Group, monumented by John A. Merdzinski on 4-13-82 and was recorded per LCRC#2941.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

E-8 Found Kent County Monument (Harrison) per witnesses from above LCRC as set by John A. Merdzinski in place of the ½" Iron Pipe he found. Said Iron Pipe checks with Kent Co. Wit. and LCRC #1253.

LCRC #2941			LCRC #6157		
Nail & Remon. tag 14" Ash	N70°E	33.52'	Nail & Remon. tag 14" dead Elm	N70°E	33.52'
Nail & Remon. tag 6" Elm	S50°E	36.06'	Centerline RR Iron in conc.	S90°W	26.3'
Nail & Remon. tag 8" Elm	S25°W	42.93'	Nail & Remon. tag 16" Ash	N60°E	35.27'
Nail & Remon. tag 8" Elm	N20°W	48.11'	C/L top hole W. end N'ly 8' CMP culv.	S15°W	69.17'
Centerline RR Iron in conc.	West	26.31	C/L top hole E. end N'ly 8' CMP culv.	S25°E	72.63'
C/L Peach Ridge is 7' East					

The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-8 Standard Kent County Monument
Nail & KC Remon. tag N. side 16" dead Elm
Centerline RR Iron in concrete
Nail & KC Remon. tag S. side 18" Ash
C/L top hole in W. end N'ly 8' CMP culvert
C/L top hole in E. end N'ly 8' CMP culvert
S25°E
72.63'

C/L Peach Ridge Ave. is 7' East ± C/L creek is South 80' ±

30077

On fence line E-W ±

4/30/98

Signed by / Lish / 2
Surveyor's Michigan License No.