\$7.00 \$2.00 MAR 08 1999

KENT COUNTY REMONUMENTATION

SECTION

*LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74 Mich. P.A. 1970

Earle	orners in	Fi	ling Requirem	ent of Act 74	l, Mich. P.A. 1	970	1		100	
							图一			
KE.	NT COUNTY (County)	Located In:	Corner	Code #			G. 67	5		
1. Pu	blic Land Survey	T1 T1	₹ <u>12₩</u> ₹	H-11			DEEDS	AH 8: 29	A TENT	
in :	operty Controlling Section	STI STI	<u> </u>					-		
3. Miscellaneous S T R						10467 Register of Deeds Stamp & File Number				
4. Lo	t No, Reco	rded Plat							,	i
5. Pr	t No , Recorvate Claims					1 A B	C D E	F G H	I J K	L N
						2 6-	5	4	2	— i—
1. K	irk Breitels	. in a field survey o	n Jan. 6	19 98 do here	hy state that under	- 1 1	8	910	11	12
requir	ements of P.A. 74, Michiga	an P.A. of 1970, the co	rner points mentio	oned in lines 1 ar	nd 2 above were in) _ [
Confor United	mance with regulations and States Department of the	I rules therefore as requ Interior, Bureau of Land	iired in the current I Management or b	manual of survey by a decree of a C	r instructions of the ourt of Law and /or		17 1	6		_13_
that th	e corner points mentioned	l in lines 3, 4 and 5 abo	ve were in conforn	nance with the rui	ies of the Michigan	· _ T				
	of Land Surveyors or by red, found as expressed be		t Of Law, establis	siled, r o e stablisi	iea, monumentea	8 —19—	20		23	 24
NOTE	E: Not more than 2 con	ners all in the same to	own and range r	nav he recorder	4	9				
,,,,,,,	on this certificate.		omi ana lango, i	nay be recorded	•	1030	29	2827	26	25
	·					11		│ 		-
	•					12 31-	323	3 34	35	<u> </u>
A D	ecorintian of original ma	onument and access	orioo ondiar aut	and weather	·_&i	13				
Α. υ	escription of original mo	onument and access	ones and/or sur	osequent restor	auon;					
ŀ	H-11 1837 GLO Whitcomb Set Post					P.A. 345	1990 KEN	IT COUN	ŢΥ	
	1967 Kent Co. 1976 LCRC #93		Concrete Mo Concrete Mo			PEER API CHAIRMA	PROYED	2/19/	981	_ ,
	1982 LCRC #29			inty Monumen	t	CHAIRMA	Nyce	nef	11-4	stre
	1995 LCRC #82	296 Breitels	Kent County	Monument						
		s corner was previo inski on 4-12-82 and				entation Pee	r Group, m	onumented		
В. [Description of corner evi	idence found and/or	method applied	in restoring or	reestablishing co	orner:				
ŀ	I-11 Found Kent Cour	nty Monument (Har	rison) per witne	esses from abo	ve LCRC as set	by John A. I	Merdzinski	in place of	?	
÷'	³ LCRC #2944	nument he found. S		LCRC #8296				1.		
	Nail & Remon.	tag P. Pole N tag 16" Cherry So	25°E 48.60'		on. tag P. Pole on. tag 30" Che	N25°E	48.60' 100.95'			
		tag for therry So			on. tag 50°Che		51.86'			
	NW corner gara	age foundation Si	35°W 168.56'	NW corner	garage foundati	on S35°W	168.56'			
	NW corner MB On C/L "X" int		55°W 84.10'	NW corner	MBT Box	S65°W	84.10'			
		ersection ion is accepted by n	ne and is genera	ally accepted b	y professional s	urveyors as t	he best ava	ilable		
C. D	escription of monument	sition of the original	l corner. ssories establis	hed to perpetua	ate locating the r	position of the	corner:			
	4-11 Standard Kent Co			, ,,				OF MIC	Marian.	
•	Nail & KC Remon	ı. tag W. side P. Pol		N25°E 48.6			117	-	(12 M	Se.
		n, tag N. side 30" Cl		S65°E 100.9			# */	KIRK Breitfi s	1 4	1
	Nail & KC Remon	n. tag W. side cor. for foundation	ence post	S40°E 51.8 S35°W 168.:			*	LAND	2 PA 2 X	
	NW corner Tele. E			S65°W 84.			九	SURVEYOR	≀ ∫ _	
	On C/L "X" inters	ection					A CA	30077	15	
		•					May 5	30077	URVE	•
	//	10 11	フジニ			,		CANO S	A STATE OF THE PARTY OF THE PAR	
Signe	ed by /Luli	But			Date	2/19/	28	KIRK BREITELS LAND SURVEYOR NO 30077		

30077

Surveyor's Michigan License No._