(T.)	1999年6月1日 1997年	ξ.
	STAVEY &	
ن م اه	REMONUMENTATION	
A(Y)	Kemonson	

MAR 08 1999

KENT COUNTY REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE

SECTIO	LANI Filit	O CORNER RECORDATION OF Act 74,	Mich. P.A. 1970	REG. OF	ATE OUNT
For corners in KENT COUNTY	Located In:	Corner Code #	i i	OF DEEDS	PROPERTY OF THE PROPERTY OF TH
(County)				BVA	AM IO:
1. Public Land Survey	T <u>9N</u> R T F T F	H-12 H-12		8 &	15 OFF
Property Controlling in Section Miscellaneous Property in Sec.	S TF S TF S TF	\		1072 Register of Deeds	22 Stamp & File Number
I, Kirk Breitels requirements of P.A. 74, Michiconformance with regulations at United States Department of the that the corner points mentions Board of Land Surveyors or recovered, found as expressed	_ , in a field survey of gan P.A. of 1970, the cond rules therefore as req e Interior, Bureau of Laned in lines 3, 4 and 5 about a Decree of a Coubelow:	on Aug. 24 1998 do her orner points mentioned in lines 1 a uired in the current manual of survey did Management or by a decree of a over were in conformance with the rort of Law; established, re-established, and range, may be recorded.	eby state that under and 2 above were in ey instructions of the Court of Law and /or ules of the Michigan shed, monumented,	9 10 30 29 11	G H I J K L M 3
A. Description of original	monument and acces	ssories and/or subsequent rest	toration:	12 31 32	<u> </u>
H-12 1837 GLO 1946 William 1967 Kent Co MBT 1968 William	ns & Works o. Wits. W 32.92' CP SE 5 ns & Works	Not Set Meas. 2643.94' to M '/'' Iron 3.32' 22" Maple NNW 85.6 Mon. Box - held stra	on. at center from S 55' 10" B. Elder E sight N-S 1/4 line bo	NE 48.14' owever	
H-12 Found 3/4" Iro PK in P. Po	evidence found and, on Pipe in Mon. Box le N85°W 33.02' onle N20°W 86'	for method applied in restoring per the following witnesses: PK in P. Pole S35°F Nail in 30" Maple N20°	E 53.35' Meas.	rner: . 2644.07° to S 1/4 co	orner

3/4" Iron Pipe in Mon. Box is 7.1' S.. & less than 0.1' E. from intersection of 1/4 lines and has been used in surveys by Byl, Clapp, Exxel, Williams & Works and Joiner.

The 3/4" Iron Pipe in Mon. Box is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the corner.

Surveyor's Michigan License No. 30077	H-12 Set Standard Kent County Monument in a Mo Nail & KC Remon. tag S. side P. Pole Nail & KC Remon. tag SW side P. Pole Nail & KC Remon. tag E. side 30" Maple Nail & KC Remon. tag W. side 30" Maple Nail & KC Remon. tag S. side 24" Poplar C/L N-S asphalt road is West 4' ±	S35°E 53.35'	