

For corners in

MAR 08 1999

KENT COUNTY REMONUMENTATION

SECTION


*LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

REG. OF DEEDS	98 MAR -5 AM 8: 30	STATE OF MICHIGAN

 $\frac{10479}{\text{Register of Deeds Stamp \& File Number}}$

I. Kirk Breitels , in a field survey on Jan. 22 , 19 98 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below.

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.



A. Description of original monument and accessories and/or subsequent restoration: P.A. 345 1990 KENT COUNTY

Set Post I-12 1837 GLO Whitcomb Mon. Box Kent Co. Wits 1971 Solid Bar in Mon. Box VanKooten 1972 LCRC #3559 Set Kent County Monument in Mon. Box Kolehouse LCRC #3630 1983 Kent County Monument LCRC #8307 **Breitels** 1995

PEER APPROVED 2/19/98 CHAIRMAN Fary Huber

The position of this corner was previously approved by the Kent County Remonumentation Peer Group, monumented by Randy J. Kolehouse on 11-26-83 and was recorded per LCRC #3630.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I-12 Found Kent County Monument (Harrison) per witnesses from above LCRC as set by Randy J. Kolehouse in place of the 1" Solid Iron he found inside a Mon. Box. Said Iron checks with Kent Co. Wits. and LCRC #3559.

LCRC #8307 LCRC #3630 S20°W 148.65' S20°W 148.65' Nail & Remon. tag P. Pole Nail & Remon, tag P. Pole S70°E 152.00' Nail & Remon. tag P. Pole 152.00' Nail & Remon. tag P. Pole S85°W 19.05 N35°W 28.6' C/L Catch Basin C/L traffic sign plst S85°W 19.05' W'ly edge pavement N. bd. M-37 N60°E 1.10 C/L C.B. Face of E'ly leg "wrong way" sign S10°E W'iy edge pavement N. bd. M-37 N60°E 4.98' On C/L Sparta Ave. ext. & on fence line West

The selected location is accepted by me and is generally accepted by professional surveyors as the best available

evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

I-12 Standard Kent County Monument
Nail & KC Remon. tag W. side P. Pole
Nail & KC Remon. tag N. side P. Pole
S20°W 148.65'
Nail & KC Remon. tag N. side P. Pole
C/L Catch Basin
S85°W 19.15'
Westerly edge pavement of N. bound M-37 N60°E
Face of Easterly leg of "wrong way" sign
On C/L Sparta Ave. extended.

Signed by Link Bruselo
Surveyor's Michigan License No. 30077

KIRK BREITELS LAND SURVEYOR NO 30077

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14,1975 REVISED JAN., 1983 REVISED OCT., 1995

2/19/