

KENT COUNTY

For corners in

M-3

MAR 08 1999

KENT COUNTY REMONUMENTATION

| | rante) | C | ALC: N | 1 | 7 | N |
|-----|--------|---|--------|---|---|-----|
| شاه | B | 6 | 2 2 | 4 | | 8 1 |

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970


| 98 MAR -5 | STATE OF MUHIDAN COUNTY OF KENT RECEIVED FOR RECORD |
|-----------|---|
| 7 | |
| လ လ | |
| | -5 AH 8: |

10497 Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____ 5. Private Claims

I, Kirk Breitels , in a field survey on Jan. 5 , 1998 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.



A. Description of original monument and accessories and/or subsequent restoration:

| 1837 | GLO | Brookfield | Set Post |
|------|---------------|------------|--------------------------|
| 1934 | Kent Co. Wits | | 1" Iron |
| 1979 | LCRC #1313 | Nederveld | 1" Round Iron |
| 1983 | LCRC #3385 | Stadt | Set Kent County Monument |
| 1995 | LCRC #8330 | Breitels | Kent County Monument |

P.A. 345 1990 KENT COUNTY
PEER APPROVED 2/19/98
CHAIRMAN Aug Frence

The position of this corner was previously approved by the Kent County Remonumentation Peer Group, monumented by Russell E. Stadt on 5-5-83 and was recorded per LCRC#3385.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

M-3 Found Kent County Monument (Harrison) per witnesses from above LCRC as set by Russell E. Stadt in place of a 1" Iron over a 1" Iron he found over a Stone. Both Irons and Stone check with Kent Co. Wits. and LCRC #1313.

| LCRC #3383 | | | LCRC #8330 | | |
|-------------------------------|-------|---------|-----------------------------------|-------|--------|
| Nail & Remon. tag 12" Oak | S25°E | 73.78' | Nail & Remon. tag Tri. 6"-15" Oak | S25°E | 73.94' |
| | | 41.68' | Nail & Remon. tag Tri. 24" Oak | | |
| Nail & Remon, tag 16" Tw. Oak | S25°W | 126.431 | * Ten | | |
| | S45°W | 82.831 | S. edge 4" steel fence post | N00°E | 32,24' |
| S. edge 4" steel fence post | North | 33.20' | Nail & Remon. tag 10" Oak | S70°E | 24.27' |

... C/L road W. is 3' N. and C/L road S. is 8' W.

The selected location is accepted by me and is generally accepted by professional surveyors as the best available

evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M-3 Standard Kent County Monument Nail & KC Remon. tag W. side Tri, 6"-15" Oak S25°E 73.75 Nail & KC Remon. tag E. side Tri. 24" Oak S25°W 126.37 NE corner house foundation (#10) S45°W 82.83' S. edge 4" dia. steel fence post (2nd post N.) N00°E 48.06 Nail & KC Remon. tag N. side 12" Oak S70°E 24.27 C/L blktp. road (ext.) West is 3' North

C/L blktp. road (ext.) South is 8' West
On fence line North

Link Butel

KIRK
BREITELS
LAND
SURVEYOR
NO
30077

Date 2/19/98

Signed by Link Butel
Surveyor's Michigan License No. 30077