Signed by

Surveyor's Michigan License No.

SEP 1 8 1995

 $2.\overline{00}$ commission

KENT COUNTY REMONUMENTATION

STATE OF MICHIGAN COUNTY OF KENT RECEIVED FOR RECORD

LAND CORNER RECORDATION CERTIFICATE Piling Deguirement of Ast 74 Mich D & 4070

95 MAY 12 AM 10: 53

10

11

12

For corners in		riting nequi	ement of Act 74, which F	1.06.1	
	(County)	Located In:	Corner Code ##	REG. OF DEEDS	
1.	Public Land Survey	T 10N R 11W			
		T R T R		8363	
2.	Property Controlling in Section	S T R S T R		0000	
3.	Miscellaneous Property in Sec.	S T R S T R		Register of Deeds Stamp & File Number	
4. 5.		Recorded Plat		A B C D E F G H ! J K L	

Kirk Breitels Feb. 21 in a field survey on _ do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:

C-2	1837 1938	GLO Kent Co. Wit.	Cathcart	Set Post Concrete Monument
	1983	LCRC #3691	Glaza	Re-rod
	1992	LCRC #6589	Bueche	Set Kent County Monument
	1992	LCRC #6619	Erickson	Kent County Monument

The position of this corner was previously approved by the Kent County Remonumentation Peer Group, monumented by John C. Bueche on 10/12/92 and was recorded per LCRC #6589.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

C-2 Found standard Kent Co. Mon. (Harrison) per witnesses from above LCRC as set by John C. Bueche in place of the Re-rod he found. Said Re-rod checks with Kent Co. Wit. and LCRC #3691.

LCRC #6589		,	
Nail NW side 22"	Ash	N40°E 31.28'	P.A. 345 1990 KENT COUNTY
Nail & KC Remon.	tag SW side 22" Oak	N40°W 49.12'	PEER APPROVED 4/27/9
	tag W. side 32" Oak	S20°E 70.44'	CHAIRMAN Trany
Nail & KC Remon.	tag E. side 12" Poplar	S30°W 42.07'	CHAIRMAN 2 range / ha
W. edge 3" angle	iron fence post	East 27.18'	/
C/L dr. W Nor	th 12' m/l: On C/L gravel	rd. N-S	

The selected location is accepted by me and is generally accepted by professional

surveyors as the best available evidence of the position of the original corner.

C-2 Standard Kent County Monument		OF M/64
Nail NW side 22" Ash	N40°E 31.26'	SE LIVE
Nail & KC Remon. tag SW side 22" Oak	N40°W 49.27'	KIRK
Nail & KC Remon. tag W. side 32" Oak	S20°E 70.47'	BREITELS LAND
Nail & KC Remon. tag E. side 12" Poplar	\$30°W 42.07'	SURVEYOR
W. edge 3" angle iron fence post	S90°E 27.18'	A NO
C/L dr. W North 12' m/l; On C/L gravel	rd. N-S	ر 30077 <u>م</u>
		The State of

A A A A 30077

OF WIEHIO

DTAMO

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971