EP 1 8 **19**95

KENT COUNTY REMONUMENTATION

STATE OF MICHIGAN COUNTY OF KENT RECEIVED FOR RECORD

95 MAY 12 AM 10: 45

LAND CORNER RECORDATION CERTIFICATE. Filing Requirement of Act 74, Mich. P.A. 1970

120

For corners in KENT COUNTY	Located In:	Corner Code ##	REG. OF DEEDS	
(County)				
1. Public Land Survey	T <u>10N</u> R <u>11W</u>	F-9		
	T R			
	T R			
	T R		\ 0.20 W	
2. Property Controlling	S T A	***************************************	`8397	
in Section	S T R		•	
3. Miscellaneous	S T R		Register of Deeds Stamp & File Number	
Property in Sec.	\$ T R			
4. Lot No	, Recorded Plat		ABCDEFGHIJKL	
5. Private Claims				

t, <u>Kirk Breitels</u>, in a field survey on <u>Feb. 24</u>, 19 <u>95</u>, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

F-9	1837	GLO Kent Co. Wit.	Cathcart	Set Post Iron
	1981	LCRC #2084	Nederveld	Nail
	1982	LCRC #2906	Jonker	Set Kent County Monument

The position of this corner was previously approved by the Kent County Remonumentation Peer Group, monumented by Robert J. Jonker on 6/9/82 and was recorded per LCRC #2906.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

F-9 Found standard Kent Co. Mon. (Harrison) per witnesses from above LCRC as set by Robert J. Jonker in place of the Rerod & cap (Nederveld) he found. Said Rerod and cap checks with Kent Co. Wit. and LCRC #2084. LCRC #2906

Remon. tag E. side 30" Maple S00°E 33.43' P.A. 345 1990 KENT COUNTY Remon. tag W. side 8" Pine N30°E PEER APPROVED 4/27/95 CHAIRMAN James Julier 43.04' Remon. tag N. side P. Pole Remon. tag E. side P. Pole S55°E 76.53 N35°W 196.6' On C/L E-W gravel

The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

r-9 Standard Kent County	Monument	
Nail & KC Remon.	tag E. side 30" Maple (dead)	S00°E 33.43'
Nail & KC Remon.	tag N. side P. Pole	S55 E 76.53'
	tag E. side P. Pole	N35°W 196.64'
Set Nail & KC Remon.		S05°W 23.74'
Set Nail & KC Remon.	tag W. side P. Pole	N15°E 155.66'
On C/L E-W gravel		
	, 1	

KIRK BREITELS

Surveyor's Michigan License No. 30077