

SECTION

## KENT COUNTY REMONUMENTATION

	) SEC	TION	KENT COU	NTY REMONUI	MENTATIO	ON	9	SE S
3.		-		RECORDATION				KÖM KÖM
For corr	ore in		Filing Require	ment of Act 74, Mi	ch. P.A. 19/0	) S	sul No	밀크유
						A (C		∃e≭
KEN	COUNTY	Located In:	Corne	er Code #	ļ	53 Ch		五天至
****	(County)			Solon Twp.		) PEEDS	od	西望高
1 Publ	ic Land Survey	T10N	R 11W	L-5			G.	즐글꽃
1,1 00	.o 24,14 02.10)	Τ	R		İ		2	e e
		Т						
		<u> </u>	_ <u>R</u>					
•	erty Controlling	S T	_ <u>R</u>	<del></del>	}			
	ection	S !	- K	<del></del>	ļ	1	1108	
3. Miscellaneous S T R								
	,		-	· · · · · · · · · · · · · · · · · · ·	<u> </u>	Register of L	eeds Stamp 8	File Number
4 Lot!	Vo Red	corded Plat						
5. Priva	ate Claims	oorded ridt			_	A B C D	E F G H	I J K L M
						2 6 5	43-	
	•					3		
I Kirl	: Breitels	. in a field survey	on Jan. 12	. 19 99 do hereby sta	ate that under	4 - 7 - 8 -	910-	11-12-
requirem	ents of P.A. 74, Micl	higan P.A. of 1970, the	corner points men	_, 19 99 do hereby stationed in lines 1 and 2 a	bove were in	5		
conform	ance with regulations	and rules therefore as re	equired in the curre	nt manual of survey instr r by a decree of a Court o	uctions of the			
that the	corner points mention	ned in lines 3, 4 and 5 a	bove were in confo	rmance with the rules of	the Michigan		10 15	
Board o	f Land Surveyors or	by a Decree of a Co		lished, re-established, r		/		
recovere	d, found as expressed	a below:				8 19 20	21 22-	
NOTE:	Not more than 2 of	comers, all in the same	e town and range	, may be recorded		9	1 1 1	
	on this certificate.					10 30 29	2827-	26 25
						11 -	+	<del>                                     </del>
						12 -31 32-	33 -34	3536
						13		<u> </u>
A. Des	scription of original	monument and acce	ssories and/or s	ubsequent restoration	1:	P.A. 345	1990 KENT	COUNTY
L-5	1 <b>837</b> GLO	Cathcart	Set Pos	t		PEER AF	PROVED Z	[25] []
	1966 Kent Co		Iron			CHAIRM	Mou	y/ Luke
	1984 LCRC #			nt County Monument	t in Mon. Box	Of IAU non	1	
•	1990 LCRC #	45591 Marschall	Kent C	ounty Monument			•	
	The position of the	his corner was previ	ously approved	by the Kent County	Remonumenta	tion Peer Group	o, monumente	ł
		house on 3-30-84 a				•	•	
B De	scription of corner	evidence found and/	or method applie	ed in restoring or reest	tablishing corne	er.		
	•			sses from above LCI			ise in nloce of	
				hecks with Kent Co.		and, 5. ILUKORO.	ase in place of	
•	LCRC #3797			LCRC #5591				
-	Nail & Remor		5°W 54.20'	Nail & Remon. tag		E 40.87'		
	Nail & Remor		0°W 70.43'	Nail & Remon. tag		W 70.35'		
	Nail & Remor		5°E 40.87'	Nail & Remon. tag		V 54.13'		
	C/L 20 Mile F	ouse foundation S40	FE 91.4	NW cor. house fou	indation S40°1	3 91.38		
		ing South is 2' East						
			me and is gener	ally accepted by prot	fessional surve	yors as the best	available	
A ==	evidence of the r	osition of the origin	al corner	· · · · · ·				
		_	cessories estab	lished to perpetuate lo	ocaung me post	aon or the come		The state of the s
L-3	Standard Kent Co	ounty Monument on, tag W. side P. Po	da Misor	40 80°			OF	MICH, WO
		on, tag W. side P. Po on, tag N. side P. Po		40.89' 7 70.40'			A PARTIE OF THE	PA
		on, tag W. side P. Pe		54.17'				IRK N
	NW corner house	-	. S40°E			į	BRE	ITELS &
		· <del>-</del>				Í	() <b>24 %</b>	VEVOD 8
								40 / 4
							(S) (A)	077
	./	100	,	•			SED L	0077

Kinh Buls Company of the Date 30077 Surveyor's Michigan License No.