

Signed by

Surveyor's Michigan License No.

30077

MAY 2.2 2000

KENT COUNTY REMONUMENTATION

-5.00	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,			
SECTION	18.6	ORNER RECORDATION CE	. P.A. 1970	ON 6661
For corners in			ES T	
KENT COUNTY	Located In:	Corner Code #		
(County)		Solon Twp.		
	T10NR 11	-	DEEDS	· I Ini
1. Public Land Survey	T 101 R 11	10-12	os	9 <u>8 8 8</u>
	†			<u>س بر </u>
	T R		'	on D
2. Property Controlling	S TR			
in Section	S TR		445	0.4
3. Miscellaneous	<u> </u>		114	9.1
Property in Sec.	S TR		Register of De	eds Stamp & File Number
4. Lot No, Recorde	ed Plat	••		
5. Private Claims			A B C D E	FGHIJKL
1			2 - 6 - 5 -	_ 4 3 2 1 -
			3	
Kirk Breitels	in a field survey on	ug. 12, 19 do hereby state t	hat under 4 7 8	9 10 11 12
requirements of P.A. 74, Michigan I	P.A. of 1970, the corner po	ints mentioned in lines 1 and 2 abov	re were in	
conformance with regulations and rul	les therefore as required in	the current manual of survey instruction	onsortne	
United States Department of the Inte	rior, Bureau or Land Manag lines 3. 4 and 5 above wer∉	gement of by a decree of a Court of La in conformance with the rules of the	Michigan	16131413-
Board of Land Surveyors or by a	Decree of a Court of La	w; established, re-established, mon	umented,	
recovered, found as expressed below	v:		8 19 20-1	_21222324-
NOTE: Not more than 2 corners	s, all in the same town an	d range, may be recorded	9	
on this certificate.	-,		10 30 29	28272625_
			11	
			12 31 32	33 34 35 36
			12	<u> </u>
A. Description of original monu	ment and acceptains s	ind/or subsequent restoration:	P.A. 345 1990	KENT COUNTY
·	ment and accessories e		PEER APPROV	
L-12 1837 GLO 1906 Williams &	Works	Not Set Iron	011	
1906 Williams & 1948-67 Williams &		2" Iron	CHAIRMAN	aug puvel
		3.80' 12" Hickory ENE 130.	18' 8" Manle E 58 85'	
		is East 4' 'Fence to West is No		,
1974 Kent Co. W		Mon. Box ? - witnesses appea		
1978 LCRC #120		2" Iron		
P. Pole W	Vest 26.65' 38" Oak S	SSE 35.54' 10" Cherry NE 62.	.0' E-W fc. 3.3' N. Fc. S.	3.5' E.
,				1
		d applied in restoring or reestabli		
		nalt road per remaining witnesse	es:	
C/L 24" Maj	ple E 59' C/L 15" Ch	erry NE 62		1.
Said DK Mail is 0.17	W &177'N from into	ersection of 1/4 lines and agrees	s with surveys by Williams &	: Works, Jonker.
Hackbardt, Jonker ar		disconding 174 lines and agrees	· · · · · ·	, , or
Hackbardt, Johner al.	id i i ioko.		T.	•
The PK Nail is accer	oted by me and is gener	ally accepted by professional st	urveyors as the best available	e evidence of the
position of the corner			•	
•				
				ľ
			ng the position of the corner:	
C. Description of monument for			ng the position of the corner:	OF MICH, MA
	tounty Monument in Mining tag NW side 15" Cher	on. Box in place of the PK Nail ry N35°E 62.14'		A STATE OF THE STA
	tag Nw side 15" Cher tag S. side 24" Maple	N90°E 59.12'		KIRK W
	tag NE side 18" Popla			BREITELS & * 1
Nail & KC Remon.		S05°W 219.85'	**************************************	LAND **
	tag S. side 24" Maple	N90°W 66.34'		SOKAELOK
	tag NE side P. Pole	N55°W 32.66'		(30077) 3 S
Capped Rerod (Hac		West 33.02'		30077 - 3
	road and on tree row E		•	PARO LAND S
· -	00			AND THE PERSON NAMED IN COLUMN TO SERVICE OF THE PERSON NAMED IN COLUMN TO SER