

# LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF--:	LOCATED IN--:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY <u>25</u> T. <u>10</u> N. <u>12</u> E. W.		<u>K-9, K-10</u>
2. PROPERTY CONTROLLING IN SECTION _____, T. _____, S. _____, R. _____ E. W.		
3. MISCELLANEOUS PROPERTY IN SECTION _____, T. _____, S. _____, R. _____ E. W.		
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

DEC 13 8 56 AM '85  
**4312**  
 REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Donald L. Bissell, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on July, 1985, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on \_\_\_\_\_, 19\_\_\_\_, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

K-9 NW Cor. Fd. Iron W. SW - 91.41' - Spike in group of Elms S. SE - 44.53' - Spike in 12" Apple Tree E. NE - 96.13' - Spike in Sign Post NE - 82.23' - Spike in 24" Oak	K-10 W 1/4 Cor. Fd. Iron S45°W - 8.68' - Nail in 10" Maple South - 4.48' - Nail in 12" Maple S85°W - 34.35' - Nail in Maple Cluster. North - 14.44' - Nail in 8" Hickory West - 235± - Center Rogue River.
--	---

Witnesses from Williams & Works

Witnesses from Burt Wickham

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K-9 NW Cor. Iron W. SW - 91.41' - Spike in group of Elms. S. SE - 44.53' - Spike in 12" Apple tree. E. NE - 96.13' - Spike in Sign Post. NE - 82.23' - Spike in 24" Oak.	K-10 W 1/4 Cor. Iron S45°W - 8.68' - Nail in 10" Maple. South - 4.48' - Nail in 12" Maple. S85°W - 34.35' - Nail in Maple Cluster North - 14.44' - Nail in 8" Hickory . West - 235± - Center Rogue River.
--	--


SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_

SURVEYOR'S MICHIGAN REGISTRATION NO. \_\_\_\_\_

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_

APPROVED AND SIGNED BY Donald L. Bissell  
CHIEF OF SURVEY PART  
MICHIGAN REGISTERED LAND SURVEYOR



SURVEYOR'S MICHIGAN REGISTRATION NO. 18655