

RECEIVED

JAN 10 1987

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF -:	LOCATED IN -:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY <u>25</u> T. <u>10</u> N. <u>12</u> E. W.		L-11,
2. PROPERTY CONTROLLING IN SECTION <u>25</u> T. <u>10</u> N. <u>12</u> E. W.		15
3. MISCELLANEOUS PROPERTY IN SECTION _____ T. _____ N. _____ S. _____ R. _____ E. _____ W.		
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

RECEIVED
 DEC 13 8 57 AM '85
 REGISTER OF DEEDS STAMP AND FILING NUMBER
4314

I, Donald L. Bissell, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on July, 1985, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

- | | |
|---|---|
| <p>L-11 S 1/4 Cor. Fd. Iron s. edge road
 S SE - 17.63' - Spike in 18" Maple
 S SW - 21.70' - Spike in 14" Maple
 North - 70.72' - Spike in Power Pole
 South - 22.70' - Spike in 10" Elm</p> | <p>15. S 1/8 Cor. of SW 1/4, Fd. iron in mon. box
 NW - 50.25' - Spike in 10" Walnut
 NE - 83.15' - Spike in 14" Twin Elm
 E SE - 48.10' - Spike in 6" Cottonwood
 W SW - 61.80' - Spike in M.B.T. Pole</p> |
|---|---|

Witnesses from Williams & Works

Witnesses from Williams & Works

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- | | |
|--|---|
| <p>L-11 S 1/4 Cor. Iron in s. edge road
 S SE - 17.63' - Spike in 18" Maple
 S SW - 21.70' - Spike in 14" Maple
 North - 70.72' - Spike in Power Pole
 South - 22.70' - Spike in 10" Elm</p> | <p>15. S 1/8 Cor. of SW 1/4 Iron in mon. box
 NW - 50.25' - Spike in 10" Walnut
 NE - 83.15' - Spike in 14" Twin Elm
 E SE - 48.10' - Spike in 6" Cottonwood
 W SW - 61.80' - Spike in MBT Pole</p> |
|--|---|


SIGNED BY _____ DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____

APPROVED AND SIGNED BY Donald L. Bissell CHIEF OF SURVEY PARTY MICHIGAN REGISTERED LAND SURVEYOR DATE 12-9-85



SURVEYOR'S MICHIGAN REGISTRATION NO. 18655