

## KENT COUNTY REMONUMENTATION

\$7.00	
\$4.00	

SECTION

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in	i-mig ive		310 	
KENT COUNTY	ocated In:	Corner Code #	A S	
(County)			3 25 5	يمسر السيداد ا
Public Land Survey     Property Controlling S	T10NR 12W TR TR  TR T_R	Tyrone Twp.  H-9		三 混淆等
in Section S. Miscellaneous S.	TR TR		1116	O
Property in Sec. S	TR		ユユュリ Register of Deeds Sta	
		_	,	
4. Lot No, Recorded 5. Private Claims	Plat		A B C D E F G	HIJKLM
			2 6 5 4	- 3 2 1 - 1
Viels Proitale	e 11 18	n. 19 , 19 99 do hereby state that under	3	
requirements of P.A. 74, Michigan P.A.	1 _			
United States Department of the Interio	r, Bureau of Land Manage	ne current manual of survey instructions of the ement or by a decree of a Court of Law and /o	; f 6 18 17 16 1	_151413
that the corner points mentioned in line	es 3, 4 and 5 above were i	In conformance with the rules of the Michigar r; established, re-established, monumented	• _ [	
recovered, found as expressed below:		,	8 19 20 21	_222324
NOTE: Not more than 2 corners,	all in the same town and	i range, may be recorded	9	+
on this certificate.			10 30 29 28	27 26 25
			11	
			12 31 32 33	34 35 36
A. Description of original monum	ent and accessories ar	nd/or subsequent restoration:	13	
H-9 1837 GLO	Whitcomb	Set Post	P.A. 345 1990 KENT	COUNTY
1966 Kent Co. Wit		Iron on Stone	PEER APPROVED _	2/25/98
1981 LCRC #1956		½" Iron	CHAIRMAN For	If twhen
19 <b>82</b> LCRC #3026 1991 LCRC #5999		Set Kent County Monument Kent County Monument		
The median of this co		pproved by the Kent County Remonu	mentation Peer Group, monu	mented
		rded per LCRC #3026.	monution red Group, mond	Montod
B. Description of corner evidence	e found and/or method	d applied in restoring or reestablishing c	orner:	
1/2" Iron Pipe over a St	onument (Harrison) pone he found. Said Ir	per witnesses from above LCRC as second & Stone check with Kent Co. Witnesses	t by Thomas C. Starr in place s. and LCRC #1956.	of the
LCRC #3026	32" Maple S25°W	LCRC #5999 87.67' Naii & Remon. tag 40" Ma	aple S25°W 87.25'	
Nail & Remon. tag	P & T Pole S40°E	88.24' Nail & Remon. tag P & T	Pole S40°E 88.24'	
	P & T Pole N45°E			
	Tri. 12" Ash N20°E P&T Pole N60°W	<del>-</del>		
NW cor. frame hou	ise S60°W	141.08' NW cor. frame house	S60°W 141.02'	1
The selected location evidence of the position C. Description of monument for	is accepted by me and on of the original com corner and accessories	is generally accepted by professional ier. sestablished to perpetuate locating the	surveyors as the best available position of the corner:	oie
H-9 Standard Kent County			<b></b>	OF MICH
Nail & KC Remon. ta	g W. side 40" Maple	S25°W 87.22'		12.8
Nail & KC Remon. ta Nail & KC Remon. ta		S40°E 88.24' N45°E 76.86'	# / * /	BREITELS BREITELS
Nail & KC Remon. ta		h N20°E 88.73'	* *	LAND **
Nail & KC Remon. ta	g S. side P. Pole	N60°W 131.30'	2/25/99	BREITELS LAND SURVEYOR NO 30077
				30077
,				CANDSUR
//	Buls		- 1 100	WHO THE PARTY OF T
Signed by	<u> </u>	Date	2/25/99	
Surveyor's Michigan License No.	30077			