KENT COUNTY REMONUMENTATION

| }\ }\ | ION | | į. | NTA | IO |
|----------|-----|---|----|------|----|
| | MAR | 0 | 8 | 1999 | |

LAND CORNER RECORDATION CERTIFICATE

| MAR 0 8 1999 | LAND CORNER RECORDATION Filing Requirement of Act 74, M | |
|--|--|--|
| For corners in KENT COUNTY Located In: (County) | | RESERVED TO SERVED TO SERV |
| 1. Public Land Survey T T T T | 10N R 12W | DEEDS OF 31 |
| 2. Property Controlling ST in Section ST T T ST T T T | R | 10507 Register of Deeds Stamp & File Number |
| 4. Lot No, Recorded Plat 5. Private Claims | | A B C D E F G H I J K L 2 6 5 4 3 2 1 1 3 |
| I, <u>Kirk Breitels</u> , in a field sur requirements of P.A. 74, Michigan P.A. of 1970, conformance with regulations and rules therefore a United States Department of the Interior, Bureau of that the corner points mentioned in lines 3, 4 and Board of Land Surveyors or by a Decree of a recovered, found as expressed below: | above were in ructions of the of Law and /or 6 18 17 16 15 14 13 | |
| on this certificate. | ame town and range, may be recorded | 9 10 -30 - 29 - 28 - 27 - 26 - 25 - 11 12 - 31 - 32 - 33 - 34 - 35 - 36 - 13 |
| A. Description of original monument and action of a second | field Set Post 1 ½" Iron ema "T" Iron | P.A. 345 1990 KENT COUNTY PEER APPROYED 2/19/98 CHAIRMAN AVAILATION |
| by John A. Merdzinski on 12-9-80 | reviously approved by the Kent County 0 and was recorded per LCRC#1501. nd/or method applied in restoring or reest | Remonumentation Peer Group, monumented |
| I-13 Found Kent County Monument (I the Wagon Wheel Hub he found. LCRC #1501 | Harrison) per witnesses from above LC Said Wagon Wheel Hub checks with I LCRC #6014 | CRC as set by John A. Merdzinski in place of |
| Nail & Remon. tag 10" Elm Nail & Remon. tag fence post Nail & Remon. tag fence post "X" cut on conc. culv. "T" Iron in Mon. Box | N45°W 34.98' Nail & Remon. tag S80°W 19.67' Nail & Remon. tag N90°E 60.53' Nail & Remon. tag by me and is generally accepted by pro | culv. S80°W 19.67' W cor. 2-9-12) N90°E 60.56' g P. Pole N15°W 101.49' g 12" Poplar N60°E 122.98' g 10" Elm S50°E 141.91' ofessional surveyors as the best available |
| I-13 Standard Kent County Monument Nail & KC Remon. tag E. side P. "X" cut on concrete culvert Nail & KC Remon. tag W. side P. Nail & KC Remon. tag SE side 12 Nail & KC Remon. tag SW side 1 Nail & KC Remon. tag S. side 14 Kent Co. Mon. (I-1, T9N, R12W) 20' ± West of West edge asphalt re | Pole S10°W 85.94' S80°W 19.67' Pole N15°W 101.49' 2" Poplar N60°E 123.08' 4" Elm S50°E 141.95' " Elm S70°E 134.42' N90°E 60.60' | KIRK BREITELS LAND SURVEYOR NO 30077 |
| Signed by Luke Buyers Surveyor's Michigan License No. 300 | | Date 2/19:/98 |