\$7.00

MAY 2 2 2000

KENT COUNTY REMONUMENTATION

22.00		•	- 14DIAOMEMI		
For any	sin SECTION	LAND CORNER RE	CORDATION CERTIL	FICATE	
For corners	- u ₁	ming Requiremen	it of Act 74, Mich. P.A.	. 1970	RE S
KENT	COUNTY Locate		·	1	STATE COUN RECEIVE
•	(County)	o in: Corner Co	de #	REG.	
1. Public L	and Survey	TION R 12W I-		90E	
		TR	5	DEEDS	의 유명품
		TR		Ds	
2. Property	Controlling S			•	ECOR B: 0
in Section 3. Miscellan	n s	TR			
Property	in Sec.	TR			- -
		IR		116	25
4. Lot No.	Possedad pu		L	Register of Deeds	Stamp & File Numbe
5. Private CI	aims			•	
Ĭ				ABCDEF	<u> </u>
(Kinte D)	. 1			2 6 5	TITIT
requirements of	tels P.A. 74, Michigan P.A. of 1970 h regulations and rules therefore	irvey on Dec. 1 40 90		3	- 1 - 2 - 1 - 1 -
conformance with	h regulations and rules therefore	the corner points mentioned in	_ do hereby state that under	4 9	10-10-1
E IDSt the semi-	" O THE OLD DISTRALL	If I and Manager	AL AMIACA HISTLIGATURE VAIP	5	12
Board of Land s	epartment of the Interior, Bureau coints mentioned in lines 3, 4 and Surveyors or by a Decree of a as expressed below:	5 above were in conformance wi	th the rules of the Michigan	6 19 17 16	15 (14)
		.,	Townshed, monumented.	7	
NOTE: Not mo	ore than 2 comers, all in the sa certificate.	me town and range may be	nauf. 1	8 19 20 21	222324
on ung	cennicate.		colded	9	++++
				10 30 29 28	272625
1				12	╿┈╏┈╏┈╏┈╏
A. Description of	of original monument and ac	Securios and		12 31 32 33	35 36
J-6 1837	GLO		restoration:	10-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-	<u> </u>
	Williams & Works	Not Set			
j	Kent Co. Wits	No information No information	DA o	-	
ł		· ·	P.A. 34	45 1990 KENT COU	VTY
		* - ₄	reen /	APPROVED 12 10	26919
			CHAIRN	WAN Hamp	Luber
				/ *	.
B. Description of	corner evidence found and/	or method applied in roots in			
J-6 Establishe	ed Intersection of 1/4 lines a	nd found nothing I seed	or reestablishing corner.		
Intersecti	ion of 1/4 lines 54-	Adding. Location	falls in a wet grassy area	a,	
	ion of 1/4 lines fits compute	d dimensions of surveys by	Roosien and Glaza		
The Inters	SECULIFICAT DA Garage	ted by me and is consecut			
CAIGHTEE	of the position of the come		ecepted by professional:	surveyors as the best ava	ulable
		,			
•	,				
C Donorius					
O. Description of mo	onument for corner and acce I' Iron Pipe with yellow "Ke	ssories established to paract	rimā. I ii		
J-6 Set 3/4" x 9	"Iron Pipe with yellow "Ke C Remon. tag W. side 14" of	nt Co. Remon " can at the I	late locating the position	of the corner	.
1 30 170 X	C Remon. tag W. side 14" of Remon. tag N. side 12" A	and at the I	ntersection of 1/4 lines.	OF MICH	
	→ INCHIOD tag H oid a cu v z	sh N60°E 94	.71'	7 7 1/2/2/2	
Nail & K(Remon. tag SE side 40" C		.03'	BREITELS	128
		ak S45°W 148	.13'	LAND SURVEYOR	*
					/\$ [
	1110 -			30077	
	11/1/0	/		A CO THE OWN	
Signed by	who had s	-	A		•
Surveyor's Michigan Lic	cense No. 30077		Date /2/15	199	