

KENT COUNTY REMONUMENTATION

		SECTION										1999	REC C	C)	
	corners in	1/03.7					1)), (In	22	733 	
K	ENT COUN	LO	cated In:	Corne	r Code#				:: [7	7 3	, Learn	70	85	<u>.</u>	
•	· (Count	W		Т	yrone Twp.				ď.			7:-	79	2.5	
1. F	ublic Land	Survey	T R_	Tyrone Twp. Tion R 12W K-3 T R T R T R T R T R T R T R T											
	roperty Cor	ntrolling S_	TR									وبرا	ميا		
	Section	S_	<u>T</u> R			-					14	101	_		
3. Miscellaneous S T R Property in Sec. S T R								77700							
•	roporty iii o							R	egiste	er of D	eeds S	Stamp	& File	Number	
4. L 5. P	ot No rivate Clain	, Recorded F	Plat					A	вс	. D	E F	G H	ΙJ	кь	
٠	make Glain		·			· · · · · · · · · · · · · · · · · · ·		2		_ 5					
									Ĭ						
l,	Kirk Breitel	ls in a	a field survey on	Jan. 18	. 19 ⁹⁹ do	hereby state that	t under		.7	_ 8		10		12	
requ	requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in											11			
Unite	ed States Depa	ertment of the Interior.	Bureau of Land M	fanagement or	by a decree o	f a Court of Law :	and /or	ı	18	 —17—	 16-	15	 14	 13	
that Boar	the corner poi d of Land Su	nts mentioned in lines rivevors or by a Dec	3, 4 and 5 above cree of a Court c	were in confor	mance with thi	e rules of the Mi	ichigan rented	7		_ _		17			
recov	vered, found as	s expressed below:	.,				iorico,	8 —	19	20	21 <u>-</u>	22-	23	324-	
NOT	E: Not mor	re than 2 comers, all	I in the same tow	n and range.	may be reco	rdedi		9	+	-	 				
		certificate.			•			10	30	2 9	28-	27-	26	52 _. 5-	
								11	+		┨	+++	-		
								12—	31-	3 2	3 3	34_	35	36	
A .	Description o	of original monume	nt and accessor	ies and/or su	ibsequent re	storation:		13	.ll					_ _	
	K-3 1837	GLO			-		D /	1 046	: 40c	30 14					
	1963	Kent Co. Wits	WILLCOMO										TY		
	1971	LCRC #90	Chambers							11 1		<u> </u>	77	_	
	1982	LCRC #3017	Starr		•		CH	AIRN	IAN	/		//	بيسكة	res	
	1991	LCRC #6023	Byl	Kent C	ounty Moni	ıment									
	The po by Tho	osition of this corn omas C. Starr on 8	er was previous -2-82 and was r	sly approved ecorded per	by the Ken LCRC #30	t County Rem 17.	onumen	tation	Peer	Grou	p, mon	ument	ed		
В.	Description of	of corner evidence	found and/or m	ethod applied	d in restoring	or reestablish	ina corn	er:							
1									as C	Starr	in nlac	e of th	æ		
	11/2" Ire	on Pipe he found.	Said Iron Pipe	checks with	ı Kent Co. V	Vit. and LCRO	C #90.			J	ni piav	,			
		C #3017 l & Remon, tag 28	O" Monto CENOT		LCRC #602				.						
		l & Remon. tag 18				emon. tag 30" emon. tag Tw				20.6. 730.1					
		l & Remon. tag 12				emon tag 15"		-		7 29.0					
		l & Remon. tag 12				emon. tag 15"		N	25°W	/ 27.1	2'				
		l & Remon. tag 10 l & Remon. tag 24				emon, tag 12"				22.7					
	The sel	lected location is a	accepted by me	and is gener	ally accepte	emon, tag 24" ed by profession	onal sur	vevors	as th	19.79 e best	availa	hle			
<u>ر</u> .	eviden	ce of the position of the monument for co	of the original o	corner.	,p. vv	ahuata ta at	. 4h	ن د د د د د د د د د د د د د د د د د د د	* 44.			.~.•			
U. I	Vescripuon o: K_3 Standon	d Kent County M	mer and access	unes establis	mea to perp	etuate locating	tne pos	mon of	the c	orner:		-	# 133 000-	ъ.	
		KC Remon: tag N		ple	S50°E 2	20.60'						. 0	# 1 C		
	Nail &	KC Remon, tag S	SE side Twin 15		S40°W 3							No.		~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~	
		KC Remon. tag S		,	S90°W 2					ž	* * /	BDS	CIRK SITELS	1	
		KC Remon, tag V KC Remon, tag V			N25°W 2						# 1	L.A	ND	7	
		KC Remon. tag V			N20°E 2 N60°E 1					3	_ 8		VEYO		
		/		•						Š			40 1077 		

LANDS

30077

Surveyor's Michigan License No.