

KENT COUNTY REMONUMENTATION

Sign of State of the State of t	****	THE COUNTY REMONORMENTA	TION	 >
The state of the s	LAND	CORNER RECORDATION CERTIFIC	CATE	
For corners in	Filing	Requirement of Act 74, Mich. P.A. 1	970	
KENT COUNTY	Located in:	Corner Code #		일 일본
(County)	Located In.			
1. Public Land Survey	T <u>10N</u> R_1	Tyrone Twp. 2W L-9	$\boldsymbol{\varphi}$	
dono zama odrecy	TR			
	TR_ TR			ယ ဗ
2. Property Controlling	S TR			
in Section 3. Miscellaneous	S TR			
Property in Sec.	S TR_		11198	
			Register of Deeds St	tamp & File Number
4. Lot No, Recorde	ed Plat		•	
5. Private Claims			ABCDEF	GHIJKL
			2 - 6 - 5 - 4 -	
Kirk Breitels	in a fold average	Ian 21 40 00	3	
I, <u>Kirk Breitels</u> , in a field survey on <u>Jan. 21</u> , 19 99 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the				10-11-12
United States Department of the Inte	lles therefore as required in erior. Bureau of Land Mana	n the current manual of survey instructions of the		
utat the corner points mentioned in	lines 3, 4 and 5 above wer	re in conformance with the rules of the Michigan aw; established, re-established, monumented,		15-14-13-
recovered, found as expressed below	<i>y</i> :	, combined, re-established, mondifiented,	8 19 20 21	22 23 24
NOTE: Not more than 2 corners, all in the same town and range, may be recorded			9	
on this certificate.			10 30 29 28	272625-
			11	
			12 31 32 33	34 35 36
A. Description of original monument and accessories and/or subsequent restoration:			P.A. 345 1990 KEN	T COUNTY
L-9 1837 GLO	Whitcomb	Set Post	PEER APPROVED	
1985 LCRC #431	l3 Bissell	Set Concrete Monument	CHAIRMAN //	us The lea
1986 LCRC #445 1991 LCRC #603		Found Concrete Monument with DNR Concrete Monument with DNR Cap	Cap at mid-point of mile	11100
	•			
The position of this of	corner was previously	approved by the Kent County Remonum	entation Peer Group as mo	numented
(Control Mondmen	with Divic Capy pres	ented by Randy J. Kolehouse on 4-5-86	and was recorded per LCR	C #4454,
B. Description of corner evider	nce found and/or metho	od applied in restoring or reestablishing cor	rner:	
 L-9 Found Concrete Mon 	nument with DNR Car	per witnesses from above LCRC as four		,
Kolehouse. Said Cor LCRC #4313	ncrete Monuement wit	th DNR Cap checks with LCRC #4313.	with presented by Italiay	
	Tri. 12" Oak N29°E 36	LCRC #6035 6.75' Nail & Remon. tag Tri. 12" (Dal N20°E 26.711	
Nail & DNR tag 1	8" Oak S80°E 43	3.50' Nail & Remon. tag 18" Oak	S80°E 43.50'	
Nail & DNR tag 1 Nail & tag 16" Ch				
C/L 18 Mile Road		Nail & Remon. tag 10 Chen	N15°W 66.24'	
The selected location	is assented by me	Nail & Remon, tag 12" Cherr	rv S60°E 36.04'	
evidence of the positi	ion of the original con	d is generally accepted by professional suner.	urveyors as the best availab	le
C. Description of monument for	corner and accessorie	ner. s established to perpetuate locating the po	sition of the corner:	
L-9 Concrete Monument v Nail & KC Remon: tz	vith DNR Cap ag W. side Tri. 15" Oa	ık N29°E 36.73'		
Nail & KC Remon. ta	ag N. side 22" Oak	S80°E 43.50'	#3/	KIRK TO THE STATE OF THE STATE
Nail & DNR tag W. s	side 14" Oak ag N. side 18" Cherry	S10°W 35.19'	A A	LAND **
Nail & KC Remon, ta		S83°W 51.95' N15°W 66.27'	اگر آ این این این این این این این این این این	JRVEYOR A
C/L 18 Mile Rd. (grav		•	A CON	KIRK REITELS LAND JRVEYOR NO 30077
,	_		/2.5-/99	LAND SURVEY
Signed by	PM			The second of th
Signed by	1/2ms	Data 2	125/99	

Signed by Date 2/25/99

Surveyor's Michigan License No. 30077